

CARR - 742

630 LUCABAUGH MILL ROAD

mid-19th century

Westminster vicinity

private

630 Lucabaugh Mill Road is shown as the J. W. Lucabaugh residence on the 1877 map. As it is not shown on the 1862 map, it was probably built between those years. It is a representative regional farmhouse with typical characteristics in plan, proportion, and details. It is constructed of brick in a stretcher bond on a stone foundation. There is a late nineteenth century frame barn on this property.



DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street  
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

SURVEY NUMBER: CARR- 742

NEGATIVE FILE NUMBER:

UTM REFERENCES:  
Zone/Easting/Northing

U.S.G.S. QUAD. MAP: Westminster

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: residence

ORIGINAL USE: residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:  
Excellent ( ) Good (X)  
Fair ( ) Poor ( )

THEME:

STYLE:

DATE BUILT: mid - 19th century

COUNTY: CARROLL

TOWN: WESTMINSTER VIC

LOCATION: 630 Lucabaugh Mill Road

TAX MAP 39 Block 15 P-317

COMMON NAME:

FUNCTIONAL TYPE: residence

OWNER: ETHEL B. EVELEIGH

ADDRESS:

ACCESSIBILITY TO PUBLIC:  
Yes ( ) No (X) Restricted ( )

LEVEL OF SIGNIFICANCE:  
Local ( ) State ( ) National ( )

GENERAL DESCRIPTION:

Structural System

- Foundation: Stone (X) Brick ( ) Concrete ( ) Concrete Block ( )
- Wall Structure
  - Wood: Log ( ) Post and Beam ( ) Balloon ( )
  - Wood Bearing Masonry: Brick (X) Stone ( ) Concrete ( ) Concrete Block ( )
  - Iron ( ) D. Steel ( ) E. Other
- Wall Covering: Weatherboard ( ) German Siding ( ) Board and Batten ( )  
Wood Shingle ( ) Shiplap ( ) Novelty ( ) Stucco ( ) Sheet Metal ( )  
Aluminum ( ) Asphalt Shingle ( ) Brick Veneer ( ) Stone Veneer ( )  
Bonding Pattern: stretcher Other:
- Roof Structure
  - Truss: Wood (X) Iron ( ) Steel ( ) Concrete ( )
  - Other:
- Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle ( ) Sheet Metal (X)  
Built Up ( ) Rolled ( ) Tile ( ) Other:
- Engineering Structure:
- Other:

Appendages: Porches (X) Towers ( ) Cupolas ( ) Dormers ( ) Chimneys ( ) Sheds ( )  
Ells ( ) Wings ( ) Other:

Roof Style: Gable (X) Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )  
Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( )  
With False Front ( ) Other:

Number of Stories: 2

Number of Bays: 4 x 2

Approximate Dimensions: \_\_\_\_\_

Entrance Location: central bays

THREAT TO STRUCTURE:  
No Threat ( ) Zoning ( ) Roads ( )  
Development ( ) Deterioration ( )  
Alteration ( ) Other:

LOCAL ATTITUDES:  
Positive ( ) Negative ( )  
Mixed ( ) Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

full-length - 1 st. front porch  
6/6 windows, jack each lintels  
interior end chimney at each gable end



RELATED STRUCTURES: (Describe)

frame bank barn

STATEMENT OF SIGNIFICANCE:

not on 1862 map bldg between 1862-1877

representative mid-19th c. brick house

REFERENCES:

1862 Martenet's Map:  
1877 LG & S Atlas: J. W. Lucasbaugh res.

SURROUNDING ENVIRONMENT:

Open Lane ( ) Woodland ( ) Scattered Buildings ( )  
Moderately Built Up (X) Densely-Built Up ( )  
Residential ( ) Commercial ( )  
Agricultural ( ) Industrial ( )  
Roadside Strip Development ( )  
Other:

RECORDED BY:

Joe Getty

ORGANIZATION:

DATE RECORDED:

July 18, 1983





CARR-742

1. 630 Lucabaugh Mill Rd.
2. Carroll Co. Md.
3. J. Betty
4. 11/83
5. Md. Hist. Trust, Annapolis, Md
6. north west elevation
7. 1/2



CARR. 742

1. 630 Lucabaugh Mill Rd.
2. Carroll Co. Md.
3. J. Getty
4. 11/83
5. Md Hist. Trust, Annapolis Md.
6. bank box, northwest elevation
7. 2/2