

CARR - 766

522 HOOK ROAD

late 19th century

Westminster vicinity

private

522 Hook Road is a late nineteenth century farmhouse that demonstrates the rural Victorian farmhouse style found frequently in Carroll County. This style basically incorporates the regional characteristics with the addition of a gabled dormer. This example has a full-length, one-story front porch with brick piers that date from the twentieth century. There is a late nineteenth century bank barn on the property.



DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

SURVEY NUMBER: CARR-766
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP: Westminster
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: residence
ORIGINAL USE: residence
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent () Good (X) Fair () Poor ()
THEME:
STYLE:
DATE BUILT: late 19th century

COUNTY: CARROLL
TOWN: Westminster vicinity
LOCATION: Barnes Ave.
522 Hook Rd TAX MAP 52 Block-3-P-458
COMMON NAME:
FUNCTIONAL TYPE:
OWNER: Ova Klougsted
ADDRESS: 522 Hook Rd. Westminster
ACCESSIBILITY TO PUBLIC: Yes () No (X) Restricted ()
LEVEL OF SIGNIFICANCE: Local () State () National ()

GENERAL DESCRIPTION:
Structural System
1. Foundation: Stone (X) Brick () Concrete () Concrete Block ()
2. Wall Structure
A. Wood: Log () Post and Beam () Balloon (X)
B. Wood Bearing Masonry: Brick () Stone () Concrete () Concrete Block ()
C. Iron () D. Steel () E. Other
3. Wall Covering: Weatherboard () German Siding () Board and Batten ()
Wood Shingle () Shiplap () Novelty () Stucco () Sheet Metal ()
Aluminum () Asphalt Shingle () Brick Veneer () Stone Veneer ()
Bonding Pattern: Other: Photos Siding
4. Roof Structure
A. Truss: Wood (X) Iron () Steel () Concrete ()
B. Other:
5. Roof Covering: Slate () Wood Shingle () Asphalt Shingle () Sheet Metal (X)
Built Up () Rolled () Tile () Other:
6. Engineering Structure:
7. Other:
Appendages: Porches (X) Towers () Cupolas () Dormers (X) Chimneys () Sheds ()
Ells (X) Wings () Other:
Roof Style: Gable (X) Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead ()
Saw Tooth () With Monitor () With Bellcast () With Parapet ()
With False Front () Other:
Number of Stories: 2 1/2
Number of Bays: 5 x 2
Approximate Dimensions:

Entrance Location: center

THREAT TO STRUCTURE:
No Threat () Zoning () Roads ()
Development () Deterioration ()
Alteration () Other:

LOCAL ATTITUDES:
Positive () Negative ()
Mixed () Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

regional rural Victorian style



DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
WASHINGTON, D.C. 20250
WESTERN FIELD OFFICE
1111 14TH STREET, N.W.
SALT LAKE CITY, UTAH 84143

RELATED STRUCTURES: (Describe)

like 1st c. bank barn

STATEMENT OF SIGNIFICANCE:

representative of rural Victorian farm houses in this region

REFERENCES:

- 1862 Martenet's Map:
- 1877 LG & S Atlas: William Beaver

SURROUNDING ENVIRONMENT:

- Open Lane () Woodland () Scattered Buildings ()
- Moderately Built Up (X) Densely-Built Up ()
- Residential () Commercial ()
- Agricultural () Industrial ()
- Roadside Strip Development ()
- Other:

RECORDED BY:

Joe Kelly

ORGANIZATION:

DATE RECORDED:

8/83



U.S.G.S. MAP
WESTMINSTER, MD.
1:24000 SCALE

Mapped by the Corps of Engineers, U. S. Army
Edited and published by the Geological Survey



CARR-766

Westminster vicinity

South facade

11/83

Photo By Joe Getty