

CARR - 768

913 ARNOLD ROAD

late 19th century

Westminster vicinity

private

913 Arnold Road is a representative late nineteenth century farm complex. The farmhouse retains the regional style characteristics and is built into a slope. It has Victorian-style ornamentation in its porch and gabled dormer. There is a late nineteenth century bank barn with a board fence around the barnyard.



DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

SURVEY NUMBER: CARR-768
NEGATIVE FILE NUMBER:
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP: Westminster
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME:
PRESENT USE: residence
ORIGINAL USE: residence
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE: Excellent ( ) Good (X) Fair ( ) Poor ( )
THEME:
STYLE:
DATE BUILT: late 19th century

COUNTY: CARROLL
TOWN: Westminster vicinity
LOCATION: 913 Arnold Rd.
TAX MAP 52 Block 10 P-55
COMMON NAME:
FUNCTIONAL TYPE: residence
OWNER: Rodney E. Hirt
ADDRESS: 913 Arnold Rd. Westminster
ACCESSIBILITY TO PUBLIC: Yes ( ) No (X) Restricted ( )
LEVEL OF SIGNIFICANCE: Local ( ) State ( ) National ( )

GENERAL DESCRIPTION:
Structural System
1. Foundation: Stone (X) Brick ( ) Concrete ( ) Concrete Block ( )
2. Wall Structure
A. Wood: Log ( ) Post and Beam (X) Balloon ( )
B. Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )
C. Iron ( ) D. Steel ( ) E. Other
3. Wall Covering: Weatherboard ( ) German Siding ( ) Board and Batten ( )
Wood Shingle ( ) Shiplap ( ) Novelty ( ) Stucco ( ) Sheet Metal ( )
Aluminum ( ) Asphalt Shingle ( ) Brick Veneer ( ) Stone Veneer ( )
Bonding Pattern: Other: Asbestos Siding
4. Roof Structure
A. Truss: Wood (X) Iron ( ) Steel ( ) Concrete ( )
B. Other:
5. Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle ( ) Sheet Metal (X)
Built Up ( ) Rolled ( ) Tile ( ) Other:
6. Engineering Structure:
7. Other:
Appendages: Porches (X) Towers ( ) Cupolas ( ) Dormers ( ) Chimneys ( ) Sheds ( )
Ells (X) Wings ( ) Other:
Roof Style: Gable (X) Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )
Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( )
With False Front ( ) Other:
Number of Stories: 2 1/2
Number of Bays: 3 x 2
Approximate Dimensions:
Entrance Location: center

THREAT TO STRUCTURE:
No Threat ( ) Zoning ( ) Roads ( )
Development ( ) Deterioration ( )
Alteration ( ) Other:

LOCAL ATTITUDES:
Positive ( ) Negative ( )
Mixed ( ) Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

representative regional style  
 gabled dormer  
 built to slope  
 full-length porch



RELATED STRUCTURES: (Describe)

bank barn - late 19th century

STATEMENT OF SIGNIFICANCE:

representative late 19th century farmhouse and farmstead

REFERENCES:

1862 Martenet's Map:  
 1877 LG & S Atlas: D. Zincken

SURROUNDING ENVIRONMENT:

Open Lane ( ) Woodland ( ) Scattered Buildings (X)  
 Moderately Built Up ( ) Densely-Built Up ( )  
 Residential ( ) Commercial ( )  
 Agricultural ( ) Industrial ( )  
 Roadside Strip Development ( )  
 Other:


RECORDED BY:

Joe Getty

ORGANIZATION:

DATE RECORDED:

8/83



U.S.G.S. MAP  
WESTMINSTER, MD.  
1:24000 SCALE

Mapped by the Corps of Engineers, U. S. Army  
Edited and published by the Geological Survey

FLD  
1:24,000



CARR-768

913 ARNOLD ROAD

Westminster vicinity

west facade

8/83

Photo By Joe Getty