

MARYLAND HISTORICAL TRUST

CE-1222

Magi No. 0812225535

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

File 755

**1 NAME**

HISTORIC

Rawlings Farm "Pattersonville"

AND/OR COMMON

**2 LOCATION**

STREET & NUMBER

Burlin Road intersection with Rock Run Road

CITY, TOWN

Port Deposit

VICINITY OF

CONGRESSIONAL DISTRICT

1

STATE

Maryland

COUNTY

Cecil

**3 CLASSIFICATION**

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input type="checkbox"/> PUBLIC	<input checked="" type="checkbox"/> OCCUPIED	<input type="checkbox"/> AGRICULTURE <input type="checkbox"/> MUSEUM
<input checked="" type="checkbox"/> BUILDING(S)	<input checked="" type="checkbox"/> PRIVATE	<input type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL <input type="checkbox"/> PARK
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> EDUCATIONAL <input checked="" type="checkbox"/> PRIVATE RESIDENCE
<input type="checkbox"/> SITE	<b>PUBLIC ACQUISITION</b>	<b>ACCESSIBLE</b>	<input type="checkbox"/> ENTERTAINMENT <input type="checkbox"/> RELIGIOUS
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input checked="" type="checkbox"/> YES: RESTRICTED	<input type="checkbox"/> GOVERNMENT <input type="checkbox"/> SCIENTIFIC
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> INDUSTRIAL <input type="checkbox"/> TRANSPORTATION
		<input type="checkbox"/> NO	<input type="checkbox"/> MILITARY <input type="checkbox"/> OTHER:

**4 OWNER OF PROPERTY**

NAME

Dudley C. Rawlings

Telephone #: 378-3721

STREET & NUMBER

245 Bublind Road

CITY, TOWN

Port Deposit

VICINITY OF

STATE, zip code

Maryland 21904

**5 LOCATION OF LEGAL DESCRIPTION**

COURTHOUSE,  
REGISTRY OF DEEDS, ETC.

STREET & NUMBER

CITY, TOWN

Clerk of the Circuit Court

Cecil County Courthouse

Elkton

Liber #: RRC 55  
Folio #: 261

STATE  
Maryland

**6 REPRESENTATION IN EXISTING SURVEYS**

TITLE

DATE

FEDERAL  STATE  COUNTY  LOCAL

DEPOSITORY FOR  
SURVEY RECORDS

CITY, TOWN

STATE

**7 DESCRIPTION**

CE-1222

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input checked="" type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input checked="" type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED      DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

**DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE**

This two story three bay by one room frame farmhouse c. 1860 is on a tract of land known as Pattersonville which borders Bullin Road on the east and Roack Run Road on the south. The house itself faces south with a east/west gable axis.

The present main block is actually an addition to a earlier two story two bay by one room section that serves as a kitchen ell. The house was extended even further with a two story west gable end addition. The irregularly shaped frame house rests on a fieldstone and granite foundation. The house is sheathed with both plain weatherboard siding and novelty siding on the main block. The main roof has a medium pitch and is covered with composition shingle. The eaves are extended and the soffits sloped.

The south (main) elevation is a traditional three bays across with a central entry. The heavily molded four panel door is bordered by a single light transom and three light sidelights. A single 2/2 sash with louvered shutters is found on either side. The second floor has a central double single pane sash windows with a bracketed and pedimented hood. The central cross gable has a slightly arched 2/2 attic window. The peak to the eave is decoration with a sawn tracery ornament. and the peak is surmounted by a pyramidal finial. The first floor is covered by a single story flat roofed porch with simple chamfered posts.

The east gable end has a centrally placed 2/2 sash window on each floor including the attic. The gable end has the same decorative sawn tracery ornament. Due to the centrally placed windows the brick stove stack rises against the interior hall wall to heat the east parlor.

The north side of the 1860 block is partially covered by what appears to be an earlier section. The main block has an exposed parlor window and hall door on the first floor and two windows on the second. The door to the hall is a heavily raised six panel door that must have been retrieved from another house and used in this spot. The rear kitchen wing is two bays across with an entrance in the southern of the two bays. A shed porch covers the first floor. The kitchen wing is detailed with similar treatment around door and windows.

The west end two story two bay by two rooms latest addition has two 6/6 sash on each floor of the south facade. An attic dormer with 6/6 sash and gable roof light the attic space. This last addition covers half of the west gable end of the main block.

**CONTINUE ON SEPARATE SHEET IF NECESSARY**

Pattersonville

Page Two

An interior end brick stove stack is flanked by a first floor 2/2 sash window.

The gable end of the addition has a side entrance through a shed screened-in porch with adjacent 2/2 sash windows. The second floor and attic are lighted by 2/2 sash also.

The first floor of the 1860 front block was the only interior seen. It consists of a traditional center hall with a room to each side. The heavily turned newel has a flat oval handrail and turned balusters. The widely molded door surrounds frame four panel doors. Original late 19th century wall paper remains in the east parlor along with a decoratively painted slate mantel with arched fireplace opening. Other woodwork in the west parlor dates from the same period.

The property retains three interesting farm structures. The most typical is the 2½ story board and batten box frame barn with gable bank entrance on the south side and later dairy to the north. The barn rests on a traditional fieldstone foundation and is covered with a tin roof. The date Sept. 13, 1872 is recorded on a tie beam and may be the construction date. The eaves are trimmed with a decorative fascia. Six pane windows light the attic and a double 6/6 sash windows light the projecting entrance bay.

Directly east of the barn is a two level combination fieldstone carriage house, workshop, dairy, and probable slaughter house. The structure faces south with a north/south gable orientation. The south elevation has two sets of double doors separated by a granite post. The second floor is lighted by double 6/6 sash windows. The eaves to the slate roof are extended and decorated with ornamental fascia.

The east side has a second level entrance to the workshop which occupies the entire second floor. An adjacent 6/6 sash permits light through the east wall. The west has other 6/6 sash that light the workshop above. Six pane sash light the spaces below the workshop. A brick chimney stack rises out of the west end to serve as a heat source for the workshop and slaughter house. The north side is a full 2½ storys since the structure is built into a slight downward slope towards the spring. The first floor has two board doors which allow access into the first floor rooms. The eastern room has an open spring while the western room has a corner fireplace. Both doors open out to concrete floor which slopes toward the spring. The second floor has a central 6/6 sash window and the attic illuminated by a six pane window.

Further east and directly behind the house is a two level meat house of semi-coursed fieldstone construction with a medium sloped gable roof. Entrance to the second level meat house is gained through the board door on the south side. An interior step puts the smoking room on a higher level than the entrance. Another board door entrance is located in the west wall and allows access to the space below for storage.

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input checked="" type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

Francis Marion Rawlings owned this complex along with 198 $\frac{1}{2}$  acres in 1877. He is listed on the Lake, Griffing, and Stevenson patron list as a Cecil County farmer. The present farmhouse is a traditional one found throughout the county. The outbuildings especially the combination carriage house, workshop, spring house, etc. <sup>are</sup> an unusual multiple purpose structure of well laid local fieldstone. One unusual feature of the house is the surviving wallpaper in the east parlor that hasn't been altered ~~except for a patch~~ since it was put up in the late 19<sup>th</sup> century.

CONTINUE ON SEPARATE SHEET IF NECESSARY

**9 MAJOR BIBLIOGRAPHICAL REFERENCES**

CE-1222

CONTINUE ON SEPARATE SHEET IF NECESSARY

**10 GEOGRAPHICAL DATA**

ACREAGE OF NOMINATED PROPERTY \_\_\_\_\_

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE	COUNTY
STATE	COUNTY

**11 FORM PREPARED BY**

NAME / TITLE

Paul B/ Touart

ORGANIZATION

Cecil County Committee

DATE

11/05/81

STREET & NUMBER

Cecil County Courthouse

TELEPHONE

398-0200

CITY OR TOWN

Elkton

STATE

Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust  
The Shaw House, 21 State Circle  
Annapolis, Maryland 21401  
(301) 267-1438



730° 404 | 1 050 000 FEET (MD.) 5° 408

Mapped, edited, and published by the Geological Survey

Control by USGS and USC&GS


Culture and drainage in part compiled from aerial photographs taken 1952. Topography by plane-table surveys 1939 and 1940. Revised 1953

Polyconic projection. 1927 North American datum. 10,000-foot grids based on Maryland coordinate system, and Pennsylvania coordinate system, south zone. 1000-meter Universal Transverse Mercator grid ticks, one 18, shown in blue.

Revisions shown in purple compiled from aerial photographs taken 1970. This information not field checked.



UTM GRID AND 1970 MAGNETIC NORTH DECLINATION AT CENTER OF SHEET



CONT  
D1

THIS MAP COMPLIES WITH THE REQUIREMENTS FOR SALE BY U. S. GEOLOGICAL SURVEY. A FOLDER DESCRIBING TOPOGRAPHIC MAPS IS AVAILABLE.

*Rising Sun Quad*



RAWLINGS FARM

CE-1222

SOUTH ELEV.

NR PORT DEPOSIT

3/80 PBT

NEG. | MP. 1+15T. TRUST



CE-1222


RAWLINGS farm

MULTI-PURPOSE OUTBUILDING

NORTHWEST ELEVATION

3/80 PBT

NEL/MO. HIST TRUST



CE-1222

RAWLINGS FARM

SMOKEHOUSE - WEST ELEV.

NR PORT DEPOSIT

3/80. PBT

NEG. IMP. HIST TRUST



Pattersonville (Rawlings) CE - 222  
South Elevation (From)  
Near Woodlawn  
2/80 PBT  
NEG - MD. Hist. Trust



CE-1222

RAWLINGS FARM

EAST ELEVATION

NR PORT DEPOSIT

3/80 PBT

NEG. / MO. HIST TRUST



CE-1222

Rawlings Farm

Near Woodlawn, Cecil County

Outbuilding - carriage House  
(workshop)

North elevation

Photographer - Paul Touart, 1979

NEG/MHT



CE-1222

Rawlings Farm

Near Woodlawn, Cecil County

Outbuilding - Hearth for washhouse

Photographer - Paul Touart, 1979

Neg/MHT



CE-1222

Rawlings Farm

Near Woodlawn, Cecil County

Corn Crib - South Elevation

Photographer - Paul Touart, 1979

Neg/MHT



CE-1222

Rawlings Farm

Near Woodlawn, Cecil County

Wash house interior

Photographer - Paul Touart, 1979

Neg/MHT



CE-1222

Rawlings Farm

Near Woodlawn, Cecil County

North elevation of carriage house

Photographer - Paul Touart, 1979

Neg/MHT



CE-1222

Rawlings Farm

Near Woodlawn, Cecil County

East elevation of carriage house

Photographer - Paul Touart, 1979

Neg/MHT



CE-1222

Rawlings Farm

Near Woodlawn, Cecil County

Smoke house

Photographer - Paul Touart, 1979

Neg/MHT