

0800366304

Form 10-445
(5/62)

1. STATE COUNTY TOWN STREET NO.	Maryland Cecil VICINITY Oakwood	HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY CE - 36
ORIGINAL OWNER ORIGINAL USE PRESENT OWNER PRESENT USE WALL CONSTRUCTION NO. OF STORIES	--- Dwelling --- Ruins Squared log grooved 2 construction	2. NAME DATE OR PERIOD STYLE ARCHITECT BUILDER
		3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION OPEN TO PUBLIC NO

This was a small log building two bays square and two stories in height which probably had an A-roof. (The roof is now completely gone.) This log dwelling was built into a slightly larger frames structure. The logs are square and laid in a grooved construction pattern, one on top of another. Many adze marks show on their surfaces. They are chinked between with plaster and fragments on broken brick.

This structure is important even in its ruinous state as one of the few surviving log structures in this county. Its site should be noted since it seems to be beyond repair. It is also interesting because it is two stories in height even though it is such a tiny structure.

Visited by MAB 4/70 - gone

Condition: RUINS

5. PHYSICAL CONDITION OF STRUCTURE Endangered Interior Exterior

6. LOCATION MAP (Plan Optional)

7. PHOTOGRAPH

2 prints
1 b & w neg
3 B&W
4-1/2" x 3-1/4"

2469

8. PUBLISHED SOURCES (Author, Title, Pages)
INTERVIEWS, RECORDS, PHOTOS, ETC.

9. NAME, ADDRESS AND TITLE OF RECORDER

Paul Alan Brinkman
16 December 1967

DATE OF RECORD

MAB
4/70

SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE

1. STATE <u>Maryland</u> COUNTY <u>Cecil</u> TOWN <u>Oakwood</u> VICINITY <u>(36)</u> STREET NO. _____ ORIGINAL OWNER ---- ORIGINAL USE <u>Dwelling</u> PRESENT OWNER ----- PRESENT USE <u>Ruins</u> WALL CONSTRUCTION <u>Squared log grooved construction</u> NO. OF STORIES <u>2</u>		HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY <u>CE-36</u>	
		2. NAME _____ DATE OR PERIOD <u>early 19th century?</u> STYLE <u>Log</u> ARCHITECT _____ BUILDER _____	
		3. FOR LIBRARY OF CONGRESS USE _____	
4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION		OPEN TO PUBLIC <u>NO</u>	
<p>This was a small log building two bayssquare and two stories in height which probably had an A-roof. (The roof is now completely gone.) This log dwelling was built into a slightly larger frame structure. The logs are square and laid in a grooved construction pattern, one on top of another. Many adze marks show on their surfaces. They are chinked between with plaster and fragments of broken brick.</p> <p>This structure is important even in its ruinous state as one of the few surviving log structures in this county. Its site should be noted since it seems to be beyond repair. It is also interesting because it is two stories in height even though it is such a tiny structure.</p>			
5. PHYSICAL CONDITION OF STRUCTURE		<u>RUINS</u> Endangered Interior Exterior	
6. LOCATION MAP (Plan Optional)		7. PHOTOGRAPH <u>3 b x 10 1/2 x 3 1/4"</u>	
8. PUBLISHED SOURCES (Author, Title, Pages) INTERVIEWS, RECORDS, PHOTOS, ETC.		9. NAME, ADDRESS AND TITLE OF RECORDER <u>Paul Alan Brinkman</u> <u>16 December 1967</u> DATE OF RECORD _____	

SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE



CECIL CTY # 36

CE-36

(36) Cecil

399 DG 12/67



Ruined Log House
Oakwood

CE - 36

DAG/1967
NEG -MD. Hist. Trust

8



Ruined Log House
Oakwood
Cornering Detail

CE - 36

DAG/1967
NEG - MD. Hist. Trust