

0800515304

Form 10-445  
(5/62)

1. STATE <b>Maryland</b> COUNTY <b>Cecil</b> TOWN <b>Hacksville</b> VICINITY STREET NO. ORIGINAL OWNER <b>---</b> ORIGINAL USE <b>Dwelling</b> PRESENT OWNER <b>James Clemens</b> PRESENT USE <b>Deserted-used for barn</b> WALL CONSTRUCTION <b>Clayboard</b> NO. OF STORIES <b>2-<del>1</del></b>	HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY <b>CE - 51</b> 2. NAME <b>Clemens house</b> DATE OR PERIOD <b>c. 1810</b> STYLE <b>Federal</b> ARCHITECT BUILDER 3. FOR LIBRARY OF CONGRESS USE
4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION <span style="float: right;">OPEN TO PUBLIC <u>NO</u></span>  <p>This is a simple frame house of the Federal period. It is now in a ruinous state and is used to store hay and tools. The house contains a very finely carved and panelled dog-leg staircase. The staircase has scrolled step-ends and a panelled wall. There are two very well-carved Federal mantels in the downstairs rooms and molded chair rails.</p> <p>The house is four bays long and one room deep with an enclosed chimney on each end. All of the windows are replaced 2/2 late 19th century sashes.</p> <p>This house contains some very fine carved woodwork and deserves better than its present treatment.</p> <p>Mr. Clemens expects to have the house removed or demolished soon -  <i>prob - 4/70</i></p> <p><u>Condition: Deserted used as a barn</u></p>	
5. PHYSICAL CONDITION OF STRUCTURE    Endangered <b>yes</b> Interior <b>poor</b> Exterior <b>poor</b>  <div style="text-align: right;"> <i>1 print</i>  <i>3 b&amp;w neg</i>  <i>2 B&amp;W</i>  <i>4-1/2 x 3-1/4</i> </div>	
6. LOCATION MAP (Plan Optional) 3. PUBLISHED SOURCES (Author, Title, Pages) INTERVIEWS, RECORDS, PHOTOS, ETC.	7. PHOTOGRAPH 9. NAME, ADDRESS AND TITLE OF RECORDER <p style="text-align: center;"><b>Paul Alan Brinkman</b> <b>13 December 1967</b></p> DATE OF RECORD

SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE





Price-Murphy-Clements House      CE - 51

Hack's Point

East Elevation

MOB/1968

NEG - MD. Hist. Trust



Price-Clements House  
East Elevation  
Hacks Point  
10/78 PBT  
NEG/MD Hist. Trust

CE-51



Price-Clements House

CE-51

South End

Hack's Point

10/78 PBT

NEG/MD Hist. Trust



Price-Clements  
North Gable End  
Hack's Point  
10/78 PBT  
NEG/MD Hist. Trust

CE-51



Price-Clements House  
South Gable End  
Hack's Point  
10/78 PBT  
NEG/MD Hist Trust

CE-51



Price-Clements House  
Southwest Elevation  
Hack's Point  
10/78 PBT  
NEG/MD Hist. Trust

CE-51







Price-Clements House  
Second Floor Joists  
Hack's Point  
10/78 PBT  
NEG/MD Hist. Trust

CE-51



Price-Clements House  
West Elevation  
Hacks Point  
10/78 PBT  
NEG/MD Hist. Trust

CE-51



Price-Clements House  
Stair Detail  
Hack's Point  
10/78 PBT  
NEG/MD Hist. Trust

CE-51



Price-Clements House  
Second Floor Joists  
Hack's Point  
10/78 PBT  
NEG/MD Hist. Trust

CE-51



Price-Clements House

CE-51

Rear Girt - Second Floor Joists

Hack's Point

10/78 PBT

NEG/MD Hist Trust



Price-Clements House  
North Wall-Attic Stair  
Hack's Point  
10/78 PBT  
NEG/MD Hist. Trust

CE-51



Price-Clements House  
South Parlor Fireplace  
Hacks Point  
10/78 PBT  
NEG/MD. Hist. Trust

CE-51



CE-51

PRICE-CLEMENTS HOUSE

KITCHEN FIREPLACE

GHOST -

NK EARLEVILLE

8/78 PBT

NEL./MD. HIST TRUST