

Inventory Number: CE-717  
Bunting House  
Cecil County, MD  
C. Mazurek  
June 1998  
Section 7.1

#### Addendum

The Bunting House is located to the west of Appleton Road, and just south of the Mason-Dixon Line in the Fair Hill N.R.M.A. It has been unoccupied for a number of years and is concealed by underbrush and vegetation.

Since the last historic sites surveys were completed in 1979 and 1984 no changes have occurred on this property. The house, silo, stone barn, and wood outbuildings are still intact; however the lack of maintenance has caused the buildings to deteriorate further.





CE-717

BUNTING HOUSE; FAIR HILL N.R. M.A.

CECIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES

HOUSE RUINS

<No. 329> 46 05 0561 N N N N-01 2



CE-717

BUNTING HOUSE; FAIR Hill N.R. M.A.

CECIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES

HOUSE RUINS

20105 8561 N N N N-01 2



3.a

<No. 1> 25 07 0561 N N N N-09 2

CE-717

BUNTING HOUSE; FAIR HILL N.R., MA.

CECIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES



CE-717

BUNTING HOUSE; FAIR HILL N.R., M.A.

CECIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES



CE-717

BUNTING HOUSE; FAIR HILL N.R. M.A.  
CECIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES  
HOUSE RUINS



CE-717

BUNTING HOUSE; FAIR HILL N.R. M.A.

CECIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES

SILO AND BARN RUINS



CE-717

HOUSE RUINS; FAIR HILL N.R. MA.  
CECIL COUNTY, MD

C. MAZUREK

12/97

DEPT. OF NATURAL RESOURCES

<No. E> 54 185 8561 N N N N-18 2

MARYLAND HISTORICAL TRUST

CE-717  
0807174204

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

**1 NAME**

HISTORIC Bunting House

AND/OR COMMON

**2 LOCATION**

STREET & NUMBER west of Appleton Road just south of the Mason Dixon Line

CITY, TOWN Elkton

CONGRESSIONAL DISTRICT 1

VICINITY OF

STATE Maryland

COUNTY Cecil

**3 CLASSIFICATION**

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input checked="" type="checkbox"/> PUBLIC	<input type="checkbox"/> OCCUPIED	<input checked="" type="checkbox"/> AGRICULTURE <input type="checkbox"/> MUSEUM
<input checked="" type="checkbox"/> BUILDING(S)	<input type="checkbox"/> PRIVATE	<input checked="" type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL <input type="checkbox"/> PARK
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> PRIVATE RESIDENCE
<input type="checkbox"/> SITE	<b>PUBLIC ACQUISITION</b>	<b>ACCESSIBLE</b>	<input type="checkbox"/> ENTERTAINMENT <input type="checkbox"/> RELIGIOUS
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input checked="" type="checkbox"/> YES: RESTRICTED	<input checked="" type="checkbox"/> GOVERNMENT <input type="checkbox"/> SCIENTIFIC
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> INDUSTRIAL <input type="checkbox"/> TRANSPORTATION
		<input type="checkbox"/> NO	<input type="checkbox"/> MILITARY <input type="checkbox"/> OTHER:

**4 OWNER OF PROPERTY**

NAME Department of Natural Resources

Telephone #:

STREET & NUMBER Tawes Office Building

CITY, TOWN Annapolis

VICINITY OF

STATE, zip code

Maryland 21401

**5 LOCATION OF LEGAL DESCRIPTION**

COURTHOUSE, REGISTRY OF DEEDS, ETC. Clerk of the Circuit Court

Liber #: WAS 347  
Folio #: 415

STREET & NUMBER Cecil County Courthouse

CITY, TOWN Elkton

STATE Maryland

**6 REPRESENTATION IN EXISTING SURVEYS**

TITLE

DATE

FEDERAL  STATE  COUNTY  LOCAL

DEPOSITORY FOR SURVEY RECORDS

CITY, TOWN

STATE

**7 DESCRIPTION**

CE-717

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input checked="" type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input checked="" type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED      DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

**DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE**

The Bunting House is a simple farmhouse built in two sections in the "colonial" style. The house is approximately 5 bays long by two bays deep and faces the south. The entire house is two stories in height and is built on two levels because the house is built into a hillside and because the two major sections were not built at the same time. The earlier part of this structure is the eastern end or eastern two bays of the house. It is built of hewn logs laid in the saddle notch style which were chinked with mud. This section as does the stone section, has a gable roof covered with asphalt shingles. Some of the early rafters still support the roof, but they appear to be mixed in with some later wood. The roof has a plain box cornice. In the east gable wall is a small brick stove chimney. There appears to have been a large fireplace in the west gable wall but it has been covered over. The exterior walls have tile shingles and the interior has a covering of lath and plaster. The facade has a central entrance and a single story Victorian porch probably built after 1900. In the upper story are two gable roof dormers. The house has 6/6 sash throughout. The interior looks like it was altered when the stone section was built. Toward the back of the log section is an open well stair with a landing at the same level as the second story of the stone section. There is no hardware left with the exception of some handmade nails.

The stone section is roughly of the same dimensions as the log side of the house. It is built of fieldstone and has been covered with stucco which has worn off in some places. In the west gable wall is a brick end chimney. The first floor room has some circa 1830 woodwork particularly some cupboards made of beaded lumber. There is also a nice door with ten panels which are flush with the stile. On the eastern wall of the first floor is an entrance to the cellar. The house has a stone foundation with log floor joists.

On the rear of both sides of the house are frame shed additions. Behind the house are several frame outbuildings that date from the late 19th century. Directly to the west of the house is an enormous stone bank barn made of fieldstone. The roof has deteriorated, but it was gable construction. The barn was about three stories in height and six bays long by three deep. Some of the stone used in the construction is serpentine.

-e

CONTINUE ON SEPARATE SHEET IF NECESSARY

**8 SIGNIFICANCE**

PERIOD		AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION	
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE	
<input type="checkbox"/> 1500-1599	<input checked="" type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE	
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN	
<input checked="" type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER	
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input checked="" type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION	
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)	
		<input type="checkbox"/> INVENTION			

---

SPECIFIC DATES	BUILDER/ARCHITECT
----------------	-------------------

---

STATEMENT OF SIGNIFICANCE

The Bunting House is important because of its log construction within the New Munster grant. This area was settled around 1711-20. Although it has not yet been determined the house could date partially from the mid to early part of the 18th century. The logs for the most part are in good condition and are worthy of preservation. The farm must have been very productive due to the size of the stone bank barn. It is the largest of its kind in the area. This house could have been lived in by a member of the Finley family an early important family. The Elk Creeks Preservation group is doing research on this building at the present time.

**9 MAJOR BIBLIOGRAPHICAL REFERENCES**

Lake, Griffith, and Stevenson An Illustrated Atlas of Cecil County Maryland Phila. 1877.  
Martenet, Simon J. Martenet's Map of Cecil County, Maryland.  
Phila. R. L. Barnes

CONTINUE ON SEPARATE SHEET IF NECESSARY

**10 GEOGRAPHICAL DATA**

ACREAGE OF NOMINATED PROPERTY \_\_\_\_\_

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE	COUNTY

**11 FORM PREPARED BY**

NAME / TITLE	
George Lutz Field Historian	
ORGANIZATION	DATE
Cecil Historical Trust	Jan 1977
STREET & NUMBER	TELEPHONE
RD 2	658-6850
CITY OR TOWN	STATE
Rising Sun	Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust  
The Shaw House, 21 State Circle  
Annapolis, Maryland 21401  
(301) 267-1438

MARYLAND HISTORICAL TRUST

CE 717

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

**1 NAME**

HISTORIC BUNTING HOUSE  
AND/OR COMMON

**2 LOCATION**

STREET & NUMBER West of Appleton Road just south of the Mason Dixon Line  
CITY, TOWN Elkton  VICINITY OF CONGRESSIONAL DISTRICT 1  
STATE Maryland COUNTY Cecil

**3 CLASSIFICATION**

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input checked="" type="checkbox"/> PUBLIC	<input type="checkbox"/> OCCUPIED	<input checked="" type="checkbox"/> AGRICULTURE <input type="checkbox"/> MUSEUM
<input checked="" type="checkbox"/> BUILDING(S)	<input type="checkbox"/> PRIVATE	<input checked="" type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL <input type="checkbox"/> PARK
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> PRIVATE RESIDENCE
<input type="checkbox"/> SITE	<b>PUBLIC ACQUISITION</b>	<b>ACCESSIBLE</b>	<input type="checkbox"/> ENTERTAINMENT <input type="checkbox"/> RELIGIOUS
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input checked="" type="checkbox"/> YES: RESTRICTED	<input checked="" type="checkbox"/> GOVERNMENT <input type="checkbox"/> SCIENTIFIC
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> INDUSTRIAL <input type="checkbox"/> TRANSPORTATION
		<input type="checkbox"/> NO	<input type="checkbox"/> MILITARY <input type="checkbox"/> OTHER:

**4 OWNER OF PROPERTY**

NAME State of Maryland, Dept. of Natural Resources Telephone #:  
STREET & NUMBER Tawes Office Building  
CITY, TOWN Annapolis VICINITY OF STATE, zip code Maryland 21401

**5 LOCATION OF LEGAL DESCRIPTION**

COURTHOUSE, LIBER #: was 347  
REGISTRY OF DEEDS, ETC. Clerk of the Circuit Court FOLIO #: 415  
STREET & NUMBER Cecil County Courthouse  
CITY, TOWN Elkton STATE Maryland

**6 REPRESENTATION IN EXISTING SURVEYS**

TITLE  
DATE  
DEPOSITORY FOR SURVEY RECORDS  
CITY, TOWN STATE  
FEDERAL STATE COUNTY LOCAL

**7 DESCRIPTION**

<b>CONDITION</b>		<b>CHECK ONE</b>	<b>CHECK ONE</b>
<input type="checkbox"/> EXCELLENT	<input checked="" type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input checked="" type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED    DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

**DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE**

The Bunting House is a simple farmhouse built in two sections. The house is 5 bays long and two bays deep, facing the south. The house is two stories built into a hillside. The earlier part, the eastern two bays of the house, are built of hewn logs laid in the saddle notch style, chinked with mud. The entire house has a single gable roof with asphalt shingles. Some of the early rafters still support the roof, but they appear to be mixed in with some later circular-sawn wood. The roof has a plain box cornice. In the east gable wall is a small brick stove chimney. There appears to have been a large fireplace in the west gable wall but it has been covered over. The exterior walls are shingled and the interior has a covering of lath and plaster. The facade has a central entrance and on story porch probably built after 1900. In the upper story are two gable roof dormers. The house has 6/6 sash throughout. The interior appears to have been altered when the stone section was built. Toward the back of the log section is an open well stair with a landing at the same level as the second story of the stone section. There is no hardware left with the exception of some handmade nails.

The stone section is roughly of the same dimensions as the log portion of the house. It is built of fieldstone and has been covered with stucco which has worn off in some places. A brick end chimney is in the west gable wall. The first floor room has some 1830's woodwork\*, particularly cupboards made of beaded lumber. There is also a nice door with ten panels which are flushwith the stile. On the eastern wall of the first floor is an entrance to the cellar. The house has a stone foundation with log floor joists.

On the rear of both sides of the house are frame shed additions. Behind the house are several frame outbuildings that date from the late 19th century. Directly to the west of the house is an enormous stone bank barn made of fieldstone. The roof has deteriorated, but it was gable construction. Some of the stone used in the construction is serpentine, some quartz.

\* 1979 examination turned up no significant woodwork. The door mentioned is gone.

**CONTINUE ON SEPARATE SHEET IF NECESSARY**

**8 SIGNIFICANCE**

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input checked="" type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input checked="" type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input checked="" type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The Bunting House is important because of its log construction within the New Munster grant. This area was settled around 1711-20. Although it has not yet been determined, the house could date partially from the mid to early part of the 18th century. The logs for the most part are in good condition and are worthy of preservation. The farm must have been very productive due to the size of the stone bank barn. It is the largest of its kind in the area. This house could have been lived in by a member of the Finley family, an early important family.

**9 MAJOR BIBLIOGRAPHICAL REFERENCES**

Lake, Griffith, and Stevenson An Illustrated Atlas of Cecil County Maryland, Phila. 1877

Martenet, Simon J. Martenet's Map of Cecil County, Maryland, Phila. R.L. Barnes

CONTINUE ON SEPARATE SHEET IF NECESSARY

**10 GEOGRAPHICAL DATA**

ACREAGE OF NOMINATED PROPERTY \_\_\_\_\_

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE COUNTY

STATE COUNTY

**11 FORM PREPARED BY**

NAME / TITLE

George Lutz, Field Historian/ John D. Hnedak

ORGANIZATION

DATE

Cecil Historical Trust/MHT

Jan 1977/1979

STREET & NUMBER

TELEPHONE

Rd 2

658-6850

CITY OR TOWN

STATE

Rising Sun

Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust  
The Shaw House, 21 State Circle  
Annapolis, Maryland 21401  
(301) 267-1438

The Bunting House is a two section structure consisting of a two-story stone section and a one and one-half story log section. The main facade faces south and in the stone section is three-bays with a central entrance. Six-over-six sash windows are in the outer bays of the first story and, on the second story, two windows are located immediately above those on the first story. The stone structure is constructed of field and quarried stone from the area. The stone <sup>r work</sup> structure was covered in stucco and whitewashed. It has a gable roof covered in asphalt shingles. The log structure has a high stone foundation that was originally covered in wood siding. It is now covered in <sup>asbestos</sup> exterior siding. The south facade has a central entrance with six-over-six windows on either side of the entrance. Above the windows are gabled dormers. Both sections have rear frame additions.

The Bunting House is located on the west side of Appleton Road, approximately 1.4 mile north of Maryland Route 273. The house is built on a sloping site approximately .2 mile west of Appleton Road. The site is presently overgrown with weeds and small trees.

The earliest section of the house appears to be the east section constructed of logs. It is a one and one-half story log structure on a ~~sub~~<sup>field</sup> stone basement. The manner in which the foundation of the stone section connects to the western portion of the house and in the way the logs are tied into the log section indicate that the log section was probably the earlier of the two. This section has a common rafter roof and the roof has been extended in catslide manner to cover a frame addition on the north facade. The logs were originally covered with stucco and white-washed. Later a weatherboard exterior was placed around the house and in the twentieth century this was covered with an asbestos siding. The log section is three-bays wide with an entrance located off-center. Six-over-six sash windows were located in the other two bays. A full-length, one-story Victorian style porch with a shed roof extended the length of the log section only. The porch has turned posts, exposed rafter ends, and a corrugated metal roof. At the easternmost portion of the porch was a stairway into the basement of the stone section. The half-story has two gabled dormer windows that rise from the front wall of the house. At the east gable end of the structure is a brick flue. However, there is evidence that a large fireplace existed at this wall at one time. The north facade of this structure has a

sharply sloping roof due to the catslide and a central entrance planked by two windows.

The stone structure is a two-story, three-bay by one-bay addition. It is constructed of fieldstone and was originally covered with stucco. The main facade has a central entrance planked by a single six-over-six window on each side. The second story has six-over-six windows immediately above the windows of the first story. The structure has a gable roof with a boxed cornice. The west gable end is unfenestrated except for two four pane windows in the gable. There is an interior-end chimney at this gable end. The north facade has a one-story frame addition with a shed roof. The second story of the stone section has two six-over-six sash windows. The frame section has a central entrance with a six-over-six window on each side.

PENNSYLVANIA  
MARYLAND

5 MASON

AND

4 DIXON

CHESTER CO  
CECIL CO

LINE

DNR-44 McCLEARY HOUSE  
CE-771

BUNTING HOUSE

DNR-33 SCHOOL HOUSE  
CE-758

DNR-1007 BARN, FEED MILL

DNR-28 McMASTER HOUSE  
CE-382

DNR-13 HAY LOFT  
CE-300-E

DNR-47 BARN  
CE-367-A

DNR-04 FINLEY BARN  
CE-301-A

DNR-12 SMOKE HOUSE  
CE-300-13

DNR-45 HOUSE  
CE-364

DNR-03 CAR TAKERS  
HOUSE

DNR-10 BEERS HOUSE  
CE-300-

DNR-50  
NEW COVERED BRIDGE

DNR-02 FINLEY HSE  
CE-301

DNR-11 BEERS BARN  
CE-300-A

DNR-03, 93, TRACK STRUCTURES  
CE-552

DNR-01 COVERED  
BRIDGE CE-238

DNR-103 CLUB  
CE-575

DNR-90-02 TRACK  
STRUCTURES CE-552

DNR-77 HOUSE  
CE-544

DNR-51 HOUSE

DNR-53 STABLES

DNR-56 STONE HOUSE  
CE-363

DNR-64 STONE STABLES  
CE-366

SCOTT MILL DAM

TYSON HOUSE  
RUINS CE-527

GAYLEN HOUSE  
RUINS CE-517

HOUSE RUINS

COVERED BRIDGE  
SITE CE-516

SCOTT MILL RUIN  
CE

NEWARK  
WEST  
QUAD.

L1L-3D

5663 III NW  
(BAY VIEW)

SANT HILL 1.5 MI.

Providence

Kenmore  
Sch

Andora

Big Elk  
Chapel

Granites

Cowe



Bunting House 1976

CE-717

ELKTON, MARYLAND

4



Bunting House

1976

CE-717

ELKTON, MARYLAND