

The Lusby House provides an illuminating example of construction sequence in Cecil County farmhouses. The story and a half log kitchen wing is alluded to by owners of similar structures but ^{usually} has been torn off for a more modern kitchen. The main 2½ story five bay frame block is a sturdy and well proportioned example of the five bay center hall single pile plan.

The sequence of construction is partially documented in the tax history of the property in the Cecil County tax records, however, a few inconsistencies remain to cloud the exact progression. The 1841 tax assessment lists Anna E. Lusby as owning 187 acres, new dwelling, and one slave all totaling \$ 1,699.00. The slave was valued \$ 200.00 alone which leaves \$ 1,499.00 for a new dwelling and 187 acres. If the land was averaged at \$ 7.00 per acre, which is rather low for the period, it would only leave \$ 190 for a new dwelling. This would probably be the value of the log section and not the main block. In 1861 an addition to the house appears on the books and was valued at \$ 300.00 which could be the five bay main frame block. If the structure did evolve in the aforesaid manner the Lusby house is a rare example of the progression from a one room story and a half log section to a five bay two and a half story center hall plan with earlier kitchen wing.

MARYLAND HISTORICAL TRUST

CE-931
MAGI #0809315435

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

File 187

1 NAME

HISTORIC

Lusby House

AND/OR COMMON

2 LOCATION

STREET & NUMBER

Stemmers Run Road

CITY, TOWN

Earleville

VICINITY OF

CONGRESSIONAL DISTRICT

1

STATE

Maryland

COUNTY

Cecil

3 CLASSIFICATION

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input type="checkbox"/> PUBLIC	<input checked="" type="checkbox"/> OCCUPIED	<input checked="" type="checkbox"/> AGRICULTURE <input type="checkbox"/> MUSEUM
<input checked="" type="checkbox"/> BUILDING(S)	<input checked="" type="checkbox"/> PRIVATE	<input type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL <input type="checkbox"/> PARK
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> EDUCATIONAL <input checked="" type="checkbox"/> PRIVATE RESIDENCE
<input type="checkbox"/> SITE	PUBLIC ACQUISITION	ACCESSIBLE	<input type="checkbox"/> ENTERTAINMENT <input type="checkbox"/> RELIGIOUS
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input checked="" type="checkbox"/> YES: RESTRICTED	<input type="checkbox"/> GOVERNMENT <input type="checkbox"/> SCIENTIFIC
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> INDUSTRIAL <input type="checkbox"/> TRANSPORTATION
		<input type="checkbox"/> NO	<input type="checkbox"/> MILITARY <input type="checkbox"/> OTHER:

4 OWNER OF PROPERTY

NAME

Grace L. Carpenter

Telephone #: 275-2032

STREET & NUMBER

CITY, TOWN

Earleville

VICINITY OF

STATE, zip code

Maryland 21919

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,
REGISTRY OF DEEDS, ETC.

Clerk of the Circuit Court

Liber #: RRC 46

Folio #: 77

STREET & NUMBER

Cecil County Courthouse

CITY, TOWN

Elkton

STATE

Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

FEDERAL STATE COUNTY LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

CE-931

CONDITION		CHECK ONE	CHECK ONE
<input checked="" type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input checked="" type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCELUSBY HOUSE

The Lusby house circa 1840-1860 is a two and one-half story five bay by one room center hall frame house on Stemmers Run Road and northwest of Earleville, Maryland. The house faces north with the main gable running east/west.

The two and one-half five bay main block has a one and one-half approximately square (one bay by one room) log kitchen section attached to the east side. Both sections rest on a partial field-stone basement and are covered with asbestos siding over weather-board. The slopes of both roofs are approximately equal and covered with composition tile. The north (main) facade of the five bay block has a central entrance with four panel door. The surrounds are slightly beaded on the first floor but survive with ovolo backbands on the second. The window sash are a typical six-over-six throughout. A flat roofed porch with square posts covers three central bays of the main block. The north slope of the roof is pierced by two six-over-six sash gabled dormers with fluted pilasters that support a simple pediment. A simple boxed cornice stretches across with a simple bed molding.

The west end is void of any detail outside simple bargeboards that protect the rafter end and a brick gable end chimney.

The south side has an asymmetrical placement of lights on the first floor. A central four panel door has two six-over-six sash to the east. Three six-over-six sash are evenly spaced across the second floor. A single six-over-six dormer lights the western half of the attic. Shutters were attached at one time and their pintels attest to that fact.

The east end is partially covered with the story and a half log kitchen. Another chimney does rise out of the east gable end. The kitchen wing is 14' 4" deep by 14' 10". A brick stack rises out of the east end. One six-over-six sash window is found on the north side and a door and window on the east end. The south side is covered by a single story shed porch. Another entrance is found on this side also.

The interior of this house was regrettably closed for any inspection of interior woodwork. The exterior has remained basically intact and I would therefore assume the interior has remained basically the same.

A log meat house with V-notched corner construction is found directly south of the main house with its central board door and strap hinges and vertical board siding, which is relatively new to the structure. A steeply pitched corrugated tin roof covers the 14' 3" by 12' 2" structure. Various barn structures are located to the south of the meat house. One two story hay barn is in rather precarious condition with its eastward leanings. It seems unusually long and narrow when compared to most frame barns.

CONTINUE ON SEPARATE SHEET IF NECESSARY

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input checked="" type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

SIGNIFICANCE

The Lusby house is an extremely important example of the progression in farmhouse construction for Cecil County. The typical story and a half log section is always alluded to by owners of similar properties but was torn down for modern conveniences. The mid 19th Century frame section, although a common form, is a sturdy and well proportioned example of the five bay center hall single pile plan. The interior is probably exemplary of mid 19th Century woodwork and design.

The sequence of construction is partially documented in the tax history of the property in the Cecil County Tax Records; however, a few inconsistencies remain to cloud the exact construction sequence. The 1841 tax assessment lists Anna E. Lusby as owning 187 acres, new dwelling and one slave all totaling \$1,699.00. The slave was valued at \$200.00 alone which leaves \$1,499.00 for a new dwelling and 187 acres. If the land was assessed at \$7.00 per acre, which is rather low for the period, it would only leave \$190 for a new dwelling. This would probably approach the value of the one and one-half story log section and not the main block. Evidence of the kitchens earlier independence can only be found on the interior wall that abutts the main block. A source of confusion does rise in the 1858-1860 tax books which list a frame house when the kitchen section is reputedly log. In 1861 an addition to the house appears on the books and valued at \$300.00 which could be the main five bay frame block.

If the structure did evolve in the aforesaid manner the Lusby house is a rare example of that progression from one room story and a half log section to a five bay two and one-half story center hall plan with kitchen wing.

A log meat house with V-notched corner construction is significant structure on the property since only a few of these structures remain in the county.

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE _____ COUNTY _____

STATE _____ COUNTY _____

11 FORM PREPARED BY

NAME / TITLE

Paul B. Touart Historic Sites Surveyor

ORGANIZATION

Cecil County Committee

DATE

11/29/79

STREET & NUMBER

Cecil County Courthouse

TELEPHONE

398-7568

CITY OR TOWN

Elkton

STATE

Maryland 21921

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438



Earleville Ohio

Q CF-93.1

Arnold Pt Light

Veazey Cem

St Pauls Ch Cem

St S Ch

Campground

Crystal Beach

Gravel Pit

BM 85

Pearce

SASSA

PEARCE

CRYSTAL NECK

VEAZEY

NECK

NECK

NECK

POPLAR NECK

ROAD

ROAD

ROAD

Project Dev 24 15

BM



CC-931

(28)

Lusby House
SOUTHERN ELEVATION
~~UNDERGROUND~~

ON
CECILTON, MD.

PBT

6/79

Dev. By
Elizabeth E. Booth

9/22/79



PE-931

(25)

LUSBY HOUSE
NORTHWEST ORIENTATION

NR ~~WILKINSON~~ MD
EARLEVILLE

6/79 PBT

W. E. Booth

9/22/79



(26)

Lusby House
NORTHWEST ELEVATION
Rt WA EARLEVILLE, MD.
6/79 PBT

PE-231

Elizabeth E. South

9/22/79