

D-107
1601075964

MARYLAND HISTORICAL TRUST WORKSHEET

NOMINATION FORM
for the
NATIONAL REGISTER OF HISTORIC PLACES, NATIONAL PARKS SERVICE

SEE INSTRUCTIONS

1. NAME

COMMON:
W. E. Stitely House

AND/OR HISTORIC:

2. LOCATION

STREET AND NUMBER:
Rt. 50

CITY OR TOWN:
East New Market

STATE: Maryland COUNTY: Dorchester

3. CLASSIFICATION

CATEGORY (Check One)	OWNERSHIP	STATUS	ACCESSIBLE TO THE PUBLIC
<input type="checkbox"/> District <input type="checkbox"/> Site <input type="checkbox"/> Object <input checked="" type="checkbox"/> Building <input type="checkbox"/> Structure 	<input type="checkbox"/> Public <input checked="" type="checkbox"/> Private <input type="checkbox"/> Both 	Public Acquisition: <input type="checkbox"/> In Process <input type="checkbox"/> Being Considered <input checked="" type="checkbox"/> Occupied <input type="checkbox"/> Unoccupied <input type="checkbox"/> Preservation work in progress 	Yes: <input type="checkbox"/> Restricted <input type="checkbox"/> Unrestricted <input checked="" type="checkbox"/> No
PRESENT USE (Check One or More as Appropriate)			
<input checked="" type="checkbox"/> Agricultural <input type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Entertainment 	<input type="checkbox"/> Government <input type="checkbox"/> Industrial <input type="checkbox"/> Military <input type="checkbox"/> Museum 	<input type="checkbox"/> Park <input checked="" type="checkbox"/> Private Residence <input type="checkbox"/> Religious <input type="checkbox"/> Scientific 	<input type="checkbox"/> Transportation <input type="checkbox"/> Other (Specify) _____ _____

4. OWNER OF PROPERTY

OWNER'S NAME:
Walter E. Stitely, life estate

STREET AND NUMBER:
RFD 1

CITY OR TOWN: East New Market STATE: Maryland 21631

5. LOCATION OF LEGAL DESCRIPTION

COURTHOUSE, REGISTRY OF DEEDS, ETC.:
Dorchester County Courthouse

STREET AND NUMBER:
High Street

CITY OR TOWN: Cambridge STATE: Maryland 21613

Title Reference of Current Deed (Book & Pg. #): 187/690, 69/57

6. REPRESENTATION IN EXISTING SURVEYS

TITLE OF SURVEY:

DATE OF SURVEY: Federal State County Local

DEPOSITORY FOR SURVEY RECORDS:

STREET AND NUMBER:

CITY OR TOWN: STATE:

7. DESCRIPTION	
CONDITION	<div style="text-align: center; margin-bottom: 5px;">(Check One)</div> <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Deteriorated <input type="checkbox"/> Ruins <input type="checkbox"/> Unexposed
	<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <div style="text-align: center; margin-bottom: 5px;">(Check One)</div> <input checked="" type="checkbox"/> Altered <input type="checkbox"/> Uncltered </div> <div style="width: 45%;"> <div style="text-align: center; margin-bottom: 5px;">(Check One)</div> <input type="checkbox"/> Moved <input checked="" type="checkbox"/> Original Site </div> </div>
DESCRIBE THE PRESENT AND ORIGINAL (if known) PHYSICAL APPEARANCE	
<p>W. E. Stitely House is a two part building of the second quarter of the 19th century. It consists of a three bay, two story section with a two bay, one and one-half story wing, all built at the same time. It had a two story porch which appears to have been original. Although the sash on both stories have 6/6 sash, there is a classical size differential. The grey asbestos siding covers the original beaded clapboard. The building is constructed on a full brick foundation and has interior chimneys at both ends. Behind the east room is a small section which is now used for a kitchen, but which may have been a hyphen to an early kitchen.</p> <p>The interior is divided into a central stair hall with a single room on each side. An enclosed stair is contained in the southeast corner of the east room. Apparently the two bedrooms above were not originally connected to the bedrooms over the other part of the house, though there is a door now.</p> <p>Roof framing in the attic has mortised and tenon and pegged joints with nailed tie beams, having a lap taken out of the tie beam only, thus the rafter is that much stronger.</p>	

SEE INSTRUCTIONS

8. SIGNIFICANCE			
PERIOD (Check One or More as Appropriate)			
<input type="checkbox"/> Pre-Columbian	<input type="checkbox"/> 16th Century	<input type="checkbox"/> 18th Century	<input type="checkbox"/> 20th Century
<input type="checkbox"/> 15th Century	<input type="checkbox"/> 17th Century	<input checked="" type="checkbox"/> 19th Century	
SPECIFIC DATE(S) (If Applicable and Known)			
AREAS OF SIGNIFICANCE (Check One or More as Appropriate)			
<input type="checkbox"/> Aboriginal	<input type="checkbox"/> Education	<input type="checkbox"/> Political	<input type="checkbox"/> Urban Planning
<input type="checkbox"/> Prehistoric	<input type="checkbox"/> Engineering	<input type="checkbox"/> Religion/Philosophy	<input type="checkbox"/> Other (Specify)
<input type="checkbox"/> Historic	<input type="checkbox"/> Industry	<input type="checkbox"/> Science	_____
<input type="checkbox"/> Agriculture	<input type="checkbox"/> Invention	<input type="checkbox"/> Sculpture	_____
<input checked="" type="checkbox"/> Architecture	<input type="checkbox"/> Landscape Architecture	<input type="checkbox"/> Social/Humanitarian	_____
<input type="checkbox"/> Art	<input type="checkbox"/> Literature	<input type="checkbox"/> Theater	_____
<input type="checkbox"/> Commerce	<input type="checkbox"/> Military	<input type="checkbox"/> Transportation	_____
<input type="checkbox"/> Communications	<input type="checkbox"/> Music		_____
<input type="checkbox"/> Conservation			_____
STATEMENT OF SIGNIFICANCE			
<p style="margin: 0;">This house has a striking similarity to the Big Mill Farm and the fact that it had a porch coincides with the presence of a porch on the Woodland Farm on Dailsville Road, which is dated 1847.</p> <p style="margin: 0;">It is interesting to see that in Dorchester County this two-part house, typical of earlier periods and often as a result of growth, were being constructed, while north of here the whole house would have been all two stories tall at this period.</p>			

SEE INSTRUCTIONS

9. MAJOR BIBLIOGRAPHICAL REFERENCES

Blank area for Major Bibliographical References.

10. GEOGRAPHICAL DATA

LATITUDE AND LONGITUDE COORDINATES DEFINING A RECTANGLE LOCATING THE PROPERTY			OR	LATITUDE AND LONGITUDE COORDINATES DEFINING THE CENTER POINT OF A PROPERTY OF LESS THAN TEN ACRES		
CORNER	LATITUDE	LONGITUDE		LATITUDE	LONGITUDE	
	Degrees Minutes Seconds	Degrees Minutes Seconds		Degrees Minutes Seconds	Degrees Minutes Seconds	
NW	° ' "	° ' "		° ' "	° ' "	
NE	° ' "	° ' "		° ' "	° ' "	
SE	° ' "	° ' "		° ' "	° ' "	
SW	° ' "	° ' "		° ' "	° ' "	

APPROXIMATE ACREAGE OF NOMINATED PROPERTY:

Acreage Justification:

Blank area for Acreage Justification.

SEE INSTRUCTIONS

11. FORM PREPARED BY

NAME AND TITLE:
Michael Bourne, Architectural Consultant

ORGANIZATION: Maryland Historical Trust

DATE: Nov, 1972,75

STREET AND NUMBER:
Shaw House, 21 State Circle

CITY OR TOWN: Annapolis

STATE: Maryland 21401

12. State Liaison Officer Review: (Office Use Only)

Significance of this property is:

National State Local

Signature _____

SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE

<p>1. STATE COUNTY <i>Dorchester</i> TOWN <i>East New Market</i> VICINITY STREET NO. <i>Rt 50</i></p> <p>ORIGINAL OWNER ORIGINAL USE <i>Dwelling</i> PRESENT OWNER <i>W. E. Stitely</i> PRESENT USE <i>Dwelling</i> WALL CONSTRUCTION <i>Frame</i> NO. OF STORIES <i>2</i></p>	<p>HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY <i>D-107</i></p> <p>2. NAME <i>W. E. Stitely</i> DATE OR PERIOD <i>c 1840-50</i> STYLE <i>Federal</i> ARCHITECT BUILDER</p> <p>3. FOR LIBRARY OF CONGRESS USE</p>
<p>4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION OPEN TO PUBLIC <i>NO</i></p> <p>W. E. Stitely House is a two part building of the second quarter of the 19th Century. It consists of a three bay, two story section with a two bay, one and one half story wing, all built at the same time. It had a two story porch which appears to have been original. Although the sash on both stories have six over six panes, there is a classical size differential. The grey asbestos siding covers the original beaded clapboard. The building is constructed on a full brick foundation and has interior chimneys at both ends. Behind the east room is a small section which is now used for a kitchen, but which may have been a hyphen to an early kitchen.</p> <p>The interior is divided into a central stair hall with a single room on each side. An enclosed stair is contained in the southeast corner of the east room. Apparantly the two bedrooms above were not originally connected to the bedrooms over the other part of the house, though there is a door now.</p> <p>Roz framing in the attic has mortised, tenon and pegged mortors under nailed tie beams, having a lap taken out of the tie beam only, thus the rafter is that much stronger.</p> <p>There is a possibility Mr. Stitely would sell the house, if it were removed from the property.</p>	
<p>5. PHYSICAL CONDITION OF STRUCTURE Endangered <i>yes</i> Interior Exterior <i>fair</i></p>	
<p>6. LOCATION MAP (Plan Optional)</p>	<p>7. PHOTOGRAPH</p>
<p>8. PUBLISHED SOURCES (Author, Title, Pages) INTERVIEWS, RECORDS, PHOTOS, ETC.</p>	<p>9. NAME, ADDRESS AND TITLE OF RECORDER</p> <p style="text-align: center;">Michael O. Bourne</p> <p style="text-align: right;">DATE OF RECORD 11/30/72</p>

.14 X 1.85

100% ~~15%~~

D-107



W.E. Stitely house

D-107

M. Bourne Nov 1975