

**INDIVIDUAL PROPERTY/DISTRICT  
MARYLAND HISTORICAL TRUST  
INTERNAL NR-ELIGIBILITY REVIEW FORM**

Property/District Name: Willard R. and Glendine Ringer Farm House Survey Number: G-VI-A-052

Project: US 219/Oakland Vicinity Improvement Project Agency: MSHA

Site visit by MHT Staff:  No  Yes Name \_\_\_\_\_ Date \_\_\_\_\_

Eligibility recommended  Eligibility not recommended

Criteria:  A  B  C  D Considerations:  A  B  C  D  E  F  G  None

Justification for decision: (Use continuation sheet if necessary and attach map)

The Willard R. and Glendine Ringer Farm, with its main dwelling built *circa* 1890 facing the bed of an earlier road and the tracks of the current CSX Railroad, documents the agricultural landscape surrounding the county seat of Oakland in the late nineteenth and early twentieth centuries. Several semi-ruinous farm buildings that were once associated with the main dwelling remain on the property, suggesting something of the original extent of this farm complex. Agriculture was the predominant economic activity outside of Oakland, as farmland comprised about 50 percent of the county's land mass in 1880, and more than 60 percent by 1910. Farms of this period typically raised potatoes, orchard products, oats, corn, buckwheat, wheat, rye, and barley as well as cattle, sheep, swine, and horses.

Research has not identified any associations with the lives of persons significant to the Oakland area's past or with events that have contributed significantly to broad patterns of the area's historical development. The architecture does not represent a particularly distinctive type, period, or method of construction, nor does it represent the work of a master, possess high artistic values, or represent a significant and distinguishable entity whose components may lack individual distinction. This resource has not yet yielded and is not likely to yield significant information important in history or prehistory.

Document on the property/district is presented in: Historic Structures Inventory and Determination of Eligibility Report

(KCI/MSHA 1997)

Prepared by: Gabrielle M. Lanier/KCI Technologies, Inc.

Concur - M. H. G. for NHP OAG 7/20/18  
Reviewer, Office of Preservation Services Date

NR program concurrence:  yes  no  not applicable

BK \_\_\_\_\_  
Reviewer, NR program Date

*Handwritten signature*

Willard R. and Glendine Ringer Farm  
~~G-IV-A-052~~ G-VI-A-052  
470 Liberty Street  
Oakland Vicinity  
Circa 1890  
Private

This farm complex includes a farmhouse, a garage and shed, and several other deteriorating agricultural buildings. The house is a two-story, three-by-three-bay, gable-roofed frame L-plan dwelling with five masonry chimneys, a shed-roofed front porch, a one-story gable-roofed rear addition, and an overhanging second story shed-roofed addition off the rear ell. The main block includes a stone foundation, asbestos-clad walls, and a standing-seam metal gable roof. It is lit mostly by one-over-one, double-hung wooden sash with wooden trim. Most of the entrances contain paneled wood and glass doors. Although the main road now runs along the eastern side of the house, the most formal entrance of this dwelling was originally oriented to an earlier roadbed which runs to the southwest. The roadbed, which is still visible, parallels the tracks of the CSX Railroad. The house faces southwest and stands on an open, gently sloping site about one mile northwest of Oakland.

The Willard R. and Glendine Ringer Farm, with its main dwelling built *circa* 1890 facing the bed of an earlier road and the tracks of the current CSX Railroad, documents the agricultural landscape surrounding the county seat of Oakland in the late nineteenth and early twentieth centuries. Several semi-ruinous farm buildings that were once associated with the main dwelling remain on the property, suggesting something of the original extent of this farm complex.

# Maryland Historical Trust Maryland Inventory of Historic Properties Form

Inventory No. G-VI-A-052

## 1. Name of Property (indicate preferred name)

historic

other William R. and Glendine Ringer Farm

## 2. Location

street & number 470 Liberty Street \_\_\_\_\_ not for publication

city, town Oakland X vicinity

county Garrett

## 3. Owner of Property (give names and mailing addresses of all owners)

name William R. and Glendine Ringer

street & number 470 Liberty Street telephone (301) 344-2538

city, town Oakland state and zip code MD 21550-5506

## 4. Location of Legal Description

courthouse, registry of deeds, etc. Garrett County Courthouse tax map and parcel 78-1-48

city, town Oakland liber and folio 134/239

## 5. Primary Location of Additional Data

- Contributing Resource in National Register District  
 Contributing Resource in Local Historic District  
 Determined Eligible for the National Register/Maryland Register  
 Determined Ineligible for the National Register/Maryland Register  
 Recorded by HABS/HAER  
 Historic Structure Report or Research report at MHT  
 Other:

## 6. Classification

Category	Ownership	Current Function		Resource Count		
				Contributing	Noncontributing	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input type="checkbox"/> agriculture	<input type="checkbox"/> landscape	<u>8</u>	<u>3</u>	buildings
<u>X</u> building(s)	<u>X</u> private	<input type="checkbox"/> commerce/trade	<input type="checkbox"/> recreation/ culture	<u>0</u>	<u>0</u>	sites
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> defense	<input type="checkbox"/> religion	<u>0</u>	<u>0</u>	structures
<input type="checkbox"/> site		<u>X</u> domestic	<input type="checkbox"/> social	<u>0</u>	<u>0</u>	objects
<input type="checkbox"/> object		<input type="checkbox"/> education	<input type="checkbox"/> transportation	<u>8</u>	<u>3</u>	Total
		<input type="checkbox"/> funerary	<input type="checkbox"/> work in progress			
		<input type="checkbox"/> government	<input type="checkbox"/> unknown			
		<input type="checkbox"/> health care	<input type="checkbox"/> vacant/not in use			
		<input type="checkbox"/> industry	<input type="checkbox"/> other:			
				<b>Number of Contributing Resources previously listed in the Inventory</b>		
						<u>0</u>

---

## 7. Description

Inventory No. G-VI-A-052

---

### Condition

<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated
<input checked="" type="checkbox"/> good	<input type="checkbox"/> ruins
<input type="checkbox"/> fair	<input type="checkbox"/> altered

---

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

This farm complex includes a farmhouse, a garage and shed, and several other deteriorating agricultural buildings. This is a two-story, three-by-three-bay, gable-roofed frame L-plan dwelling with a shed-roofed front porch, a one-story gable-roofed rear addition with a projecting gable, and an overhanging second story shed-roofed addition off the rear ell. The house faces southwest and stands on an open, gently sloping site about one mile northwest of Oakland. This dwelling still faces the bed of an earlier road and the tracks of the CSX Railroad rather than the present main road.

The house rests on an uncoursed and roughly dressed fieldstone foundation that encloses a full cellar. It is sheathed in green asbestos siding with white trim; the upper parts of the gables are sheathed in white wavy-edged asbestos shingles. The main block and the rear two-story ell are topped with standing-seam metal gable roofs finished with plywood boxed eaves and a flat wooden verge. The rear one-story addition is topped with an asphalt-shingled roof. Five masonry chimneys are present. Three of these are interior brick chimneys with corbelled tops, two of which are located toward either end of the main block at the ridge and one of which rises from the southeast slope of the roof covering the rear ell. The other two chimneys are built of concrete block with projecting clay flue tiles. One rises on the outside of the northwest gable wall; the other, an interior stack, exits from the northwest slope of the roof over the one-story rear addition.

Windows are mostly single, one-over-one, double-hung wooden sash finished with flat wooden surrounds and sills. Several one-light hopper windows are also present. The two first-floor windows flanking the front door are shaded by awnings. The front entrance is centered on the southwest elevation and is fitted with a paneled wooden door with a glass-paned upper section. The rear entrance leads into the northeast side of the one-story rear addition; it contains a paneled wood three-light half-glass door. Both door openings are finished with flat wooden surrounds and sills. A bulkhead entrance flanked by stone retaining walls pierces the southeast gable.

The open-sided front porch spans only about one-quarter of the width of the house. It includes a concrete block foundation and deck and a pole-supported shed roof clad in asphalt shingles. Fiberboard sheathes the exposed gable peaks, and a set of stone steps leads up to the level of the porch deck. The rear porch consists of a slate-covered concrete deck with a stone balustrade on one side, a mixture of turned and four-by-four wooden posts, and a shed roof protected with tarred standing seam metal. Green asbestos shingles sheath the exposed gable of the porch roof. A protected patio area is formed by the overhanging second-floor addition on the southeast side of the rear ell. This overhanging addition is supported on a mixture of metal poles and turned wooden posts; it is clad in the same green asbestos shingles as the rest of the house and is protected by an extension of the southeast slope of the same roof that covers the rear ell. The patio below consists of poured concrete. The one-story gable-roofed rear addition projects from the rear ell. The lower part of this extension is clad in a facing of dressed coursed stone; asbestos shingles sheath the upper part. The upper gables are sheathed in wooden weatherboards laid in a chevron pattern. The addition is topped by an asphalt-shingled roof with a boxed wooden cornice and a projecting gable. Wooden hopper windows light the interior.

Just east of the house stands a one-story pyramidal-roofed frame shed. The foundation of this building was not visible when the property was surveyed, but the walls are clad in green wavy-edged asbestos siding finished with white wooden corner boards. The building is topped with a red asphalt-shingled roof finished with zigzag edges. A paneled wooden door finished with flat wooden surrounds pierces the northwest elevation. To the northeast stands a one-story frame gable-fronted garage with an attached leanto. This building is clad in green asbestos siding and topped with a rolled asphalt gable roof finished with a wooden eave. One large overhead wooden garage-sized door pierces the southwest elevation, and a standard-sized paneled wooden door pierces the southwest wall of the leanto addition. West of the house stands a one-story shed-roofed frame shed. Clad in green rolled asphalt and topped by a corrugated metal roof, this building is accessed by a vertical board door in its northeast elevation. West of the garage stands a small 1/2-story frame rabbit hutch or dog house clad in wooden boards and topped with a shed roof.

# Maryland Historical Trust

## Maryland Inventory of Historic Properties Form

Inventory No. G-VI-A-052

Name

Continuation Sheet

Number 7 Page 2

---

Further up the hill to the northeast stand several more partially or completely ruinous frame buildings that relate to an earlier farm complex on this site. These buildings are accessed by a grass drive that extends in a northeasterly direction beyond the existing macadam driveway.

An L-shaped building consisting of a one-story gable-roofed gable-fronted frame garage with an attached gable-roofed shed addition stands furthest to the northeast. The garage portion of this building rests on a concrete block foundation; it is sheathed in asphalt brick siding and topped with an asphalt-shingled roof. A set of swinging wooden doors provides access to the interior. A leanto addition adjoins each long wall; one of these additions is topped with a corrugated metal roof. The attached one-story gable-roofed frame shed is clad in board-and-batten siding and topped with an asphalt-shingled roof; it, too, has been extended with a small shed-roofed leanto on one gable. A paneled wooden door finished with flat wooden surrounds provides access to the interior.

Just to the northwest stands a semi-ruinous wooden A-shaped hay barrack or shed. This structure is simply built of sloping wooden boards. A rectangular shed stands to the east. This building rests on a concrete block foundation finished with red mortar joints. It is clad in a mixture of asphalt shingles and corrugated metal and topped with a corrugated metal shed roof. A garage-sized wooden door pierces one long elevation, and a standard-sized vertical board door finished with plain wooden surrounds leads into the gable. A series of four-light fixed wooden sash windows pierce the southwest elevation. A round stone silo foundation stands immediately adjacent to this building. Several metal turnbuckles are stacked on top of the foundation. A shed-roofed stone and frame shed with a single stone wall stands next to the silo foundation. This building is clad in asphalt siding and topped with a corrugated metal roof. A concrete block foundation remnant that parallels the long axis of this building rests just to the east; this foundation ruin probably relates to this shed. A partially ruinous one-story gable-roofed corn crib stands further to the southwest, about midway between the house and the sheds and silo foundation. This building is clad in a mixture of horizontal wooden slats and boards and topped with a corrugated metal and rolled asphalt roof. Diagonal wooden poles presently brace one long wall. A vertical board door pierces the east gable. A partially ruinous one-story frame shed-roofed privy stands just west of the corn crib. This building rests on wooden piers; it is sheathed in horizontal planks and topped with a corrugated metal roof. A flat wooden door pierces the southwest elevation.

A line of wooden worm fence runs across the northernmost portion of the property. The lower portion of the property is mostly open, while the upper section leading to the partially ruinous outbuildings is semi-shaded with a mixture of deciduous and coniferous trees. A macadam driveway that runs perpendicular to the main road leads up to the main house and runs between the northern side of the house and the garage. Although the main road now runs along the eastern side of the house, the most formal entrance of this dwelling was originally oriented to an earlier roadbed which runs to the southwest. The roadbed, which is still visible, parallels the tracks of the CSX Railroad. The house is presently occupied and in good to fair condition.

## 8. Significance

Inventory No. G-VI-A-052

Period	Areas of Significance	Check and justify below		
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> health/medicine	<input type="checkbox"/> performing arts
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> archeology	<input type="checkbox"/> education	<input type="checkbox"/> industry	<input type="checkbox"/> philosophy
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> architecture	<input type="checkbox"/> engineering	<input type="checkbox"/> invention	<input type="checkbox"/> politics/government
<input checked="" type="checkbox"/> 1900-1999	<input type="checkbox"/> art	<input type="checkbox"/> entertainment/ recreation	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 2000-	<input type="checkbox"/> commerce	<input type="checkbox"/> ethnic heritage	<input type="checkbox"/> law	<input type="checkbox"/> science
	<input type="checkbox"/> communications	<input checked="" type="checkbox"/> exploration/ settlement	<input type="checkbox"/> literature	<input type="checkbox"/> social history
	<input type="checkbox"/> community planning		<input type="checkbox"/> maritime history	<input type="checkbox"/> transportation
	<input type="checkbox"/> conservation		<input type="checkbox"/> military	<input type="checkbox"/> other:

**Specific dates** Circa 1890 **Builder/Architect** Unknown

Evaluation for:

National Register     Maryland Register     not evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance reports, complete evaluation on a DOE Form - see manual).

The Willard R. and Glendine Ringer Farm, with its main dwelling built *circa* 1890 facing the bed of an earlier road and the tracks of the current CSX Railroad, documents the agricultural landscape surrounding the county seat of Oakland in the late nineteenth and early twentieth centuries. Several semi-ruinous farm buildings that were once associated with the main dwelling remain on the property, suggesting something of the original extent of this farm complex. Agriculture was the predominant economic activity outside of Oakland, as farmland comprised about 50 percent of the county's land mass in 1880, and more than 60 percent by 1910. Farms of this period typically raised potatoes, orchard products, oats, corn, buckwheat, wheat, rye, and barley as well as cattle, sheep, swine, and horses.

# Maryland Historical Trust Maryland Inventory of Historic Properties Form

Inventory No. G-VI-A-052

Name  
Continuation Sheet  
Number 8 Page 1

---

## HISTORIC CONTEXT:

### **MARYLAND COMPREHENSIVE PRESERVATION PLAN DATA**

Geographic Organization: Western Maryland

Chronological/Developmental Period(s): Industrial / Urban Dominance, A.D. 1870 - 1930

Historic Period Theme(s): Agriculture

Resource Type:

Category: Building

Historic Environment: Rural

Historic Function(s) and Use(s): Dwelling and agricultural buildings

Known Design Source: None

---

## 9. Major Bibliographical References

---

Inventory No. G-VI-A-052

(See Continuation Sheet)

---

## 10. Geographical Data

---

Acreage of property 64.61 acres  
Acreage surveyed 64.61 acres  
Quadrangle name Oakland, MD-WVA

Quadrangle scale 1:24,000

---

### Verbal boundary description and justification

Parcel 48, Map 78, Grid 1

---

## 11. Form Prepared By

---

name/title Gabrielle M. Lanier / Architectural Historian

organization KCI Technologies, Inc.

date 3-12-97

street & number 10 North Park Drive

telephone 410-316-7857

city or town Hunt Valley

state and zip code MD 21030-1888

---

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust  
DHCD/DHCP  
100 Community Place  
Crownsville, MD 21032  
410-514-7646

# Maryland Historical Trust

## Maryland Inventory of Historic Properties Form

Name

Continuation Sheet

Number 9 Page 1

---

### BIBLIOGRAPHY

Garrett County Historical Society. v. d. Vertical Files. On file at the Garrett County Historical Society, Oakland, MD.

Lacoste, Kenneth C., Robert D. Wall, and Robert C. Sonderman. *An Archeological Study of the Western Maryland Coal Region: The Historic Resources*. Maryland Geological Survey. Report on file at the Maryland Historical Trust, Crownsville, MD. 1989.

Roberts, Charles S. *West End, Cumberland to Grafton, 1848-1991*. Barnard, Roberts & Co., Inc., Baltimore, MD. 1991.


Schlosnagle, Stephen, and The Garrett County Bicentennial Committee. *Garrett County, A History of Maryland's Tableland*. McClain Printing Company, Parsons, West Virginia. Second Edition. 1989.

Ware, Donna M., and Mark R. Edwards. *Final Report of the Coal Region Historic Sites Survey, Volume I: Methodology and Management Plan*. Maryland Historical Trust. Report on file at the Maryland Historical Trust, Crownsville, MD. 1984.

Ware, Donna M., Orlando Ridout V and Geoffrey B. Henry. *Final Report of the Coal Region Historic Sites Survey, Volume II: Historical, Architectural, and Industrial Overviews*. Maryland Historical Trust. Report on file at the Maryland Historical Trust, Crownsville, MD. 1984.



Ware, Donna M., Orlando Ridout V, Geoffrey B. Henry and Mark R. Edwards. *Green Glades & Sooty Gob Piles*. Maryland Historical & Cultural Publications. Crownsville, MD. 1991.

Weeks, Thekla Fundenberg. *Oakland Centennial History, 1849-1949*. The Sincell Printing Company, Oakland, MD. 1949.



**Resource Sketch Map**

G-VI-A-052  
 Willard R. and Glendine Ringer Farm  
 Oakland, Garrett County



**Location Map**  
 G-VI-A-052  
 Willard R. and Glendine Ringer Farm  
 Oakland, Garrett County  
 Oakland, MD-WVA Quadrangle Map (USGS 1974)



G-VI-A-052

GARRETT COUNTY, MD

STUART DIXON

1/22/97

MD SHPO

0

55 1005 0-15 15

55

0557

+05-04+0 -06 NH

W + S ELEVATIONS LOOKING E

1 OF 10



G-VI-A-052

GARRETT COUNTY, MD  
STUART DIXON

1/22/97

MD SHPD


N + W ELEVATIONS OF

2 OF 10

54 1005-15 15 0

+05-04+0 -06 NN 0557

SHED LOOKING SE



G-IV-A-052

GARRETT COUNTY, MD  
STUART DIXON  
1/22/97

MD SHPO

N+E ELEVATIONS OF SHED LOOKING SW

3 OF 10

0

53 1005-0-15 15

53

0557

+05-04+0 -06 NN



G-VI A-052

GARRETT COUNTY, MD  
STUART DIXON

1/22/97

MD SHPO

0

1885 0 0 15

52

0557

+05-04+0 -06 NH

SW + SE ELEVATIONS OF HNY BARRACK  
LOOKING N

4 OF 10



G-IV-A052

GARRETT COUNTY, MD

STUART DIXON

1/22/97

MD SHPO

SW + SE ELEVATIONS OF SHED/SILO GROUP  
LOOKING N

5 OF 10

0

51. 1005 0-15 15

51.

0557

+05-04+0 107 MN



G-VI-A-052

GARRETT COUNTY, MD

STUART DIXON

1/22/97

MD SHPO

0

1005 0-10-15


50

0557

+05-04+0 -06 NY

NE + NW ELEVATIONS CONNECTED SHEETS  
LOOKING S

6 OF 10



G-VI-A-032

GARRETT COUNTY, MD

STUART DIXON

1/22/97

MD SHPO

SW + SE ELEVATIONS CONNECTED SHEDS  
LOOKING N

7 OF 10

0

1005 0-15 15

49

0557

+05-04+0 -05 NH



G-VI.A-032

GARRETT COUNTY,  
STUART DIXON

1/22/97

MD SHPO

SW + SE ELEVATIONS CRIB & PRIVY  
LOOKING N

8 OF 10

0

1005 0-15 5

48

0557

+05-04+0 -07 N



G-VI-A-052

GARRETT COUNTY, MD  
STUART DIXON

1/22/97

MD SHPO

N + E ELEVATION LOOKING SW

9 OF 10


0

10050-15 15

57

0557

+05-04+0 -06 NN



G.VI.A.052

GARRETT COUNTY, MD  
STUART DIXON  
1/22/97

MD SHPO

S + E ELEVATIONS OF GARAGE LOOKING  
NW

10 OF 10

56 1005 0-15 15 0

+05-24+0 -04 NN 0557