
7. Description

Inventory No. HA-2243

Condition

excellent deteriorated
 good ruins
 fair altered

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

A simple two-ranked, two story 45 degree pitch roof, side-gabled asymmetrical colonial revival house built in 1900, with a single story addition at the rear of the structure. The front entry is an addition with a hipped roof porch, approximately 10 X 12 feet in size. The rear addition is a low slope roof, side-gabled structure with an outside entry. The windows appear as double sash single pane (non-functional shuttered) windows.

8. Significance

Inventory No. HA-2243

Period	Areas of Significance	Check and justify below		
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> health/medicine	<input type="checkbox"/> performing arts
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> archeology	<input type="checkbox"/> education	<input type="checkbox"/> industry	<input type="checkbox"/> philosophy
<input type="checkbox"/> 1800-1899	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> engineering	<input type="checkbox"/> invention	<input type="checkbox"/> politics/government
<input checked="" type="checkbox"/> 1900-1999	<input type="checkbox"/> art	<input type="checkbox"/> entertainment/ recreation	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 2000-	<input type="checkbox"/> commerce	<input type="checkbox"/> ethnic heritage	<input type="checkbox"/> law	<input type="checkbox"/> science
	<input type="checkbox"/> communications	<input type="checkbox"/> exploration/ settlement	<input type="checkbox"/> literature	<input type="checkbox"/> social history
	<input type="checkbox"/> community planning		<input type="checkbox"/> maritime history	<input type="checkbox"/> transportation
	<input type="checkbox"/> conservation		<input type="checkbox"/> military	<input type="checkbox"/> other: _____

Specific dates

Architect/Builder

Construction dates 1900

Evaluation for:

National Register


Maryland Register

not evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance projects, complete evaluation on a DOE Form – see manual.)

Representative example of the colonial revival style.

HA-2243
510 Maxa Road
Aberdeen Quadrangle, 1953 (Photorevised 1985)



National Web Map Service 6" Orthophoto Map,
Overlay with MD State Planning parcel boundaries

Harford County Tax Maps 201 and 202
(Tax Map 201, Parcel 63)

