

**MARYLAND HISTORICAL TRUST  
DETERMINATION OF ELIGIBILITY FORM**

NR Eligible: yes   
no

Property Name: Robert Smith Stone House - Abbott's Forest Inventory Number: HA-987

Address: West side of Carsins Run Road 0.1 N. of Tower Rd. City: Carsins Run (Aberdeen) Zip Code: 21001

County: Harford County USGS Topographic Map: Aberdeen, Maryland, 1985

Owner: Robert H. Smith - 3768 Aldino Rd. Aberdeen, MD 21001 Is the property being evaluated a district? NO

Tax Parcel Number: \_\_\_\_\_ Tax Map Number: \_\_\_\_\_ Tax Account ID Number: \_\_\_\_\_

Project: Adams Property Agency: Federal Communications Commission

Site visit by MHT Staff:  no  yes Name: \_\_\_\_\_ Date: \_\_\_\_\_

Is the property located within a historic district?  yes  no

<i>If the property is within a district</i>		District Inventory Number: _____
NR-listed district <input type="checkbox"/> yes	Eligible district <input type="checkbox"/> yes	District Name: _____
Preparer's Recommendation: Contributing resource <input type="checkbox"/> yes <input type="checkbox"/> no Non-contributing but eligible in another context <input type="checkbox"/>		

<i>If the property is not within a district (or the property is a district)</i>	
Preparer's Recommendation: Eligible <input type="checkbox"/> yes <input checked="" type="checkbox"/> no	

Criteria:  A  B  C  D Considerations:  A  B  C  D  E  F  G  None

Documentation on the property/district is presented in:

**Description of Property and Eligibility Determination:** *(Use continuation sheet if necessary and attach map and photo)*

The property was most recently observed and photographed on January 17, 2003. Its condition was changed since the preparation of the Inventory Form for State Historic Sites Survey form in the library of the Maryland Historical Trust.

The property is described in the Maryland Historical Trust Inventory Form For State Historic Sites Survey prepared by Susan M. Deeney, Field historian with Harford County Historical District Commission, on June 30, 1977.

During the site visit on January 17, 2003, it was discovered that the subject property was incorrectly mapped on the USGS Topographic Map for Aberdeen, Maryland, 1985, in the library of the Maryland Historical Trust. Please find attached an accurate map of the location and please note that the correct location of the building is beyond the one mile view shed.

Prepared by: William C. Riggs, RA  
Historic Architect


Date Prepared: 01.28.03

MARYLAND HISTORICAL TRUST REVIEW	
Eligibility recommended <input type="checkbox"/>	Eligibility not recommended <input type="checkbox"/>
Criteria: <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	Considerations: <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> None
Comments: <u>NOT Evaluated</u>	
Reviewer, Office of Preservation Services	Date
Reviewer, NR Program	Date

**Photo Negative List - Adams Raw Land 09.75132.0272**

Ordered by Property Number

Roll 1		Roll 2		Roll 3		Summary	No Photos- (Bldg. demolished, or not in survey area)
Neg	Property	Neg	Property	Neg	Property		
1-33	HA-1294	2-17	HA-0987	3-4	HA-1296	HA-0987	HA-988
1-34	HA-1294	2-18	HA-0987	3-5	HA-1296	HA-0989	HA-1295
1-35	HA-1294	2-19	HA-0987	3-6	HA-1296	HA-0991	HA-1304
1-36	HA-1294	2-2	HA-0989	3-7	HA-1297	HA-0998	HA-1313
1-1	HA-1533	2-3	HA-0989	3-8	HA-1297	HA-0999	
1-2	HA-1533	2-4	HA-0989	3-9	HA-1297	HA-1293	
1-3	HA-1533	2-11	HA-0991	3-10	HA-1297	HA-1294	
1-4	HA-1533	2-12	HA-0991	3-1	HA-1554	HA-1296	
1-5	HA-1533	2-13	HA-0991	3-2	HA-1554	HA-1297	
1-6	HA-1534	2-14	HA-0991	3-3	HA-1554	HA-1533	
1-7	HA-1534	2-15	HA-0991			HA-1534	
1-8	HA-1534	2-16	HA-0991			HA-1535	
1-9	HA-1534	2-33	HA-0998			HA-1536	
1-10	HA-1534	2-34	HA-0998			HA-1553	
1-11	HA-1534	2-35	HA-0998			HA-1554	
1-12	HA-1534	2-36	HA-0998			HA-1618	
1-13	HA-1534	2-25	HA-0999			HA-1875	
1-14	HA-1534	2-26	HA-0999				
1-23	HA-1535	2-27	HA-0999				
1-24	HA-1535	2-28	HA-0999				
1-25	HA-1535	2-29	HA-0999				
1-26	HA-1535	2-30	HA-0999				
1-27	HA-1535	2-20	HA-1293				
1-28	HA-1535	2-21	HA-1293				
1-29	HA-1535	2-22	HA-1293				
1-15	HA-1553	2-23	HA-1293				
1-16	HA-1553	2-24	HA-1293				
1-17	HA-1553	2-1	HA-1536				
1-18	HA-1553	2-5	HA-1536				
1-19	HA-1553	2-6	HA-1536				
1-20	HA-1553	2-7	HA-1536				
1-21	HA-1553	2-8	HA-1536				
1-22	HA-1553	2-9	HA-1536				
1-30	HA-1618	2-10	HA-1536				
1-31	HA-1618	2-31	HA-1875				
1-32	HA-1618	2-32	HA-1875				



Map created with TOPO® ©2002 National Geographic (www.nationalgeographic.com/topo)

**SITE VICINITY MAP**  
Aberdeen, MD Quadrangle  
**SCALE: As Shown**



**Property Condition Assessment**  
HA-987\_Robert Smith Stone House  
Aberdeen, MD 21001



HA-987

ROBERT SMITH STONE HOUSE  
CARBINS RUN RD., ABERDEEN,  
HARFORD CO., MD 21001  
PHOTO BY: JAMISON STOVER, 01.17.03

NEG. @ MD 54PD  
FRONT ELEVATION

1/1

94557-2 929-9171235

ROBERT SMITH STONE HOUSE HA-987  
ABERDEEN, MD 21001 01.03

Photo Gallery, 01/29/03

HA - 987

Tract: Abbott's Forest (Robert Smith Stone House)  
Carsins Run Road  
Aberdeen, Maryland 21001

This small, stone house is located on the west side of Carsins Run Road and faces east. The two story structure has a center stairway but no through hall. A cinderblock addition hides the west facade.

The house is abandoned and in lamentable condition. It is shown on the 1858 Jennings and Herrick Map of Harford County. A twin to this house (HA - 989) is located further north on the same road.

MARYLAND HISTORICAL TRUST

HA-987

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

**1 NAME**

HISTORIC Tract: Abbott's Forest  
 AND/OR COMMON Robert Smith Stone House

**2 LOCATION**

STREET & NUMBER Carsins Run Road  
 CITY, TOWN Aberdeen VICINITY OF CONGRESSIONAL DISTRICT First  
 STATE Maryland 21001 COUNTY Harford

**3 CLASSIFICATION**

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input type="checkbox"/> PUBLIC	<input type="checkbox"/> OCCUPIED	<input type="checkbox"/> AGRICULTURE <input type="checkbox"/> MUSEUM
<input checked="" type="checkbox"/> BUILDING(S)	<input checked="" type="checkbox"/> PRIVATE	<input checked="" type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL <input type="checkbox"/> PARK
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> PRIVATE RESIDENCE
<input type="checkbox"/> SITE	<b>PUBLIC ACQUISITION</b>	<b>ACCESSIBLE</b>	<input type="checkbox"/> ENTERTAINMENT <input type="checkbox"/> RELIGIOUS
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input checked="" type="checkbox"/> YES: RESTRICTED	<input type="checkbox"/> GOVERNMENT <input type="checkbox"/> SCIENTIFIC
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> INDUSTRIAL <input type="checkbox"/> TRANSPORTATION
		<input type="checkbox"/> NO	<input type="checkbox"/> MILITARY <input type="checkbox"/> OTHER

**4 OWNER OF PROPERTY**

NAME Robert H. Smith Telephone #: 734-7715  
 STREET & NUMBER 3768 Aldino Road  
 CITY, TOWN Aberdeen VICINITY OF STATE, zip code MD 21001

**5 LOCATION OF LEGAL DESCRIPTION**

COURTHOUSE, REGISTRY OF DEEDS, ETC Harford County Courthouse Liber #: 787 Folio #: 119  
 STREET & NUMBER 40 S. Main Street  
 CITY, TOWN Bel Air, MD. 21014 STATE MD

**6 REPRESENTATION IN EXISTING SURVEYS**

TITLE  
 DATE  
 DEPOSITORY FOR SURVEY RECORDS  
 CITY, TOWN STATE

NA-287

# 7 DESCRIPTION

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED    DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

## DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This small stone house is located on the west side of Carsins Run Road and faces east. This rubble stone structure is two stories high and covered with asphalt. A stuccoed, corbelled brick chimney is located at each inside end. The principal door is in the center bay of the east facade. A two light transom is overhead while side lights of three panes each flank the door way. Windows through out the house are six lights over six. There are four windows at the second elevation of the east facade. Attic windows of four lights are the only windows on the north and south facade.

The interior of this house could be seen through broken windows and doors. A large fireplace is still present on the north wall. It is stuccoed and has no mantle. On the south wall no fireplace remains, just a hole for a wood stove. A center stairway has a plain newel and handrail and square balusters.

A one story cinder-block addition attached to the west wall mars this house's simple beauty. A mound of rubble and old plaster is located at the rear of the house.

CONTINUE ON SEPARATE SHEET IF NECESSARY

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

This small stone house is in lamentable condition. Abandoned several years ago, this house has been vandalized and left to the elements.

The house's main unit, the three bay, two story stone section is a twin to another house, HA-989, located on Carsins Run Road, north of Churchville Road.

The 1858 Jennings and Herrick Map of the County shows a house on this spot but gives no owners name. The Martenet map of 1878 gives H. and W. Preston as the owners. This corresponds with the chain of title.

**9 MAJOR BIBLIOGRAPHICAL REFERENCES**

- 1783 Maryland Tax List
- 1798 Federal Tax List
- 1814 Maryland Tax List

CONTINUE ON SEPARATE SHEET IF NECESSARY

**10 GEOGRAPHICAL DATA**

ACREAGE OF NOMINATED PROPERTY 20 acres, 40 per.

VERBAL BOUNDARY DESCRIPTION

This property is bounded by Carsins Run Road on the East and the property of John E. Schenning on the west.

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE	COUNTY
STATE	COUNTY

**11 FORM PREPARED BY**


NAME / TITLE	Susan M. Deeney, Field Historian	June 30, 1977
ORGANIZATION	Historic District Commission	DATE
STREET & NUMBER	45 South Main Street	838-6000 ext. 207
CITY OR TOWN	Bel Air	STATE
		Maryland
		TELEPHONE

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust  
 The Shaw House, 21 State Circle  
 Annapolis, Maryland 21401  
 (301) 267-1438

HA - 987



Title Search  
HA-987

Robert H. Smith

Aberdeen RFD, MD 21001

787	119	8/19/1968	Grantor: Catherine M. Smith Grantee: Robert Henry Smith Acreage: "Abbott's Forest" 26 acres, 40 perches
SWC	230	399 7/6/1934	Grantor: Stewart O. Day Grantee: Lorenze Smith and Catherine M. Smith Acreage: 26 acres, 40 perches
DGW	203	53 3/10/1927	Grantor: William B. Walls and Jettie J., wife Grantee: William Worthington Hopkins Acreage: "Abbot's Forest"
JAR	158	215 12/22/1917	Grantor: James Fulker Grantee: William B. Walls and Jettie J., wife
ALJ	53	233 2/4/1885	Grantor: Parker F. Forwood and wife Grantee: James Fulker
ALJ	45	241 3/23/1882	Grantor: J. Henry Preston and wife, and et al Grantee: Parker F. Forwood Acreage: 52½ acres
ALJ	34	436 3/6/1877	Grantor: William F. Pannell and wife Grantee: J. Henry Preston and William T. Preston Acreage: "Abott's Forest" 52½ acres
WG	12	449 2/25/1862	Grantor: William H. Preston and Martha A., wife Grantee: William F. Pannell
ALJ	8	392 5/2/1857	Grantor: Richard Green, Henry D. Farnandis and Hannah, wife, Ralph and Mary E. Hewitt Grantee: William H. Preston "Abbott's Forest"
HD	22	125 3/23/1839	Grantor: Elizabeth Webster, et al Grantee: Richard Green Acreage: "Abbott's Fourest"

HA-987

HD	18	84	3/19/1835	Grantor: Elizabeth Webster, et al Grantee: Philip E. Thomas, exec.
HD	T	406	10/27/1808	Grantor: Isaac Lee Webster Grantee: John Lee Webster Acreage: "Abbott's Forest"
JLG	I	168	4/20/1790	Grantor: John Bond, et al Grantee: John Lee Webster
JLG	A	255	7/29/1776	Grantor: John Bond Grantee: John Talbott Acreage: "Abbott's Forrest"

1309274404 HA 987

N. R. FIELD SHEET

NATIONAL REGISTER OF HISTORIC PLACES  
INVENTORY - NOMINATION FORM

(Type all entries - complete applicable sections)

STATE:	
COUNTY:	
FOR NPS USE ONLY	
ENTRY NUMBER	DATE

**1. NAME**

COMMON: Robert Smith stone house

AND/OR HISTORIC:

**2. LOCATION**

STREET AND NUMBER: West side of Carsin's Run Road about 0.1 mi north

CITY OR TOWN: Carsin Run of Tower Road

STATE: Maryland CODE: COUNTY: Hol/ore CODE:

**3. CLASSIFICATION**

CATEGORY (Check One)	OWNERSHIP	STATUS	ACCESSIBLE TO THE PUBLIC
District <input type="checkbox"/> <u>Building</u> <input type="checkbox"/>	Public <input type="checkbox"/>	<u>Occupied</u> <input type="checkbox"/>	<u>Yes: Restricted</u> <input type="checkbox"/>
Site <input type="checkbox"/> Structure <input type="checkbox"/> <u>Private</u> <input type="checkbox"/>	Public Acquisition: <input type="checkbox"/>	Unoccupied <input type="checkbox"/>	Unrestricted <input type="checkbox"/>
Object <input type="checkbox"/>	In Process <input type="checkbox"/>	Preservation work in progress <input type="checkbox"/>	No: <input type="checkbox"/>
	Both <input type="checkbox"/>	Being Considered <input type="checkbox"/>	

PRESENT USE (Check One or More as Appropriate)

Agricultural <input type="checkbox"/>	Government <input type="checkbox"/>	<u>Park</u> <input type="checkbox"/>	Transportation <input type="checkbox"/>	Comments <input type="checkbox"/>
Commercial <input type="checkbox"/>	Industrial <input type="checkbox"/>	<u>Private Residence</u> <input type="checkbox"/>	Other (Specify) <input type="checkbox"/>	
Educational <input type="checkbox"/>	Military <input type="checkbox"/>	Religious <input type="checkbox"/>		
Entertainment <input type="checkbox"/>	Museum <input type="checkbox"/>	Scientific <input type="checkbox"/>		

**4. OWNER OF PROPERTY**

OWNERS NAME: Robert H Smith

STREET AND NUMBER: Carsin Run

CITY OR TOWN: Aberdeen BFD STATE: Md CODE:

**5. LOCATION OF LEGAL DESCRIPTION**

COURTHOUSE, REGISTRY OF DEEDS, ETC.: CLERK OF THE CIRCUIT COURT

STREET AND NUMBER: HARFORD COUNTY COURTHOUSE

CITY OR TOWN: BEL AIR STATE: MARYLAND CODE: 40 S. MAIN ST.

ACREAGE APPROXIMATE ACREAGE OF NOMINATED PROPERTY:

**6. REPRESENTATION IN EXISTING SURVEYS**

TITLE OF SURVEY:

DATE OF SURVEY: Federal  State  County  Local

DEPOSITORY FOR SURVEY RECORDS:

STREET AND NUMBER:

CITY OR TOWN: STATE: CODE:

STATE: COUNTY: ENTRY NUMBER: DATE: FOR NPS USE ONLY

7. DESCRIPTION	
CONDITION	Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> (Check One) <u>Deteriorated</u> <input checked="" type="checkbox"/> Ruins <input type="checkbox"/> Unexposed <input type="checkbox"/>
INTEGRITY	(Check One) <u>Altered</u> <input checked="" type="checkbox"/> Unaltered <input type="checkbox"/> (Check One) Moved <input type="checkbox"/> <u>Original Site</u> <input checked="" type="checkbox"/>
DESCRIBE THE PRESENT AND ORIGINAL (If known) PHYSICAL APPEARANCE	
<p>           This little stone house needs attention; there are large cracks in the masonry, and woodwork needs repair and paint.         </p> <p>           L-shaped, the house faces south, 3 bays by 0 on the first floor, 4 by 0 upstairs. Masonry has been disturbed and inadequately replaced around the two windows downstairs. A lintel is still in place, on each side, wide enough for a wagon door. The center hall door has 6 lights and 3 on the side of the doorway. Windows have 6 lights over 6 except that <sup>upstairs</sup> the lower sashes have been replaced with plywood in a way that is not secure against the weather.         </p> <p>           With no heat, electricity or telephone, the house is unsuitable for occupancy now.         </p>	

**SIGNIFICANCE**

PERIOD (Check One or More as Appropriate)

Pre-Columbian       16th Century       18th Century       20th Century   
 15th Century       17th Century       19th Century

SPECIFIC DATE(S) (If Applicable and Known)

AREAS OF SIGNIFICANCE (Check One or More as Appropriate)

Aboriginal	Education <input type="checkbox"/>	Political <input type="checkbox"/>	Urban Planning <input type="checkbox"/>
Prehistoric <input type="checkbox"/>	Engineering <input type="checkbox"/>	Religion/Philosophy <input type="checkbox"/>	Other (Specify) <input type="checkbox"/>
Historic <input type="checkbox"/>	<u>Industry</u> <input type="checkbox"/>	Science <input type="checkbox"/>	_____
Agriculture <input type="checkbox"/>	Invention <input type="checkbox"/>	Sculpture <input type="checkbox"/>	_____
Art <input type="checkbox"/>	Landscape <input type="checkbox"/>	Social/Humanitarian <input type="checkbox"/>	_____
Commerce <input type="checkbox"/>	Architecture <input type="checkbox"/>	Theater <input type="checkbox"/>	_____
Communications <input type="checkbox"/>	Literature <input type="checkbox"/>	Transportation <input type="checkbox"/>	_____
Conservation <input type="checkbox"/>	Military <input type="checkbox"/>		
<u>Architecture</u> <input type="checkbox"/>	Music <input type="checkbox"/>		

STATEMENT OF SIGNIFICANCE (Include Personages, Dates, Events, Etc.)

It is difficult to understand alterations to this house. Masonry was altered in the front wall, but not around the front door. Possibly a house was altered to make a shop for blacksmith, wheelwright etc. and then front back, leaving insets in the new masonry over two new windows?

Neglect may have foiled possibility of restoring this, but if its condition were such it could be very attractive



2 areas where masonry is disturbed

**9. MAJOR BIBLIOGRAPHICAL REFERENCES**

[Empty space for major bibliographical references]

**10. GEOGRAPHICAL DATA**

LATITUDE AND LONGITUDE COORDINATES DEFINING A RECTANGLE LOCATING THE PROPERTY			O R	LATITUDE AND LONGITUDE COORDINATES DEFINING THE CENTER POINT OF A PROPERTY OF LESS THAN ONE ACRE		
CORNER	LATITUDE	LONGITUDE		LATITUDE	LONGITUDE	
	Degrees Minutes Seconds	Degrees Minutes Seconds		Degrees Minutes Seconds	Degrees Minutes Seconds	
NW	° ' "	° ' "		° ' "	° ' "	
NE	° ' "	° ' "		° ' "	° ' "	
SE	° ' "	° ' "		° ' "	° ' "	
SW	° ' "	° ' "		° ' "	° ' "	

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE:	CODE	COUNTY	CODE
STATE:	CODE	COUNTY:	CODE
STATE:	CODE	COUNTY:	CODE
STATE:	CODE	COUNTY:	CODE

**11. FORM PREPARED BY**

NAME AND TITLE: \_\_\_\_\_

ORGANIZATION \_\_\_\_\_ DATE \_\_\_\_\_

STREET AND NUMBER: \_\_\_\_\_

CITY OR TOWN: \_\_\_\_\_ STATE \_\_\_\_\_ CODE \_\_\_\_\_

**12. STATE LIAISON OFFICER CERTIFICATION**

As the designated State Liaison Officer for the National Historic Preservation Act of 1966 (Public Law 89-665), I hereby nominate this property for inclusion in the National Register and certify that it has been evaluated according to the criteria and procedures set forth by the National Park Service. The recommended level of significance of this nomination is:

National  State  Local

Name \_\_\_\_\_

Title \_\_\_\_\_

Date \_\_\_\_\_

**NATIONAL REGISTER VERIFICATION**

I hereby certify that this property is included in the National Register.

\_\_\_\_\_  
Chief, Office of Archeology and Historic Preservation

Date \_\_\_\_\_

ATTEST:

\_\_\_\_\_  
Keeper of The National Register

Date \_\_\_\_\_

INVENTORY NO. HA-987

ELECTION DISTRICT \_\_\_\_\_

DATE: \_\_\_\_\_

TAX MAP NO. \_\_\_\_\_

REMODELING: Drastic, moderate, minor

PARCEL NO. \_\_\_\_\_

NAME OF PROPERTY: \_\_\_\_\_

LOCATION OF PROPERTY: \_\_\_\_\_

DIRECTION DWELLING FACES: East

NAME OF OWNER: Robert Smith Stone House (I guess)

ADDRESS: \_\_\_\_\_

STORIES: 1[ ] 2[X] 3[ ] 4[ ] 5[ ] 6[ ] BAYS: 2nd floor W W W W

WINGS, ADDITIONS: cinderblock  
1st W D W

WALL CONSTRUCTION:

- [ ] FRAME: Bevel, clapboard, weatherboard, wood shingles, board & batten(type?)
- [ ] BRICK: Bond type- common, English, Flemish. Sketch variants.
- [X] STONE: Bond type- rubble, ashlar (random or regular), quoins-plain, rusticated
- [ ] LOG

WALL FEATURES: BELT COURSE, PILASTERS, OTHERS \_\_\_\_\_

FOUNDATIONS: HIGH, LOW, BRICK, STONE

WATER TABLE: NONE, PLAIN, BEVELED, MOULDED BRICK

WINDOWS, TRIM, SHUTTERS: 1/1[ ] 2/2[ ] 6/6[X] 9/6[ ] 9/9[ ] other[ ]  
pegged[ ] nailed[ ] wide[ ] narrow[ ]  
original[ ] replaced[ ]

✓ ENTRANCE, DOORS: LOCATION: center  
HARDWARE: original [ ] replaced[ ]  
FAN LIGHT, TRANSOM SIDE LIGHTS, PLAIN  
2 ft 3 ft

CORNICE, BARGE, EAVES:  
original[ ] replaced[ ]

✓ ROOF: GABLE FRONT, GABLE FLANK, HIP, MANSARD, FLAT, DORMERS  
MATERIAL: wood shingles, slate, tin, asphalt original[ ] replaced[ ]

PORCHES: SHAPE OF ROOF - shed[ ] hip[ ] gable[ ]

✓ CHIMNEYS: NUMBER 2 BRICK[X] STONE[ ] CORBELED[X] original[ ] replaced[ ]  
LOCATION: each gable end stuccoed

ARCHES:

COMMENTS: 4 ft attic windows

587NA-987

ELECTION DISTRICT

DATE

TAX MAP NO.

REMARKS: (PROPERTY, ADDRESS, ETC.)

PARCEL NO.


NAME OF PROPERTY

LOCATION OF PROPERTY

DIRECTION-SURVEY LINE

NAME OF OWNER

ADDRESS



Carains Park Road

R+22

FLOOR FINISH: (MATERIAL, TYPE, ETC.)

CONCRETE, MAKE MARKS

(REMARKS) (REPLACEMENT)

ROOF: (TYPE, MATERIAL, ETC.)

(REMARKS) (REPLACEMENT)

ROOFING: (TYPE, MATERIAL, ETC.)

(REMARKS) (REPLACEMENT)

ADDRESS

OWNER



HA-987


Abbott's Forest (Robert Smith Stone House, Preston Stone House)  
1952 Aerial Photo by HistoricAerials.com




Closer view



HA-987  
Abbott's Forest (Robert Smith Stone House, Preston Stone House)  
Tax Map 51, Parcel 51



HA-987  
Abbott's Forest (Robert Smith Stone House, Preston Stone House)  
Aberdeen quadrangle 1953, Photorevised 1985





PRIVATE  
DRIVE

Robert Smith Stone House      HA-987  
Carsins Run Road  
Aberdeen, MD  
Susan M. Deeney  
East  
March, 1977