

June

INDIVIDUAL PROPERTY/DISTRICT
MARYLAND HISTORICAL TRUST
INTERNAL NR-ELIGIBILITY REVIEW FORM

Property/District Name: Buckley Farm Survey Number: HO-638

Project: Village of Long Reach Agency: F/COE

Site visit by MHT Staff: no yes Name _____ Date _____

Eligibility recommended _____ Eligibility not recommended

Criteria: A B C D Considerations: A B C D E F G None

Justification for decision: (Use continuation sheet if necessary and attach map)
The Buckley Farm consists of a dwelling and a collection of six outbuildings. Dating from the late nineteenth and early to mid 20th centuries, the complex is located off of Snowden River Parkway and south of Tamar Drive in a developing section of Columbia. The frame dwelling rises 2½ stories, measures three bays wide and is capped by a hipped roof. A cross bled bay (square tower) projects from the center of the building. A colonial revival porch was added to the main facade. A dairy barn, chicken house, corn crib, garage and failed buildings represent the agricultural component. The vernacular complex is in various states of disrepair and deterioration. The complex is a common property type which exists throughout the piedmont. Other examples retain a higher level of integrity. I concurred that the property does not meet the criteria for evaluation.

Documentation on the property/district is presented in: MD Inventory, A Phase 1 Archeological Site Identification Survey of the Village of Long Reach, and later revisions
HO-61

Prepared by: James Gibb, David Gleason

Lauren L. Bowlin 11/4/94
Reviewer, Office of Preservation Services Date

NR program concurrence: yes no not applicable
R. Anderson 15 Nov 94
Reviewer, NR program Date

MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA - HISTORIC CONTEXT

I. Geographic Region:

- Eastern Shore (all Eastern Shore counties, and Cecil)
- Western Shore (Anne Arundel, Calvert, Charles, Prince George's and St. Mary's)
- Piedmont (Baltimore City, Baltimore, Carroll, Frederick, Harford, Howard, Montgomery)
- Western Maryland (Allegany, Garrett and Washington)

II. Chronological/Developmental Periods:

- Paleo-Indian 10000-7500 B.C.
- Early Archaic 7500-6000 B.C.
- Middle Archaic 6000-4000 B.C.
- Late Archaic 4000-2000 B.C.
- Early Woodland 2000-500 B.C.
- Middle Woodland 500 B.C. - A.D. 900
- Late Woodland/Archaic A.D. 900-1600
- Contact and Settlement A.D. 1570-1750
- Rural Agrarian Intensification A.D. 1680-1815
- Agricultural-Industrial Transition A.D. 1815-1870
- Industrial/Urban Dominance A.D. 1870-1930
- Modern Period A.D. 1930-Present
- Unknown Period (prehistoric historic)

III. Prehistoric Period Themes:

- Subsistence
- Settlement
- Political
- Demographic
- Religion
- Technology
- Environmental Adaption

IV. Historic Period Themes:

- Agriculture
- Architecture, Landscape Architecture, and Community Planning
- Economic (Commercial and Industrial)
- Government/Law
- Military
- Religion
- Social/Educational/Cultural
- Transportation

V. Resource Type:

Category: buildings

Historic Environment: rural

Historic Function(s) and Use(s): domestic/residential, agricultural/farm

Known Design Source: _____

Capsule Summary

HO638

Buckley Farm Complex - Principal Dwelling

Columbia Vicinity

Private

Circa 1900

The Buckley Farm Complex Principal Dwelling is a 3-bay, 2 1/2 story frame structure located in Howard County near Dorsey Run. The dwelling has a center hall double pile plan with full front porch and half basement. The exterior of the house has been altered by the addition of asbestos shingles, alterations to the porch, and storm windows and doors and suffers from a lack of maintenance. The interior has suffered from the addition of several closets and the blocking-off of the second floor landing.

Once the main house of a small dairy farm, the principal dwelling and outbuildings is slated for removal.

Maryland Comprehensive Historic Preservation Plan Data

Buckley Farm Complex HO638

Geographic Organization

Piedmont

Chronological/Development Period

Industrial/Urban Dominance - A.D. 1870 - 1930

Historic Period Theme

Agricultural

Resource Type

Category:	Buildings
Historic Environment:	Rural
Historic Function/Use:	Farm Complex
Known Design Source:	None

Maryland Historical Trust
State Historic Sites Inventory Form

MARYLAND INVENTORY OF
HISTORIC PROPERTIES

Survey No. H0638

Magi No.

DOE yes no

1. Name (indicate preferred name)

historic

and/or common Buckley Farm Complex - Principal Dwelling

2. Location

street & number Old Montgomery Road not for publication

city, town Columbia vicinity of congressional district

state Maryland county Howard

3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input checked="" type="checkbox"/> private residence
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input checked="" type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input checked="" type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military	<input checked="" type="checkbox"/> other: Construction staging area

4. Owner of Property (give names and mailing addresses of all owners)

name Howard Research and Development Corporation

street & number 10275 Little Patuxent Parkway telephone no.:(410)992-6033

city, town Columbia state and zip code MD 21044-345

5. Location of Legal Description

courthouse, registry of deeds, etc. Howard County Courthouse liber 477

street & number folio 460

city, town Ellicott City state MD

6. Representation in Existing Historical Surveys

title none (See Architectural Assessment of the Buckley Farm Complex

date Howard County, MD-Prepared by David H. Gleason, October 14, 1994)
 federal state county local

pository for survey records

city, town state

7. Description

Condition		Check one	Check one	
<input type="checkbox"/> excellent	<input checked="" type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input checked="" type="checkbox"/> original site	
<input type="checkbox"/> good	<input checked="" type="checkbox"/> ruins	<input checked="" type="checkbox"/> altered	<input type="checkbox"/> moved	date of move _____
<input checked="" type="checkbox"/> fair	<input type="checkbox"/> unexposed			

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

CONTRIBUTING RESOURCE COUNT: 5

The principal dwelling is a 2½ story, single family, balloon frame building with a partial cellar. It consists of three principal bays with a projecting central bay, or square tower with dormer. The hipped roof has paired pediments on either end that appear to be part of the original structure. The entire roof is sheathed in galvanized metal. The upper half-story sports imbricated shake siding, while the remaining portions of all of the facades are covered in asbestos shingles. Plain board moldings highlight both the windows and the principal corners of the front (north) facade. Tongue-and-groove board has been used on all of the eaves and porch soffits.

A full-length Colonial Revival porch with tapered columns and unadorned capitals was added to the front facade. It is in poor condition with one column failing completely, another beginning to fail, and the tongue-and-groove soffit in an advanced state of decay. The rear lean-to porch is in much better condition, being wholly enclosed and serving, in part, as a laundry and utility room. Single story, projecting bays have been added to the west and east facades, retaining the bilateral symmetry of the overall exterior and interior designs. All of the windows have been conserved with metal frame storm windows. A brick chimney stack has been added to the north facade to service the oil burner in the partial cellar below. The original chimneys, however, survive and consist of symmetrically-placed interior stacks that vent at least two fireplaces on the first floor. They are devoid of decorative treatment. The overall condition of the exterior is fair, deterioration attributable to neglect over the past 25 to 30 years. Although the roof appears to be tight, the gutters have not been maintained and significant damage from stormwater is imminent. The windows also are in need of replacement.

Several partition walls have been installed, and several plaster walls have been replaced with dry wall; however, the interior first and second floors retain much of their original configuration. Two large public rooms flank the central hall with its plain paneled stair. Original half-round moldings survive throughout most of the first and second floors, at least in those public areas to which we had access. The fireplace in the east room of the first floor retains its plain mantle with machine-carved central figure of a wreath and crossed torches. Most of the surviving doors are plain paneled. The interior, in general, is in fair condition.

8. Significance

Survey No. H0638

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input checked="" type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates

Builder/Architect

check: Applicable Criteria: A B C D
and/or

Applicable Exception: A B C D E F G

Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.

The Buckley farmstead consists of a principal dwelling that dates to the last quarter of the 19th century or the first quarter of the 20th century, and a collection of at least six outbuildings that date to the early to mid-20th century. The large barn, silo and milk parlor complex probably date to the second quarter of the 20th century. The large barn, silo and milk parlor complex probably date to the second quarter of the 20th century, judging from the extensive use of concrete block in the construction. Overall, the Buckley farmstead represents a late 19th through 20th century dairy farmstead. Such farmsteads were common throughout the region into the middle of the 20th century. Rapid urbanization within the Washington-Baltimore metropolitan area, however, has largely destroyed the architectural character of the region, and, particularly, the open-pasture atmosphere characteristic of dairying, and the farmsteads that served as landmarks in what was once open, rolling country.

From an archaeological perspective, recent construction-related activities have destroyed the integrity of the homelot. Architecturally, however, the principal dwelling--and the principal dwelling alone--is potentially historically significant insofar as it represents an unusual architectural style in the area and it is one of a rapidly diminishing architectural resource base.

Maryland Historical Trust State Historic Sites Inventory Form

MARYLAND INVENTORY OF
HISTORIC PROPERTIES

1. Name (indicate preferred name)

historic

and/or common Buckley House

2. Location

street & number

 not for publicationcity, town COLUMBIA vicinity of

congressional district

state MARYLANDcounty HOWARD

3. Classification

Category

district
 building(s)
 structure
 site
 object

Ownership

public
 private
 both

Public Acquisition

in process
 being considered
 not applicable

Status

occupied
 unoccupied
 work in progress

Accessible

yes: restricted
 yes: unrestricted
 no

Present Use

agriculture
 commercial
 educational
 entertainment
 government
 industrial
 military

museum
 park
 private residence
 religious
 scientific
 transportation
 other: ^{construction} staging area

4. Owner of Property (give names and mailing addresses of all owners)

name Howard Research and Development Corporationstreet & number 10275 Little Patuxent Parkway telephone no.: (410) 992-6033city, town Columbiastate and zip code MD21044-3456

5. Location of Legal Description

courthouse, registry of deeds, etc. Howard County Courthouseliber 477

street & number

folio 460city, town Ellicott Citystate MD

6. Representation in Existing Historical Surveys

title

date

 federal state county local

pository for survey records

city, town

state

7. Description

Survey No. HO-638

Condition		Check one	Check one	
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input checked="" type="checkbox"/> original site	
<input type="checkbox"/> good	<input type="checkbox"/> ruins	<input checked="" type="checkbox"/> altered	<input type="checkbox"/> moved	date of move _____
<input checked="" type="checkbox"/> fair	<input type="checkbox"/> unexposed			

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The principal dwelling is a 2½ story, single family, balloon frame building with a partial cellar. It consists of three principal bays with a projecting central bay, or square tower with dormer. The hipped roof has paired pediments on either end that appear to be part of the original structure. The entire roof is sheathed in galvanized metal. The upper half-story sports imbricated shake siding, while the remaining portions of all of the façades are covered in asbestos shingles. Plain board moldings highlight both the windows and the principal corners of the front (north) façade. Tongue-and-groove board has been used on all of the eaves and porch soffits.

A full-length Colonial-Revival porch with tapered columns and unadorned capitals was added to the front façade. It is in poor condition with one column failing completely, another beginning to fail, and the tongue-and-groove soffit in an advanced state of decay. The rear lean-to porch is in much better condition, being wholly enclosed and serving, in part, as a laundry and utility room. Single story, projecting bays have been added to the west and east façades, retaining the bilateral symmetry of the overall exterior and interior designs. Most of the windows have been replaced with metal frame storm windows. A brick chimney stack has been added to the east façade to service the oil burner in the partial cellar below. The original chimneys, however, survive and consist of symmetrically-placed interior stacks that vent at least two fireplaces on the first floor. They are devoid of decorative treatment. The overall condition of the exterior is fair, deterioration attributable to neglect over the past 25 to 30 years. Although the roof appears to be tight, the gutters have not been maintained and significant damage from stormwater is imminent. The windows also are in need of replacement.

Several partition walls have been installed, and several plaster walls have been replaced with dry wall; however, the interior first and second floors retain much of their original configuration. Two large public rooms flank the central hall with its plain, paneled stair. Original half-round moldings survive throughout most of the first and second floors, at least in those public areas to which we had access. The fireplace in the east room of the first floor retains its plain mantle with machine-carved central figure of a wreath and crossed torches. Most of the surviving doors are plain paneled. The interior, in general, is in very good condition.

8. Significance

Survey No. HO-638

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/ humanitarian
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> theater
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> transportation
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> other (specify)
		<input type="checkbox"/> invention		

Specific dates	Builder/Architect
check: Applicable Criteria: <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D and/or	
Applicable Exception: <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G	
Level of Significance: <input type="checkbox"/> national <input type="checkbox"/> state <input checked="" type="checkbox"/> local	

Prepare both a summary paragraph of significance and a general statement of history and support.

The Buckley farmstead consists of a principal dwelling that dates to the last quarter of the 19th century or the first quarter of the 20th century, and a collection of at least six outbuildings that date to the early to mid-20th century. The large barn, silo and milk parlor complex probably date to the second quarter of the 20th century, judging from the extensive use of concrete block in the construction. Overall, the Buckley farmstead represents a late 19th through 20th century dairy farmstead. Such farmsteads were common throughout the region into the middle of the 20th century. Rapid urbanization within the Washington-Baltimore metropolitan area, however, has largely destroyed the agricultural character of the region, and, particularly, the open-pasture atmosphere characteristic of dairying, and the farmsteads that served as landmarks in what was once open, rolling country.

From an archaeological perspective, recent construction-related activities have destroyed the integrity of the homelot. Architecturally, however, the principal dwelling—and the principal dwelling alone—is potentially historically significant insofar as it represents an unusual architectural style in the area and it is one of a rapidly diminishing architectural resource base.

9. Major Bibliographical References

Survey No. HO-638

10. Geographical Data

Acreage of nominated property 41 acre

Quadrangle name Savage

Quadrangle scale 1:24000

UTM References do NOT complete UTM references

A	<input type="text"/>	<input type="text"/>	<input type="text"/>
	Zone	Easting	Northing

B	<input type="text"/>	<input type="text"/>	<input type="text"/>
	Zone	Easting	Northing

C	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

D	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

E	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

F	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

G	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

H	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

Verbal boundary description and justification

List all states and counties for properties overlapping state or county boundaries

state	code	county	code

11. Form Prepared By

name/title James G. GIBB

organization Archaeological Consultant date 11 NOVEMBER 1993

street & number P.O. Box 378 telephone (410) 257-9377

city or town North Beach state MD 20714


The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust
Shaw House
21 State Circle
Annapolis, Maryland 21401
(301) 269-2438

MARYLAND HISTORICAL TRUST
DHCP/DHCD
100 COMMUNITY PLACE
CROWNSVILLE, MD 21032-2023
410-7100

Map 1: Project Area and Location Map



Map 2: Tax Record Map, L. 37, Howard County

HO-638 9

OPEN SPACE

LOT 1

SNOWDEN

LOT 3
LOTS G-1 THRU G-87
P. 549

OPEN SPACE
Δ8576, 9436-37983
LOTS E-1 TO E-122

Δ8158

LOT 7

OPEN SPACE

MONTGOMERY

LOT 8

HO. RES. & DEV. COMP.
47/480
44.50A.
P. 254

MAP 36-RR

HOWARD RESEARCH
DEVELOPMENT

OPEN SPACE
117

P. 653

P. 654

36

BLACK STAR

OPEN

R 438
R 560
P. 200
P. 235

P. 246

206

209

210

211

212

213

214

215

216

217

218

219

220

221

222

223

224

225

226

227

228

229

230

231

232

233

234

235

236

237

238

239

240

241

242

243

244

245

246

247

248

249

250

251

252

253

254

255

256

257

258

259

260

261

262

263

264

265

266

267

268

269

270

271

272

273

274

275

276

277

278

279

280

281

282

283

284

285

286

287

288

289

290

291

292

293

294

295

296

297

298

299

300

301

302

303

304

305

306

307

308

309

310

311

312

313

314

315

316

317

318

319

320

321

322

323

324

325

326

327

328

329

330

331

332

333

334

335

336

337

338

339

340

341

342

343

344

345

346

347

348

349

350

351

352

353

354

355

356

357

358

359

360

361

362

363

364

365

366

367

368

369

370

371

372

373

374

375

376

377

378

379

380

381

382

383

384

385

386

387

388

389

390

391

392

393

394

395

396

397

398

399

400

401

402

403

404

405

406

407

408

409

410

411

412

413

414

415

416

417

418

419

420

421

422

423

424

425

426

427

428

429

430

431

432

433

434

435

436

437

438

439

440

441

442

443

444

445

446

447

448

449

450

451

452

453

454

455

456

457

458

459

460

461

462

463

464

465

466

467

468

469

470

471

472

473

474

475

476

477

478

479

480

481

482

483

484

485

486

487

488

489

490

491


492

493

494

HO-638

Map 4: USGS Map, 1974






Figure 3. Topographic map and project area location.

BUCKLEY FARM COMPLEX PHOTOGRAPHS

1. West Facade
2. Detail of original German siding and corner boards, North Facade
3. Detail of Front Porch, looking North
4. South Facade
5. Detail of eave, South Facade
6. North Facade
7. East and North Facades
8. Detail of window trim and shutter, East Facade
9. Detail of newel, Stair Hall, Ground Floor
10. Detail of main stair, Ground Floor
11. Detail of dropped newel at Landing, Ground Floor ceiling
12. Fireplace, Parlor A, Ground Floor
13. Detail of fireplace, Parlor A, Ground Floor
14. Fireplace, Parlor B, Ground Floor
15. Detail of arch at bay, Parlor A, Ground Floor
16. Landing with modern plasterboard wall, Second Floor
17. Landing newels, main stair, Second Floor
18. Newel, back stair, Second Floor
19. Typical interior door
20. Dairy Barn, South Facade
21. Garage, South Facade
22. Garage, North Facade



LC638

EXHIBIT 1011 2002001

CONCRETE VIBRATION EQUIPMENT

THEODORE W. WILSON, JR., CHAIRMAN

DATE 10/20/01

WILSON'S REPORT ON THE TESTS OF THE VIBRATION EQUIPMENT

FOR THE PROJECT

AT THE UNIVERSITY

TECHNICAL UNIVERSITY OF CALIFORNIA

1992



HO 603

EXHIBIT 1 - NORTH FACADE

SECTION 1 - CORNER BOARD, NORTH FACADE

SECTION 2 - SIDING, NORTH FACADE

SECTION 3 - SIDING, NORTH FACADE

SECTION 4 - SIDING, NORTH FACADE

SECTION 5 - SIDING, NORTH FACADE

SECTION 6 - SIDING, NORTH FACADE

SECTION 7 - SIDING, NORTH FACADE

SECTION 8 - SIDING, NORTH FACADE

2. Detail of original German siding and corner boards, North Facade



HO 638

BOCKLEY FARM COMPLEX

COLUMBIA VICINITY, HOWARD COUNTY,
MARYLAND

PHOTOGRAPHER: DAVID H. GLEASON

DATE: OCT 1994

NEGATIVE LOCATION:

DAVID H. GLEASON ASSOC,
520 N. FULTON ST
BALTIMORE, MD

PRINCIPLE DWELLING, DETAIL
OF FRONT PORCH, LOOKING
NORTH

3/22



10653

BUCKLEY FARM COUNTRY

COLUMBIA COUNTY, HOWARD COUNTY, MARYLAND

THOMAS BUCKLEY FARM, W. SPENCER

1871, 1872, 1873

MARYLAND COLLEGE, FARM BUCKLEY, W. SPENCER
421 N. FARM ST.
FARMER, MD

Spencer, Maryland, South Facade

1871



2020

PROJECT NAME: [unclear]

CLIENT: [unclear]

LOCATION: [unclear]

DATE: [unclear]

DESCRIPTION: [unclear]

[unclear]

[unclear]

SCOPE OF WORK: [unclear]

[unclear]

[unclear]



HC 675

BUCKLEY FAIRY COTTAGE

COLUMBIA VICINITY, HOWARD CO., MD

PHOTOGRAPHER: DAVID H. GLEASON

DATE: OCT. 1994

NEGATIVE LOCATION:

DAVID H. GLEASON ASSOC.

520 N. EUTAW ST.

BALTIMORE, MD

PRINCIPLE DWELLING, NORTH FACADE

6/22



#0638

BUCKLE / FARM COMPLEX

COLUMBIA VICINITY, HOWARD CO., MD

PHOTOGRAPHER: DAVID E. GLEASON

DATE: OCT 1994

NEGATIVE LOCATION:

DAVID H. GLEASON ASSOC.

520 N. EUTAW ST.

BALTIMORE MD

DRILLING TOWER S, EAST AND NORTH
FACADES

7/22

7. East and North Facades



10-103

BRADLEY BRIDGE COUNTRY

CONDOMINIUM VICINITY, HOWARD COUNTY,
MARYLAND

PHOTOGRAPHER: DAVID H. GIBSON

DATE: OCT 1994

NEGATIVE INFORMATION

DAVID H. GIBSON ASSOC.
10000 WOODBURN ST.
BETHESDA, MD

EXHIBIT 25E100, DETAIL OF
WINDOW TRIM AND SHUTTER,
EAST FACADE

9/22





10/22

ROCKWELL FARM COMPANY

COLUMBUS UNIVERSITY, HOWARD CO.,
MICHIGAN

PHOTOGRAPHY, LATE H. J. JENSEN

DATE: OCT 1974

LOCATION: LOCATION

1000 S. JENSEN ST.

1000 S. JENSEN ST.

1000 S. JENSEN ST.

1000 S. JENSEN ST., DETAIL OF

1000 S. JENSEN ST., GROUND FLOOR

10/22



H.C. 658

BOOKER T. FARM, CHARLOTTE

CONTRACTOR: WALTER H. FERRIS, COUNTY, WATKINS

PROPERTY OWNER: CAROL H. GIBSON

DATE: OCT. 1951

VIEWING LOCATION:

CAMP 4, GIBSON ASSOC.

520 W. FIFTH ST.

CHARLOTTE, N.C.

DESCRIPTION: TO SHOW DETAIL OF DROPPED NEWEL

AT LANDING 2, GROUND FLOOR CEILING

H.C. 658

11. Detail of dropped newel at Landing, Ground Floor ceiling



HCG 38

BUCKLEY PARK, GROUND
FLOOR, COLUMBIA UICM (1), HOWARD CO,
MERCURY, MD

INTERIOR WALLS: PLASTER, H₂O, SPANISH
DATE: 9/20/1974

NEGATIVE LOCATION

217-2 B, GLEASON APT. 2,
520 N. EIGHTH ST.,
BETHESDA, MD

PRIMITIVE DRAWING, SITE PLAN
PARLOR A, GROUND FLOOR

12/22



PHOTOGRAPHY
PROPERTY OF THE
FEDERAL BUREAU OF INVESTIGATION
COMMERCIAL VICINITY, HOWARD
CO, MARYLAND

PHOTOGRAPHER:

DAVID H. GIBSON

DATE: OCT 1964

NEGATIVE LOCATION:

DAVID H. GIBSON - 520

520 N. AVIATION ST

BALTIMORE MD

DEVELOPED BY THE FBI, DETAIL
OF FIREPLACE, PARLOR A

17/22



HOGS

BOCKLEY FARM, COVINGTON

COLUMBIA COUNTY, HOWARD COUNTY, MARYLAND

PARCEL ADJACENT TO FARM, N. OF ROAD

DATE: OCT 1954

GENERAL DESCRIPTION: DIRT, N. OF ROAD, ADJ. TO

ROAD, N. OF ROAD, N. OF

FACTORY, N. OF

INDICATE THE LOCATION OF THE FLOCK

UPON THE FLOCK

(X) 1 =



110 G²

BLOCKING FRAME CONCRETE

COLUMBIA UNIVERSITY, HASTINGS CO.

MARSHALL

PHOTOGRAPHY UNIT, UNIVERSITY OF MICHIGAN

DATE: OCT 1974

NEGATIVE LOCATION:

TABLE 4, REASON AS OF

200 N. HOLLAND ST

FACILITY, MI

TAKEN FROM DRAWING, DETAIL OF

ARCH AT BAY, PARLOR A,

GROUND FLOOR

15/12



H0638

BACKLIP FARM, OMAHA

COLUMBIA DISTRICT, HAWAII CO.,
HAWAII

TELEPHONED BY TACIS H. GUNSON

DATE: OCT 1994

NEGATIVE LOCATION

TACIS H. GUNSON ASSOC.,
500 N. BROAD ST.,
BARTHOLOMEW, HI.

PRINCIPLE DIRECTOR, LANDS WITH
MODERN PLASTERBOARD WALL
SECOND FLOOR

16/2/94



HO 6-55

BOOKING TABLE COURTESY

COLUMBIA UNIVERSITY HERBARIUM

NATIONAL

PHOTOGRAPHER: TABLE H. GIBSON

DATE: OCT 19-71

ALTERNATE LOCATION

TABLE H. GIBSON ARCHIVE

500 N. JIMMIE ST

FACULTY, UIC

TRICHOPUS DACTYLUS, LAMINAR

ALTERNATE LOCATION

SECOND FLOOR

PAGE 2



110 013

BUCKET / PAINT / BRUSH

CHRYSLER LIGHTING FIXTURE CO.,
WASHINGTON

BRIDGE PLANT, DORIS H. STATION

LATE OCT 1970

REGARDING 1000000

DANIEL H. GLEASON 2500


5000 5000

TEMPERATURE, MS

TEMPERATURE 2500, 2500,

2500 STAIR, SECOND FLOOR

12/1/70



#2 67

REC'D BY: [unclear]

COLUMBIA UNIVERSITY, ACADEMIC CC.,
BAPTIST

INTERVIEWER: DAVID H. GIBSON

DATE: OCT. 1931

INTERVIEW LOCATION:

DAVID H. GIBSON, ASSESSOR
500 N. ELSTON ST
CHICAGO, ILL.

INTERVIEW SUBJECT: TYPICAL
INTERIOR DOOR (TABLE A,
GROUND FLOOR)

19/32



PROF. DAVID H. GLEASON
UNIVERSITY OF CALIFORNIA, HOWARD CO, MARYLAND

PHOTOGRAPHER: DAVID H. GLEASON

DATE: OCT 1954

NEGATIVE LOCATION: DAVID H. GLEASON ARCHIVE
500 N. WASHINGTON ST.
BALTIMORE MD

DAIRY BARN, SOUTH FACADE

20/20



21.22

BRITISH FARM COUNTRY

COLUMBIA LIGNUM, HEWARD CO., MD.

PHOTOGRAPHER: DAVID H. GLEASON

DATE: OCT 1994

NEGATIVE LOCATION: DAVID H. GLEASON ASSOC
520 AL. EDWARDS ST
BALTIMORE, MD

21.22, SOUTH FACADE

71/22

21. Garage, South Facade



HOLES

BLOCKLEY FARM COMPLEX

COLUMBIA VICINITY, HEWARD CC, MD

PHOTOGRAPHER: DAVID H. GIBSON

DATE: OCT 1994

NEGATIVE LOCATION: COLLEGE PARK
570 N. WASHINGTON ST
BALTIMORE MD

GARAGE, NORTH FACADE

22/22

22. Garage, North Facade



HO-638

Buckley House
Columbia, Md.

Jibb G. Gibb
11 Nov. 93