

1. STATE <u>Maryland</u> COUNTY <u>Kent</u> TOWN <u>Crumpton</u> VICINITY STREET NO. <u>Rt 290, .8 mile south of Rt 291</u> <u>(east to house - 1/2 mile)</u> ORIGINAL OWNER ORIGINAL USE <u>dwelling</u> PRESENT OWNER <u>Frank Peacock</u> PRESENT USE <u>tenant house</u> WALL CONSTRUCTION <u>brick</u> NO. OF STORIES <u>1 1/2</u>	HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY <u>K-200</u>
	2. NAME <u>Peacock Tenant House</u> DATE OR PERIOD <u>18th Century</u> STYLE <u>Colonial</u> ARCHITECT BUILDER 3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION OPEN TO PUBLIC NO

The old house on the Comegys Farm is a one and one-half story brick dwelling which is nearly in ruins but nonetheless still occupied. It has a very tall steeply-pitched "A" roof with three dormers on each side. There is a chimney within each gable, though the one on the west gable, as well as part of the gable has collapsed.

Apparently it was built in two stages, although it is five bays long with a central door. The east portion including the door was probably constructed first, then the two bays west of the door were added, apparently not long afterward. Its south facade is laid in Flemish bond in a crude fashion and there is a cellar entrance east of the door. On the east end of the house is a one story frame kitchen, also in bad repair. There are other sheds in the yard but not as old as the house.

It looks over a field to a bay in the Chester River formed (over)

5. PHYSICAL CONDITION OF STRUCTURE Endangered yes Interior Exterior poor

6. LOCATION MAP (Plan Optional)	7. PHOTOGRAPH
---------------------------------	---------------

8. PUBLISHED SOURCES (Author, Title, Pages) INTERVIEWS, RECORDS, PHOTOS, ETC.	9. NAME, ADDRESS AND TITLE OF RECORDER <u>Michael Bourne</u> DATE OF RECORD <u>May, 1970</u>
----------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------------------


SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE

K-200

where the Red Lion branch 'makes' into the Chester River.


(fantastic possibilities!)

K-200



(CHURCH HILL) CRUMPTON 0.7 MI. CENTREVILLE 20 MI.

SCALE 1:24 000



CONTOUR INTERVAL 20 FEET
 DATUM IS MEAN SEA LEVEL
 WAVES AND SOUNDINGS IN FEET—DATUM IS MEAN LOW WATER
 DASHED LINE REPRESENTS THE APPROXIMATE LINE OF MEAN HIGH WATER
 THE MEAN RANGE OF TIDE IS 2 FEET

GALENA
 QUAD

ROAD CLASS
 Heavy-duty ———— 4 LANE 6
 Medium-duty ———— 4 LANE 6
 U. S. Route



QUADRANGLE LOCATION

FEB 1963



Presbury
Corneygas Farm
Near Crumpton
Kent County
Michael Bourne
1963

1831

K-200-B

FEB 1963



15

Coppeyges Farm
Near Crompton
Kent County
Michael Bourne
1963

1831

K-200-C