

K-584

1700-1799?

Tayman-Chance House

Near Georgetown

Private

This small, two-part frame house now on the east side of Route 213 between Galena and Georgetown was moved about 1950 from the old Dr. Tayman farm to the southeast, near Mill Lane. The large, frame 2 or 2-1/2 storey old Tayman farmhouse was dismantled to remove at least some of the parts for re-use in a new farmhouse. This two-part wing was detached, sold, and moved to the nearby location. The now southern gable-roofed section, with front shed dormer, appears to be the older. Though the interior was not inspected, the very low (but resurfaced) first-storey ceiling appears to indicate that this section is a true 1-1/2 storey dwelling, one room with loft that once stood independently before becoming part of the larger farmhouse. Though the building has been extensively reworked, wrought nails appear to be part of original construction, and the wall studs may be riven. The southern section of the Tayman-Chance house appears to be a rarely surviving example of what in early Kent County must have been a very common form of dwelling, one room with loft reached by either corner stair or ladder stair. Some have been incorporated into larger dwellings and cannot now be easily identified, but far more probably have deteriorated and been abandoned or simply have been replaced by larger, more sophisticated dwellings.

Maryland Historical Trust State Historic Sites Inventory Form

1. Name (indicate preferred name)

historic Dr. Tayman House

and/or common Chance House (preferred)

2. Location

street & number East side Rt. 213, .7 mile south of Sassafras River bridge not for publication

city, town Georgetown vicinity of congressional district First

state Maryland county Kent

3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input checked="" type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input type="checkbox"/> private residence
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input checked="" type="checkbox"/> not applicable	<input checked="" type="checkbox"/> no	<input type="checkbox"/> military	<input checked="" type="checkbox"/> other: storage

4. Owner of Property (give names and mailing addresses of all owners)

name John Chance

street & number _____ telephone no.: _____

city, town Henderson state and zip code Maryland 21640

5. Location of Legal Description

courthouse, registry of deeds, etc. Court House liber WHG 25

street & number Cross Street folio 453

city, town Chestertown state Maryland

6. Representation in Existing Historical Surveys NONE

title _____

_____ federal state county local

depository for survey records _____

city, town _____ state _____

7. Description

Survey No. K-584

Condition		Check one	Check one	
<input type="checkbox"/> excellent	<input checked="" type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input type="checkbox"/> original site	
<input type="checkbox"/> good	<input type="checkbox"/> ruins	<input checked="" type="checkbox"/> altered	<input checked="" type="checkbox"/> moved	date of move
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed			<u>Circa 1950</u>

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

This small, two-part frame house now on the east side of Route 213 between Galena and Georgetown was moved about 1950 from the old Dr. Tayman farm to the southeast, near Mill Lane. The large, frame 2 or 2 1/2 story old Tayman farmhouse was being dismantled to remove at least some of the parts for re-use in a new farmhouse. This wing was detached, sold, and moved to the nearby location. The now southern gable-roofed section, with front shed dormer, appears to be the older. Though the interior was not inspected, the very low (but resurfaced) first-story ceiling appears to indicate that this section is a true 1-1/2 story dwelling, one room with loft that once stood independently before becoming part of the larger farmhouse. Though the building has been extensively reworked, wrought nails appear to be part of original construction, and the wall studs may be riven.

(Continued)

8. Significance

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> ? 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates **Builder/Architect**

check: Applicable Criteria: A B C D
 and/or
 Applicable Exception: A B C D E F G
 Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.

The southern section of the Tayman-Chance house appears to be a rarely surviving example of what in early Kent County must have been a very common form of dwelling, one room with loft reached by either corner stair or ladder stair. Some have been incorporated into larger dwellings and cannot now be easily indentified, but far more probably have deteriorated and been abandoned or simply have been replaced by larger, more sophisticated dwellings.

The southern section is about 15 feet wide and 16 feet . The later, north wing, with its front (west) wall flush with the earlier section's, is about 16 feet wide by 14 feet deep. Both sections are two bays wide. The added section also appears to be true 1-1/2 storey in height, but its roof is considerably lower and the pitch somewhat shallower than that of the earlier section.

Both sections are now covered with asbestos shingles over horizontal, lapped weatherboard, which is exposed in some places; some may be replacement material.

The chimney, appearing to have been built after the move, is located within the wing at the common wall with the main section. Given the location of the front and rear openings, it is most likely that there was once a chimney within the south end of the main section.


The door and window in both front and rear walls, opposite each other, are not placed with reference to a center point but set somewhat to the north. The materials do not seem to be original. The double-hung sash have 6-over-6 lights. There are no windows on the south end.

There is a single shed-roofed front dormer in the main section, slightly to the north of center. The sash are double-hung with 6-over-6 lights. The aluminum storm window-screen cover face details. The cheeks are of lapped weatherboard applied diagonally, following the pitch of the main roof.

There are now replacement flush verge boards, applied over the asbestos shingles. At front and rear the roof overhangs only slightly, and structural members do not appear to do so, only the roofing, which is wood shingles beneath asphalt shingles. There may be some very small blocking material, however.

In its later years, attached to the larger farmhouse, this section seems to have been used to house farm workers, at least on the upper storey.

55' 1:110 000 FEET



GALENA QUADRANGLE

560 FEE

SASSAFRAS 4.8 MI

MASSEY 3 MI



K-584

Chance House

Rt 213, near Galena

M. Q. Fallaw - 4/19/85

View to northeast

K584-20



K-584

Chance House

Rt. 213 near Galena

M. Q. Fallaw - 4/19/85

View to northwest

K584-24