

MARYLAND HISTORICAL TRUST ABRIDGED INVENTORY FORM
INTERCOUNTY CONNECTOR PROJECT

Property Name: Knox Property
Survey No.: PACS D2.34

Resource Summary:

Property Address 15516 Santini Road, Burtonsville, Montgomery County, Maryland 20866

M.15-112

Historic/Current Function Dwelling/Dwelling

Year Built circa 1920

Property is not individually eligible for National Register because:

It is less than 50 years old and does not meet N.R.

Exception G

It is an undistinguished example of a common building type or architectural style

Its integrity is compromised by alterations or deterioration

Its historic setting has been compromised by development

Other (explain): _____



Description:

The Knox Property is a 2½-story, Four-square house on the west side of Santini Road, Montgomery County. Constructed circa 1920, the house has an asphalt shingle, hipped-roof, is clad in asbestos shingles, has a concrete foundation, and has two interior brick chimneys. It has a concrete foundation and double-hung wood windows. Several windows on the north and south elevations have been replaced with modern bay windows. There is a large 2-story addition on the west, or rear elevation, which obscures the entire facade. A 1-story canted bay window has been added to the south elevation, as well as a modern deck, which wraps around the house to the west facade.

A brick, three-car garage is located directly northwest of the house. The garage has a side gable roof covered with asphalt shingles, and the garage doors are wood.

The property is located on the west side of Santini Road, with residences to the north and south, and trees to the west. The site is level with several large trees. The property's setting is suburban.

MHT CONCURRENCE:			
Eligibility	<input type="checkbox"/> Recommended	<input checked="" type="checkbox"/> Not recommended	
Criteria	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	Considerations	<input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> None
Comments: _____			


 Reviewer, Office of Preservation Services		 Reviewer, NR Program	
 Date		 Date	

Preparer:
P.A.C. Spero & Company
October 1996

(Handwritten mark)

Resource Sketch Map

M: 15-112





~~PLAC, P. 151~~ M:15-112

2 KNOX TREATMENT

3 MONTGOMERY COUNTY MD

4 PAC Spero & Co.

5 11/95

6 PAC Spero & Co

40 W. Chesapeake Ave #412

BALTO MD 21204

7 5516 SANTINI ROAD

100TH E, EAST FACADES

8 1003



11-02-31 M: 15-112

KLUX PROPERTY
MONTGOMERY CO, MD

4740 Sp...
5-195

60X Sp... & Co.
40 W. Chesapeake Ave # 412

BALTO, MD 21204
715516 - SANTINI ROAD
SOUTH & EAST FACADES

8 - of 2



~~PAGE~~ ~~DATE~~

M:15-112

KNOX PROPERTY

MONTGOMERY CO., MD

6 PAC Square & Co

5/1/95

6 PAC Square & Co

40 W. Chesapeake Ave

11/1/2

BALTIMORE, MD 21201

710000 - INDUSTRIAL KNOX

GARAGE VIEW - WEST

83 of 13