

MARYLAND HISTORICAL TRUST WORKSHEET 1603085404

NOMINATION FORM
for the
NATIONAL REGISTER OF HISTORIC PLACES, NATIONAL PARKS SERVICE

SEE INSTRUCTIONS

1. NAME			
COMMON:			
AND/OR HISTORIC: Isaac Young House			
2. LOCATION			
STREET AND NUMBER: Route 107			
CITY OR TOWN: Martinsburg			
STATE: Maryland		COUNTY: Montgomery	
3. CLASSIFICATION			
CATEGORY (Check One) <input type="checkbox"/> District <input type="checkbox"/> Site <input type="checkbox"/> Object	<input checked="" type="checkbox"/> Building <input type="checkbox"/> Structure <input type="checkbox"/> Object	OWNERSHIP <input type="checkbox"/> Public <input checked="" type="checkbox"/> Private <input type="checkbox"/> Both	STATUS <input checked="" type="checkbox"/> Occupied <input type="checkbox"/> Unoccupied <input type="checkbox"/> Preservation work in progress
ACCESSIBLE TO THE PUBLIC			
Yes: <input type="checkbox"/> Restricted <input type="checkbox"/> Unrestricted <input checked="" type="checkbox"/> No			
PRESENT USE (Check One or More as Appropriate)			
<input type="checkbox"/> Agricultural <input type="checkbox"/> Commercial <input type="checkbox"/> Educational <input type="checkbox"/> Entertainment	<input type="checkbox"/> Government <input type="checkbox"/> Industrial <input type="checkbox"/> Military <input type="checkbox"/> Museum	<input type="checkbox"/> Park <input checked="" type="checkbox"/> Private Residence <input type="checkbox"/> Religious <input type="checkbox"/> Scientific	<input type="checkbox"/> Transportation <input type="checkbox"/> Other (Specify) _____ _____
4. OWNER OF PROPERTY			
OWNER'S NAME: Mrs. Eleanor Matthews			
STREET AND NUMBER: Martinsburg Road			
CITY OR TOWN: Dickerson		STATE: Maryland	
5. LOCATION OF LEGAL DESCRIPTION			
COURTHOUSE, REGISTRY OF DEEDS, ETC.: Montgomery County Court House			
STREET AND NUMBER:			
CITY OR TOWN: Rockville		STATE: Maryland	
Title Reference of Current Deed (Book & Pg. #):			
6. REPRESENTATION IN EXISTING SURVEYS			
TITLE OF SURVEY: None			
DATE OF SURVEY: <input type="checkbox"/> Federal <input type="checkbox"/> State <input type="checkbox"/> County <input type="checkbox"/> Local			
DEPOSITORY FOR SURVEY RECORDS:			
STREET AND NUMBER:			
CITY OR TOWN:		STATE:	

M:16-13

7. DESCRIPTION				
CONDITION	(Check One) <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input checked="" type="checkbox"/> Fair <input type="checkbox"/> Deteriorated <input type="checkbox"/> Ruins <input type="checkbox"/> Unexposed			
	<table border="0"> <tr> <td>(Check One) <input checked="" type="checkbox"/> Altered</td> <td><input type="checkbox"/> Unaltered</td> <td>(Check One) <input type="checkbox"/> Moved</td> <td><input checked="" type="checkbox"/> Original Site</td> </tr> </table>	(Check One) <input checked="" type="checkbox"/> Altered	<input type="checkbox"/> Unaltered	(Check One) <input type="checkbox"/> Moved
(Check One) <input checked="" type="checkbox"/> Altered	<input type="checkbox"/> Unaltered	(Check One) <input type="checkbox"/> Moved	<input checked="" type="checkbox"/> Original Site	
DESCRIBE THE PRESENT AND ORIGINAL (if known) PHYSICAL APPEARANCE				
<p>The house is a 2 1/2 story frame house with external stone chimneys. The main (south) facade has three bays with entrance through the east bay. The cornice is boxed and returned into the gable ends. The chimneys are positioned off-center, the one on the east end being north of the ridge and the one on the west end being south of the ridge. On the interior, a lateral partition wall divides the house into front and rear rooms, each with a fireplace but on opposite end walls. The interior walls are nailed to the cellar girt and a summer beam.</p> <p>The staircase rises against the east end wall in a straight run. On the 2nd floor there is a room opening at the top of the stairs and two rooms to the west of the hall. One room has a thimble for a stovepipe into the chimney.</p> <p>The attic is ceiled at the collar beams. The rafters are not joined, but a number of non-supporting, cut-off members suggests extensive changes in the roof.</p> <p>The house sits on a stone foundation. An exposed sill is a flattened log, as are some of the first floor joists. A girt runs laterally across the house and is supported by the foundation walls and three posts.</p> <p>The house has brick infilling between the framing members. Angle braces are exposed where the plaster has fallen off on the first floor. None of the framing is mortised or pegged, however; all joining is by notching/into members</p>				

SEE INSTRUCTIONS

B. SIGNIFICANCE

PERIOD (Check One or More as Appropriate)

- Pre-Columbian 16th Century 18th Century 20th Century
- 15th Century 17th Century 19th Century

SPECIFIC DATE(S) (If Applicable and Known)

AREAS OF SIGNIFICANCE (Check One or More as Appropriate)

- | | | | |
|--|---|---|--|
| <input type="checkbox"/> Aboriginal
<input type="checkbox"/> Prehistoric
<input type="checkbox"/> Historic
<input type="checkbox"/> Agriculture
<input type="checkbox"/> Architecture
<input type="checkbox"/> Art
<input type="checkbox"/> Commerce
<input type="checkbox"/> Communications
<input type="checkbox"/> Conservation | <input type="checkbox"/> Education
<input type="checkbox"/> Engineering
<input type="checkbox"/> Industry
<input type="checkbox"/> Invention
<input type="checkbox"/> Landscape
<input type="checkbox"/> Literature
<input type="checkbox"/> Military
<input type="checkbox"/> Music | <input type="checkbox"/> Political
<input type="checkbox"/> Religion/Phi-
losophy
<input type="checkbox"/> Science
<input type="checkbox"/> Sculpture
<input type="checkbox"/> Social/Human-
itarian
<input type="checkbox"/> Theater
<input type="checkbox"/> Transportation | <input type="checkbox"/> Urban Planning
<input type="checkbox"/> Other (Specify)
<hr/> <hr/> <hr/> <hr/> <hr/> <hr/> |
|--|---|---|--|

STATEMENT OF SIGNIFICANCE

SEE INSTRUCTIONS

each other and nailing them together. There is an L wing to the rear, sitting on a separate foundation. Behind the house is a bankbarn.

9. MAJOR BIBLIOGRAPHICAL REFERENCES

Empty space for major bibliographical references.

10. GEOGRAPHICAL DATA

LATITUDE AND LONGITUDE COORDINATES DEFINING A RECTANGLE LOCATING THE PROPERTY			O R	LATITUDE AND LONGITUDE COORDINATES DEFINING THE CENTER POINT OF A PROPERTY OF LESS THAN TEN ACRES		
CORNER	LATITUDE	LONGITUDE		LATITUDE	LONGITUDE	
	Degrees Minutes Seconds	Degrees Minutes Seconds		Degrees Minutes Seconds	Degrees Minutes Seconds	
NW	° ' "	° ' "		° ' "	° ' "	
NE	° ' "	° ' "		° ' "	° ' "	
SE	° ' "	° ' "		° ' "	° ' "	
SW	° ' "	° ' "		° ' "	° ' "	

APPROXIMATE ACREAGE OF NOMINATED PROPERTY:

Acreeage Justification:

Empty space for acreage justification.

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE:		COUNTY:	

11. FORM PREPARED BY

NAME AND TITLE: Christopher Owens, Park Historian

ORGANIZATION: M-NCPPC DATE: 31 May 1973

STREET AND NUMBER: 8787 Georgia Avenue

CITY OR TOWN: Silver Spring STATE: Maryland

12. State Liaison Officer Review: (Office Use Only)

Significance of this property is:

National State Local

Signature _____

SEE INSTRUCTIONS



NAME ISAAC YOUNG HSE.

M: 16-13

LOCATION Rt. 107 & WAESCHE Rd, POOLESVILLE, Md

FACADE S. (FRONT)

PHOTO TAKEN 5/31/73 M. DWYER

30



M. 16-13

NAME ISAAC YOUNG HSE.

LOCATION Rt. 107 & WAESCHE Rd., POODREVILLE, Md.

FACADE W.

PHOTO TAKEN 5/31/73 M. DWYER

27



NAME ISAAC YOUNG HSE.

11:16-13

LOCATION RT. 6074 WAESCHE Rd. POOLESVILLE, Md.

FACADE N.E. - CHIMNEY

PHOTO TAKEN 5/31/73 M. DWYER

2



NAME ISAAC YOUNG FARM - BARN

M: 16-13

LOCATION RT. 107 & WAESCHE RD POOLESVILLE AREA

FACADE S.E.

PHOTO TAKEN 5/31/73 M. DWYER