

GAITHERSBURG HISTORIC SITES SURVEY FIELD SHEET

ADDRESS 106 S. FREDERICK AVE. MHT # M-21-126  
County: Montgomery  
Gaithersburg LIBER 6, FOLIO 7

SURVEY # 006  
LOT -, BLOCK -

OWNER: Ballet 106  
ADDRESS: same  
CITY: same

PRESENT USE: dance studio  
ORIGINAL USE: residence  
BUILDER: unknown

STYLE: Late Victorian

DATE BUILT: c.1900

PHYS. COND: good

GENERAL DESCRIPTION

STRUCTURAL SYSTEM:

FOUNDATION: brick  
WALL STRUCTURE: Balloon  
WALL COVERING: stucco

ROOF CONSTRUCTION:

ROOF STRUCTURE: Wood Truss  
ROOF COVERING: pressed tin, fish-scale pattern  
ROOF STYLE: modified hip  
EAVES: boxed cornice, plain frieze with return  
CHIMNEYS: 1, offset rear interior

APPENDAGES:

ADDITIONS: rear  
ELLS: -  
PORCHES: front, wrap-around  
SUPPORTS: doric columns  
OUTBUILDINGS: -

STORIES: 2 1/2

BAYS: 3 x 2

APPROX DIMENSION: 23 x 27

WINDOWS:

TYPE: d.h.s., casement  
LIGHTS: 1/1, single/double casement, 6 lights  
BAY WINDOWS: 1 storey, right  
SIDE BY SIDES: front  
GABLE TYPES: single 1/1 d.h.s.

ENTRANCES:

LOCATION: 2nd bay  
DESCRIPTION: 2 light transom

THREAT: roads/development

SURROUNDINGS: commercial/buffer

M:21-126

DESCRIPTION: Gables-single 1/1 d.h.s. windows with plain surrounds. Decorative staggered butt shingles. Front-2nd storey two double 1/1 d.h.s. windows, plain surrounds. 1st storey, single 1/1 d.h.s. window, front door with two-light transom, five horizontal panels. 3rd bay has double 1/1 d.h.s. window. Porch supported by Doric columns, standing seam tin roof, original tongue/groove on floor now covered with plywood. Right-one-storey bay window with 1/1 d.h.s. windows in each bay, standing seam tin roof. Door in N.E. side of bay with one-light transom and glass in upper half. Double d.h.s 1/1/ windows in first bay, second storey; Back-1/1 d.h.s. windows in all three bays, middle one shorter. Addition has tin roof. Original part has German siding with single-light casement window on north side. Second part of addition is flush board with a single and double casement window, 6 lights in each, plain surrounds. Left-single 1/1 d.h.s. window in each bay. Strange addition between bays: high gable shingle roof to top of second storey, wood exterior paneling.

Recorded by:  
Lee Bowers  
October 26, 1982  
Historic Inventory Task Force