

GAITHERSBURG HISTORIC SITES SURVEY FIELD SHEET  
- - -

ADDRESS 209 E. DEER PARK DRIVE MHT # M-21-133  
County: Montgomery  
Gaithersburg

SURVEY # 016  
LOT -, BLOCK -

LIBER -, FOLIO -

OWNER: -  
ADDRESS: -  
CITY: -

PRESENT USE: residence  
ORIGINAL USE: residence  
BUILDER: unknown

STYLE: Late Victorian

DATE BUILT: c.1900

PHYS. COND: good

GENERAL DESCRIPTION

STRUCTURAL SYSTEM:

FOUNDATION: rubble stone, concrete covered  
WALL STRUCTURE: Balloon  
WALL COVERING: aluminum siding

ROOF CONSTRUCTION:

ROOF STRUCTURE: Wood Truss  
ROOF COVERING: asphalt shingle  
ROOF STYLE: hip  
EAVES: -  
CHIMNEYS: interior, corbel

STORIES: 2 1/2

BAYS: 3 X 2

APPROX DIMENSION: 31 X 35

WINDOWS:

TYPE: d.h.s.  
LIGHTS: 2/2  
BAY WINDOWS: none  
SIDE BY SIDES: dormer, west elevation  
GABLE TYPES: double 1/1 d.h.s., facade

ENTRANCES:

LOCATION: 2nd bay  
DESCRIPTION: oval window, decorative woodwork

THREAT: none

SURROUNDINGS: residential

M: 21-133

DESCRIPTION: Front-2/2 d.h.s. windows with plain surrounds. Dormer in gable has side-by-side 1/1 d.h.s. windows. Door in 2nd bay has large oval window and fancy decorative woodwork in corners. The house has no frieze or returns. Porch is supported by four plain posts, no railing and has hipped roof.

West elevation-1st bay has side-by-side d.h.s. window on first floor, single windows in both 2nd storey bays and second bay of 1st storey. Rear elevation-small shed-roofed addition, tin roof. Dormer in center of roof with 2/2 d.h.s. window. Offset gable to west. Chimney offset in gable roof with corbeled cap.

Windows in front and west side have original shutters(wood louvered). East side has replacement metal shutters. East elevation-3 bays deep with regularly spaced 2/2 d.h.s windows and small casement window between 2nd and 3rd bay.

Recorded by:

L. Bowers

October 31, 1982

Historic Inventory Task Force