

Easement

M: 30-12

ACHS SUMMARY FORM

- Name Corby Estate (now Stathmore Hall Arts Center - 1985)
2. Planning Area/Site Number 30/12 3. MNCPPC Atlas Reference
Map 21 Coordinate B-2
4. Address 10701 Rockville Pike
Rockville, MD
5. Classification Summary
- Category Building
Ownership Private
Public Acquisition Being considered
Status Unoccupied
Accessible No
Present use Educational
Previous Survey Recording National Reg. Federal State County Local
nomination

6. Date early 20th century 7. Original Owner Charles Israel Corby
8. Apparent Condition
- a. Excellent c. Original Site
- b. Unaltered

Description

"T"-shape floor plan, four room central hall main section, with large two story high room, once housing an organ. Brick exterior, flemish bond, with white marble quoins, water table, window frames and belt course. North facade: central one story portico, semi-circular, with porch above; 3 bays wide either side of portico, each side having its own hip roof structure. South facade: two story portico with ionic columns and pediment, in front of two story, three bay pavilion. One story projection in each internal corner of "T" balustrade at roof perimeter. Oak paneling and wainscoting interiors; large fountain in central hall.

10. Significance

Built by Charles Corby, who was instrumental in modernizing baking industry. Significant as a large 20th century mansion, well executed in a mix of styles, basically Georgian and Federal.

Charles Israel Corby and his brother William, contributed much to the nationwide bakery industry. The Corby brothers developed machines which could perform all the steps needed in the process of making bread, and were granted patents on many of them. They did much to establish modern baking methods.

Charles Corby's mansion is one of the finest examples of the early 20th century estates built along Rockville Pike.

11. Date researched 1977; Roy Gauzza
12. Compiler David F. Rinn 13. Date Compiled 8/23/78 14. Designation Approval
15. Acreage: 26 acres

Easement

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

FOR NPS USE ONLY	
RECEIVED	M - 30 - 12
DATE ENTERED	

**NATIONAL REGISTER OF HISTORIC PLACES
INVENTORY -- NOMINATION FORM**

SEE INSTRUCTIONS IN *HOW TO COMPLETE NATIONAL REGISTER FORMS*
TYPE ALL ENTRIES -- COMPLETE APPLICABLE SECTIONS

1 NAME

HISTORIC

AND/OR COMMON

Corby Estate

2 LOCATION

STREET & NUMBER

10701 Rockville Pike (at Strathmore Ave.)

NOT FOR PUBLICATION

CITY, TOWN

Rockville

VICINITY OF

Fourth

STATE

Maryland

CODE

024

COUNTY

Montgomery

CODE

031

3 CLASSIFICATION

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input type="checkbox"/> PUBLIC	<input type="checkbox"/> OCCUPIED	<input type="checkbox"/> AGRICULTURE
<input checked="" type="checkbox"/> BUILDING(S)	<input checked="" type="checkbox"/> PRIVATE	<input checked="" type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> MUSEUM
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> COMMERCIAL
<input type="checkbox"/> SITE	PUBLIC ACQUISITION	ACCESSIBLE	<input checked="" type="checkbox"/> EDUCATIONAL
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input type="checkbox"/> YES: RESTRICTED	<input type="checkbox"/> PARK
	<input checked="" type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> PRIVATE RESIDENCE
		<input checked="" type="checkbox"/> NO	<input type="checkbox"/> RELIGIOUS
			<input type="checkbox"/> GOVERNMENT
			<input type="checkbox"/> INDUSTRIAL
			<input type="checkbox"/> MILITARY
			<input type="checkbox"/> OTHER

4 OWNER OF PROPERTY

NAME

American Speech and Hearing Association

STREET & NUMBER

9030 Old Georgetown Road

CITY, TOWN

Bethesda,

VICINITY OF

STATE

Maryland 20014

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,
REGISTRY OF DEEDS, ETC.

Montgomery County Courthouse

STREET & NUMBER

CITY, TOWN

Rockville,

STATE

Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

FEDERAL STATE COUNTY LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7-DESCRIPTION

M:30-12

CONDITION		CHECK ONE	CHECK ONE
<input checked="" type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input checked="" type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Charles Corby Mansion is located on the east side of U.S. Route 355, Rockville Pike, five miles north of the Maryland-Washington, D.C. line in Montgomery County, Maryland. It is a Colonial Revival house dating from the early twentieth century designed in the shape of a T with the leg of the T extending south from the central entrance of the building terminating in the garden facade. The principal (northern) entrance is accented by a semicircular stone portico with fluted Doric columns and a flat roof featuring an ornate balustrade. This one story entrance is flanked on either side by identical two-story blocks of three bays, each having a hip roof covered with slate shingles. Large stone-capped chimney stacks project from within the end walls, and carved wooden balustrades surround the entire roofline of each block. The garden (southern) entrance is emphasized by a central two-story Ionic portico having a slate deck and a pediment with richly carved modillions. This two-story, three-bay central pavillion has a hip roof of slate shingles and two interior chimneys projecting above the west wall and one stone-capped chimney on the east. There is a molded cornice with dentils surrounding the entire house. The brick walls are laid in Flemish bond and have white marble quoins at each corner. White marble trim also appears in the water table, window frames and sills, and a wide belt course between the first and second stories. A wrought iron balcony projects from the end wall of the west block and from the second story in the south portico. In each angle of the T is a one-story unit with parapet walls on four sides surrounded by fluted Doric pilasters.

The first floor of the house follows a four-room central hall plan with modifications. From the central entrance in the north facade, three French doors with transomes open into an entrance hall with marble floors, stone walls, and an ornate skylight of leaded glass. The hall is dominated by a stone foundation with a fluted base and stone claw-like feet supporting each tier. On the west wall are three French doors with transomes, and on the south wall are three similar ones of mirrors. Centered on the east wall is a French door with a transome. The double doors and transomes of the west, north, and east walls have panes of translucent glass with an intricate pattern. Fluted stone pilasters flank each door and four lamps of brass with stone bases similar to lampadaires stand against the north and south walls.

To the west of the entrance hall, a large organ room with a parquet floor fills the entire west block. This room is two stories high and has oak paneling for half its height, then stone continuing to the ceiling. A low chair rail and a rose marble baseboard surround the room. Exposed oak beams extend across the ceiling. On the west end wall, a massive carved stone fireplace is centered with French doors on either side leading to a balcony. Extending across the end of the room over the mantel and doors is an oak chamber originally for the organ pipes.

See Continuation Sheet #1

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

FOR NPS USE ONLY
RECEIVED
DATE ENTERED

**NATIONAL REGISTER OF HISTORIC PLACES
INVENTORY -- NOMINATION FORM**

Corby Estate
Montgomery County,
Maryland

CONTINUATION SHEET ITEM NUMBER 7 PAGE 1

DESCRIPTION (continued)

Supporting this projecting organ chamber are fluted Doric columns of oak. On the south wall, a central double door leads to the west sunroom. Three windows are evenly spaced on the north wall with one being under the organ chamber. Between the two windows within the room is an oak recess where the organ was located. On the east wall above the three French doors is a Palladian window. Ornate chandeliers are suspended from the ceiling, and similar wall sconces are under the organ chamber on the north and south walls.

To the rear of the entrance hall is a paneled stair hall. Walls of the one bay wide by two bay deep stair hall have a cornice with dentil rows and a baseboard of marble. A low chair rail surrounds the room. Along the entire south wall are three French doors with transomes. On the east wall is a sliding door flanked by fluted pilasters, and in the northeast corner is an additional French door. All the doors have window panes of translucent glass. Along the west wall is a dog-leg stair with rectangular step ends. The balusters are wrought iron with sections of ornamental patterns and form a spiral around the newel. On the north wall at the stair landing is a Palladian window with fluted pilasters. In the stair hall are two chandeliers, and sconces are located on the west and east walls as well as that of stair landing.

West of the stair hall is a drawing room and office which together formed the original drawing room. Both rooms have paneling with a low chair rail, marble baseboards and a simple cornice. Addition of the wall dividing the original drawing room resulted in a change in the location of a door to the west sun room. Now there are two French doors and an additional single door near the office. Centrally placed in the west wall of the office is a door flanked by fluted pilasters. The west wall of the original drawing room had three French doors with the center one opposite the door to the stair hall. These were flanked by single doors on either side. Along the south wall of the office is a window between arched bookcases. A small elevator, opening into the drawing room has been added by enclosing a corner of the west sun room. As with the drawing room, the original sun room has been divided and now has a wood floor over its slate deck.

Opposite the drawing room on the east side of the stair hall is the library completely paneled in oak. The room contains intricately carved patterns in oak in the fireplace mantel, the pilasters on the front of the fireplace, and the overmantel, which features a central block of a carved coat of arms. The same pattern is repeated in the pilasters flanking the west and north wall doorways. There is an oak cornice with egg and dart molding. On the west wall, bookshelves occupy the entire

See Continuation Sheet #2

M:30-12

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

FOR NPS USE ONLY

RECEIVED

DATE ENTERED

**NATIONAL REGISTER OF HISTORIC PLACES
INVENTORY -- NOMINATION FORM**

Corby Estate
Montgomery County,

CONTINUATION SHEET Maryland

ITEM NUMBER 7

PAGE 2

DESCRIPTION (continued)

area on either side of the centrally located doorway. The fireplace on the east wall, with carved marble facing, is flanked by double paneled doors. On the north wall a short hall in the center terminates in a double sliding doorway. The south wall contains a large window identical to the window on the south wall of the office. Sconces are located on the south and north walls.

East of the library is another sun room. Part of it has been altered for a bathroom, closet area and bookshelves. The ceiling has been lowered and a wood floor placed over the slate deck. Originally this east sun room was enclosed entirely by glass as was the western one.

North of the library and east of the entrance hall is a paneled dining room. A handsome cornice with minute detail surrounds the room. On the east wall, a fireplace with carved marble mantle and a dog-eared overmantel has fluted pilasters on the front. To the south side of the fireplace is a French door with transome and side lights opening to the small room which resulted from the alterations in the east sunroom. On the north wall is a large window behind a screen of Ionic columns. Sconces are located on the front of the fireplace and on the south and north walls. To the east of the dining room is a butler's pantry with staircase on the east wall, having a dog-leg staircase with winders. At the foot of the stairway, a doorway leads to a room of modern alterations. Originally the kitchen, this room reflects little evidence of its past use. East of this is a modern kitchen (originally the summer kitchen) with a small enclosed porch.

On the second floor above the stair hall and library is the master bedroom with an adjoining sitting room. The door to the master bedroom on the north wall has side lights and transom. On the south wall is a large glass double door leading to a balcony in the south portico. Its paneled sitting room has been divided into two rooms and a hall. There is an elaborate cornice with diamond and rectangular designs and a low chair rail of rosette carving surround the original four walls of the sitting room. The north wall of the hall (north wall of original sitting room) has two elaborate pedimented doorways, one of which leads to a marbled bathroom-dressing room. The east wall of the original sitting room has a fireplace mantel with carved marble figurines and Wedgewood panels. Windows in these rooms have a cornice overhead similar to that at the ceiling. In another bedroom over the drawing room there is a bay window. There and in two other bedrooms, different styles of sconces are located on the walls.

See Continuation Sheet #3

M:30-12

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

FOR NPS USE ONLY
RECEIVED
DATE ENTERED

**NATIONAL REGISTER OF HISTORIC PLACES
INVENTORY -- NOMINATION FORM**

Corby Estate
Montgomery County,

CONTINUATION SHEET Maryland ITEM NUMBER 7 PAGE 3

DESCRIPTION (continued)

Currently the Metro Transit System's excavation for the subway system passes by the west side of the mansion and extends the entire length of the property. The excavated area is twelve feet from the nearest wall of the mansion leaving a ninety degree slope of over thirty feet.

With the purchase of the property by the American Speech and Hearing Association, interior alterations to the mansion and the addition of an 86-spaced parking area on the east side of the mansion will result. A 40,000 square foot building designed to accommodate up to 140 employees and appurtenant parking facilities will be constructed in the northwest corner of the property. If the planned resale of the mansion and fifteen acres occurs after the new building is completed, the Montgomery County government will become one of the primary interested parties for the purchase of the mansion. The Montgomery County government rates the Corby Estate as the most desirable site for a new performing arts-civic center facility.

M: 30-12

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input checked="" type="checkbox"/> OTHER (SPECIFY) Local History
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

Corby Mansion was built for Charles Israel Corby, a successful businessman of Washington, D.C. Early in the twentieth century he and his brother, William, contributed much to the nationwide baking industry. William Corby was a partner in the baking firm of Fay and Stiles when Charles joined in 1890. By 1912 the business had enlarged and was incorporated as the Corby Baking Company with Charles T. Corby as president. The Corby Brothers were granted eight United States patents, and some foreign ones, for the first dough-molding machines which shaped dough into loaf forms. They eventually developed machines which could perform all the steps needed in the process of making bread. In 1898, they began wrapping their bread in waxed paper and, the next year, used refrigeration to control the fermentation period during manufacture. By 1901, the Corby Brothers began a scientific laboratory to study the problems related to bread-making and fermentation. They received a patent on July 11, 1905, for a machine which divided and weighed the dough. Their revolving dough-proofing cabinet saved much labor and was more sanitary than previous methods. The Corby's oven, built in 1914, baked more bread per pound of coal and doubled the output in the same amount of floor space formerly required. Thus Charles and William Corby did much to establish modern baking methods.

Charles Corby's mansion is a well-designed and executed example of Colonial Revival architecture. While it has a mix of elements from various styles, the basis of the design is from Georgian sources. The main block laid in Flemish bond has a white marble beltcourse and quoins. Inside, large central entrance and stair halls open onto the principal living and dining rooms of the first floor. There is a combination of Georgian and Federal treatment in the modillioned cornices, columns and pilasters and most of the mantelpieces. Federal influence can be seen in the semicircular entrance portico, the Palladian windows and, to some degree, in the projection of various rooms from a rectangular, central block. These projections are most evident when the mansion is seen from the garden. However, the extension of the kitchen wing and organ room are more evident in plan.

The Corby Mansion and John Russell Pope's Woodend (Wells Estate), now the Audubon Society Headquarters, are similar in form. The two of them are the best examples of the early twentieth century estates built in the area along Rockville Pike.

9 MAJOR BIBLIOGRAPHICAL REFERENCES

M: 30-12

Proctor, John Clagett. Washington-Past and Present. Lewis Historical Society, 1929-1930, pp 41-43

The Washington Star: Baking Concern Buys Corby Plant. 1925

Proctor, pp 41-43.

Ibid

Feasability study for the acquisition of the Corby

Ibid

Mansion-Montgomery County government (1975-76).

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY 33 acres

UTM REFERENCES

A	ZONE	EASTING	NORTHING	B	ZONE	EASTING	NORTHING
C	ZONE	EASTING	NORTHING	D	ZONE	EASTING	NORTHING

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE	CODE	COUNTY	CODE
STATE	CODE	COUNTY	CODE

11 FORM PREPARED BY

njm

NAME / TITLE

Roy H. Gauzza

ORGANIZATION

DATE

May 1977

STREET & NUMBER

TELEPHONE

10907 Jolly Way

CITY OR TOWN

STATE

Kensington,

Maryland 20795

12 STATE HISTORIC PRESERVATION OFFICER CERTIFICATION

THE EVALUATED SIGNIFICANCE OF THIS PROPERTY WITHIN THE STATE IS:

NATIONAL

STATE

LOCAL

As the designated State Historic Preservation Officer for the National Historic Preservation Act of 1966 (Public Law 89-665), I hereby nominate this property for inclusion in the National Register and certify that it has been evaluated according to the criteria and procedures set forth by the National Park Service.

STATE HISTORIC PRESERVATION OFFICER SIGNATURE

TITLE

DATE

FOR NPS USE ONLY

I HEREBY CERTIFY THAT THIS PROPERTY IS INCLUDED IN THE NATIONAL REGISTER

DATE

DIRECTOR, OFFICE OF ARCHEOLOGY AND HISTORIC PRESERVATION

TEST:

DATE

KEEPER OF THE NATIONAL REGISTER

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

AND/OR COMMON

Corby Estate

(now Strathmore Hall Arts Center - 1985)

2 LOCATION

STREET & NUMBER

10701 Rockville Pike (at Strathmore Ave.)

CITY, TOWN

Rockville

— VICINITY OF

CONGRESSIONAL DISTRICT

STATE

Maryland

COUNTY

Montgomery

3 CLASSIFICATION

CATEGORY

DISTRICT
 BUILDING(S)
 STRUCTURE
 SITE
 OBJECT

OWNERSHIP

PUBLIC
 PRIVATE
 BOTH
PUBLIC ACQUISITION
 IN PROCESS
 BEING CONSIDERED

STATUS

OCCUPIED
 UNOCCUPIED
 WORK IN PROGRESS
ACCESSIBLE
 YES: RESTRICTED
 YES: UNRESTRICTED
 NO

PRESENT USE

AGRICULTURE
 COMMERCIAL
 EDUCATIONAL
 ENTERTAINMENT
 GOVERNMENT
 INDUSTRIAL
 MILITARY
 MUSEUM
 PARK
 PRIVATE RESIDENCE
 RELIGIOUS
 SCIENTIFIC
 TRANSPORTATION
 OTHER:

4 OWNER OF PROPERTY

NAME

Sisters of the Holy Cross

Telephone #:

STREET & NUMBER

10701 Rockville Pike

CITY, TOWN

Rockville

— VICINITY OF

STATE, zip code
Maryland

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,
REGISTRY OF DEEDS, ETC.

Montgomery County Courthouse

Liber #:

Folio #:

STREET & NUMBER

CITY, TOWN

Rockville

STATE
Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

— FEDERAL — STATE — COUNTY — LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

M.30-12

CONDITION		CHECK ONE		CHECK ONE	
<input checked="" type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input checked="" type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE	<input type="checkbox"/> MOVED	DATE _____
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input type="checkbox"/> ALTERED			
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED				

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This is a huge, opulent brick building, built to resemble a magnificent Georgian mansion. The house is built in the shape of a T, with the leg of the T extending south from the central entrance of the building. This central entrance is located in the (north) main facade, and is accented by a columned, flat-roofed, stone portico, that features an ornate balustrade on the roof. This one-story entrance is flanked on either side by two-story, three-bay blocks of identical design. Each block has a hip roof covered with slate shingles. Large chimney stacks project from within the end walls. Carved stone balustrades surround the entire roofline of each block. The molded cornices have dentil rows. The brick walls are laid in Flemish bond, and have white marble quoins at each corner. The white marble trim also appears in the water-table, window frames and sills, and a wide belt course between the first and second stories.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

M. 30-12

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

This is an elegant Georgian Revival mansion of the early-20th Century that is no doubt the "queen" of the Rockville Pike estate architecture of that period. It was reportedly built for Carl Corby, whose family made their fortune in Washington building and real estate businesses. It has been owned by a Catholic religious order in recent years, and the Montgomery County government is currently considering purchasing the property for a county arts center.

CONTINUE ON SEPARATE SHEET IF NECESSARY

M. 30-12

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Feasibility study for the acquisition of the Corby Mansion-Mont. Co. government (1975-76).

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

unmarked form

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE COUNTY

STATE COUNTY

11 FORM PREPARED BY

NAME / TITLE

Michael F. Dwyer, Senior Park Historian

ORGANIZATION

M-NCPCC

DATE

5/14/75

STREET & NUMBER

8787 Georgia Ave.

TELEPHONE

589-1480

CITY OR TOWN

Silver Spring


STATE

Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438



**KENSINGTON, MD.
QUAD**

*M:30-12
COREY
MANSION*

M:30-12

1125
1124
2' 30"
1123
1122
495
1121
1120
1119
1118
1117
1116
1115
1114
1113
1112
1111
1110
1109
1108
1107
1106
1105
1104
1103
1102
1101
1100
1099
1098
1097
1096
1095
1094
1093
1092
1091
1090
1089
1088
1087
1086
1085
1084
1083
1082
1081
1080
1079
1078
1077
1076
1075
1074
1073
1072
1071
1070
1069
1068
1067
1066
1065
1064
1063
1062
1061
1060
1059
1058
1057
1056
1055
1054
1053
1052
1051
1050
1049
1048
1047
1046
1045
1044
1043
1042
1041
1040
1039
1038
1037
1036
1035
1034
1033
1032
1031
1030
1029
1028
1027
1026
1025
1024
1023
1022
1021
1020
1019
1018
1017
1016
1015
1014
1013
1012
1011
1010
1009
1008
1007
1006
1005
1004
1003
1002
1001
1000
999
998
997
996
995
994
993
992
991
990
989
988
987
986
985
984
983
982
981
980
979
978
977
976
975
974
973
972
971
970
969
968
967
966
965
964
963
962
961
960
959
958
957
956
955
954
953
952
951
950
949
948
947
946
945
944
943
942
941
940
939
938
937
936
935
934
933
932
931
930
929
928
927
926
925
924
923
922
921
920
919
918
917
916
915
914
913
912
911
910
909
908
907
906
905
904
903
902
901
900
899
898
897
896
895
894
893
892
891
890
889
888
887
886
885
884
883
882
881
880
879
878
877
876
875
874
873
872
871
870
869
868
867
866
865
864
863
862
861
860
859
858
857
856
855
854
853
852
851
850
849
848
847
846
845
844
843
842
841
840
839
838
837
836
835
834
833
832
831
830
829
828
827
826
825
824
823
822
821
820
819
818
817
816
815
814
813
812
811
810
809
808
807
806
805
804
803
802
801
800
799
798
797
796
795
794
793
792
791
790
789
788
787
786
785
784
783
782
781
780
779
778
777
776
775
774
773
772
771
770
769
768
767
766
765
764
763
762
761
760
759
758
757
756
755
754
753
752
751
750
749
748
747
746
745
744
743
742
741
740
739
738
737
736
735
734
733
732
731
730
729
728
727
726
725
724
723
722
721
720
719
718
717
716
715
714
713
712
711
710
709
708
707
706
705
704
703
702
701
700
699
698
697
696
695
694
693
692
691
690
689
688
687
686
685
684
683
682
681
680
679
678
677
676
675
674
673
672
671
670
669
668
667
666
665
664
663
662
661
660
659
658
657
656
655
654
653
652
651
650
649
648
647
646
645
644
643
642
641
640
639
638
637
636
635
634
633
632
631
630
629
628
627
626
625
624
623
622
621
620
619
618
617
616
615
614
613
612
611
610
609
608
607
606
605
604
603
602
601
600
599
598
597
596
595
594
593
592
591
590
589
588
587
586
585
584
583
582
581
580
579
578
577
576
575
574
573
572
571
570
569
568
567
566
565
564
563
562
561
560
559
558
557
556
555
554
553
552
551
550
549
548
547
546
545
544
543
542
541
540
539
538
537
536
535
534
533
532
531
530
529
528
527
526
525
524
523
522
521
520
519
518
517
516
515
514
513
512
511
510
509
508
507
506
505
504
503
502
501
500
499
498
497
496
495
494
493
492
491
490
489
488
487
486
485
484
483
482
481
480
479
478
477
476
475
474
473
472
471
470
469
468
467
466
465
464
463
462
461
460
459
458
457
456
455
454
453
452
451
450
449
448
447
446
445
444
443
442
441
440
439
438
437
436
435
434
433
432
431
430
429
428
427
426
425
424
423
422
421
420
419
418
417
416
415
414
413
412
411
410
409
408
407
406
405
404
403
402
401
400
399
398
397
396
395
394
393
392
391
390
389
388
387
386
385
384
383
382
381
380
379
378
377
376
375
374
373
372
371
370
369
368
367
366
365
364
363
362
361
360
359
358
357
356
355
354
353
352
351
350
349
348
347
346
345
344
343
342
341
340
339
338
337
336
335
334
333
332
331
330
329
328
327
326
325
324
323
322
321
320
319
318
317
316
315
314
313
312
311
310
309
308
307
306
305
304
303
302
301
300
299
298
297
296
295
294
293
292
291
290
289
288
287
286
285
284
283
282
281
280
279
278
277
276
275
274
273
272
271
270
269
268
267
266
265
264
263
262
261
260
259
258
257
256
255
254
253
252
251
250
249
248
247
246
245
244
243
242
241
240
239
238
237
236
235
234
233
232
231
230
229
228
227
226
225
224
223
222
221
220
219
218
217
216
215
214
213
212
211
210
209
208
207
206
205
204
203
202
201
200
199
198
197
196
195
194
193
192
191
190
189
188
187
186
185
184
183
182
181
180
179
178
177
176
175
174
173
172
171
170
169
168
167
166
165
164
163
162
161
160
159
158
157
156
155
154
153
152
151
150
149
148
147
146
145
144
143
142
141
140
139
138
137
136
135
134
133
132
131
130
129
128
127
126
125
124
123
122
121
120
119
118
117
116
115
114
113
112
111
110
109
108
107
106
105
104
103
102
101
100
99
98
97
96
95
94
93
92
91
90
89
88
87
86
85
84
83
82
81
80
79
78
77
76
75
74
73
72
71
70
69
68
67
66
65
64
63
62
61
60
59
58
57
56
55
54
53
52
51
50
49
48
47
46
45
44
43
42
41
40
39
38
37
36
35
34
33
32
31
30
29
28
27
26
25
24
23
22
21
20
19
18
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2
1
0

NATIONAL NAVAL MEDICAL CENTER
STONE LAKE

GAITHERSBURG 10 MI
117° 01' 00"



NAME CORBY ESTATE

(ESTATE FILE)

30-12

LOCATION 10701 ROCKVILLE PIKE, BETHESDA, MD.

FACADE NW

PHOTO TAKEN 5/14/75

M. ROYER



M. 30-12

Corby Mansion

front facade



M-30-12

Corby Mansion
garden facade



M 30-12

Corby Mansion



M 30-12

Corby Mansion



M 30-12

Corby Mansion



No. 30-12

(Conroy Estate)

Front Portico
Strathmore Hall
Montgomery City.

2/92