

PRINCE GEORGE'S COUNTY  
HISTORIC SITE SUMMARY SHEET

Survey #:     P.G. #68-12-14     Building Date:     circa 1900    

Building Name:                     Martha Miller House                    

Location:           4320 41st Street, Brentwood, Maryland          

Private/Residence/Occupied/Good/Inaccessible

Description

The Martha Miller House is a two-and-one-half story front-gabled frame dwelling. Entrance is in the third bay of the three-bay southeast gable front. Sheltering this facade is a one-story hip-roof porch which turns and shelters part of the north elevation; the porch has wide panelled posts on molded concrete bases. The house is sheathed with German siding painted beige. Windows are 2/2 and their surrounds are painted brown, as is most of the trim. The upper gable is sided with courses of fishscale, rectangular and sawtooth shingles; it encloses a small pointed-arch window at loft level. On the southwest elevation at loft level, there is a small flush crossgable which encloses a small triangular window.

Significance

The Martha Miller House is a very good example of the front-gabled frame dwellings which were built on the lots of the developing subdivisions of the early twentieth century. It was built circa 1900 for the family of Martha Miller, a widow who lived in this house with her daughter, a dressmaker, and her son, a carpenter. The Millers' house was a somewhat larger version of this popular house form, being three bays wide, and it was varied by a small flush crossgable on one of the side elevations.

Acreage: 6,554 Square feet

# Maryland Historical Trust State Historic Sites Inventory Form

## 1. Name (indicate preferred name)

historic Martha Miller House

and/or common

## 2. Location

street & number 4320 41st Street \_\_\_ not for publicationcity, town Brentwood \_\_\_ vicinity of congressional district 4state Maryland county Prince George's

## 3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input checked="" type="checkbox"/> private residence
<input type="checkbox"/> site	<b>Public Acquisition</b>	<b>Accessible</b>	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input checked="" type="checkbox"/> not applicable	<input checked="" type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

## 4. Owner of Property (give names and mailing addresses of all owners)

name Jose Ramos

street & number 4320 41st Street telephone no.:city, town Brentwood state and zip code MD 20722

## 5. Location of Legal Description

courthouse, registry of deeds, etc. Prince George's County Courthouse liber 4890street & number 14735 Main Street folio 773city, town Upper Marlboro state MD

## 6. Representation in Existing Historical Surveys

title None

date \_\_\_ federal \_\_\_ state \_\_\_ county \_\_\_ local

depository for survey records

city, town state

## 7. Description

Survey No. PG#68-12-14

<b>Condition</b>		<b>Check one</b>	<b>Check one</b>	
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input checked="" type="checkbox"/> original site	
<input checked="" type="checkbox"/> good	<input type="checkbox"/> ruins	<input checked="" type="checkbox"/> altered	<input type="checkbox"/> moved	date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed			

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The Martha Miller House is a two-and-one-half story front-gabled frame dwelling. Entrance is in the third bay of the three-bay southeast gable front. Sheltering this facade is a one-story hip-roof porch which turns and shelters part of the north elevation; the porch has wide panelled posts on molded concrete bases. The house is sheathed with German siding painted beige. Windows are 2/2 and their surrounds are painted brown, as is most of the trim. The upper gable is sided with courses of fishscale, rectangular and sawtooth shingles; it encloses a small pointed-arch window at loft level. On the southwest elevation at loft level, there is a small flush crossgable which encloses a small triangular window.

# 8. Significance

Survey No. PG#68-12-14

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input checked="" type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates ca. 1900

Builder/Architect

check: Applicable Criteria:  A  B  C  D  
and/or


Applicable Exception:  A  B  C  D  E  F  G

Level of Significance:  national  state  local

Prepare both a summary paragraph of significance and a general statement of history and support.

The Martha Miller House is a very good example of the front-gabled frame dwellings which were built on the lots of the developing subdivisions of the early twentieth century. It was built circa 1900 for the family of Martha Miller, a widow who lived in this house with her daughter, a dressmaker, and her son, a carpenter. The Millers' house was a somewhat larger version of this popular house form, being three bays wide, and it was varied by a small flush crossgable on one of the side elevations.





PG# 68-12-14

O

PG# 68-12-14  
Martha Miller House  
Brentwood  
Prince George's County  
Washington East Quadrangle



Pg # 68-12-14

14

Martha Miller House  
4320 41<sup>st</sup> Street  
Brentwood, P.G. Co.  
Susan H. Pearl  
March 1992  
Antitrust records

1 of 1