

Magi No.

DOE ___yes ___no

Maryland Historical Trust State Historic Sites Inventory Form

1. Name (indicate preferred name)

historic Bon Durant Residence

and/or common C. K. McConkey & Sons General Contractors

2. Location

street & number 3828 34th Street _____ not for publication

city, town Mt. Rainier _____ vicinity of _____ congressional district 5

state Maryland _____ county Prince George's

3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input checked="" type="checkbox"/> private residence
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input checked="" type="checkbox"/> not applicable	<input checked="" type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

4. Owner of Property (give names and mailing addresses of all owners)

name Charles and Sylvia McConkey

street & number 3824 34th Street _____ telephone no.:

city, town Mt. Rainier _____ state and zip code Maryland 20712

5. Location of Legal Description

courthouse, registry of deeds, etc. Prince George's County Courthouse _____ liber 4602

street & number Main Street _____ folio 160

city, town Upper Marlboro _____ state Maryland

6. Representation in Existing Historical Surveys

title Historic Sites and Districts Plan

date 1981 _____ federal _____ state county _____ localdepository for survey records ^{M-NCPPC} Historic Preservation Commission, Rm. 4010, C.A.B.

city, town Upper Marlboro _____ state Maryland

7. Description

Condition		Check one	Check one
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input checked="" type="checkbox"/> original site
<input checked="" type="checkbox"/> good	<input type="checkbox"/> ruins	<input checked="" type="checkbox"/> altered	<input type="checkbox"/> moved date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed		

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

3828 34th Street is a two-story rectangular plan frame dwelling sheathed with asphalt shingles and surmounted by a gable roof (see Slide #26). The roof is gable-ended at the north and south facades and is covered with asphalt shingles. The east (34th Street) slope has a centered shed roof dormer with a narrow 6/6 sash double-hung window. The first story of the main (east) facade is sheltered by an almost facade-wide shed roof raised porch covered with asphalt shingles and supported by plain Doric-style wooden columns. The south and southeast portions of the porch are enclosed by a wooden railing with simple rectangular spindles. There is a single wooden door entry at right (north) and a triple 6/1 sash double-hung window at left (south). At the second story above the entry, is a single 1/1 sash double-hung window. To the left (south) is a triple window identical to the one at the first story, but positioned slightly to the south of it. The north and south facades contain 1/1 sash double-hung windows at the first and second story. The east half of the north facade contains a single wood entry door at grade. The gable ends of the north and south facades are supported by two simple wooden brackets. The house retains an early character with the exceptions of the asphalt shingles of the facades and the small second story window of the main facade which appears to be out of scale and may be a modern replacement.



