

QA-180

Hollingsworth Farm
Church Hill vicinity
private

c. 1850-60

The Hollingsworth Farm is a mid-19th century frame vernacular structure, consisting of a five-bay long, two story main part and a four-bay, 1 1/2 story service wing. Its plan and form are typical of houses from the late 18th century thru the mid 19th century. Only the details of the windows, doors and porch indicate its late construction.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

AND/OR COMMON

Hollingsworth Farm

2 LOCATION

STREET & NUMBER

Hollingsworth Road, .2 miles north of Md. Rt. 302

CITY, TOWN

Church Hill

X VICINITY OF

CONGRESSIONAL DISTRICT

1st

STATE

Maryland

COUNTY

Queen Anne's

3 CLASSIFICATION

CATEGORY

- DISTRICT
- BUILDING(S)
- STRUCTURE
- SITE
- OBJECT

OWNERSHIP

- PUBLIC
- PRIVATE
- BOTH
- PUBLIC ACQUISITION**
- IN PROCESS
- BEING CONSIDERED
- not applicable

STATUS

- OCCUPIED
- UNOCCUPIED
- WORK IN PROGRESS
- ACCESSIBLE**
- YES: RESTRICTED
- YES: UNRESTRICTED
- NO

PRESENT USE

- AGRICULTURE
- MUSEUM
- COMMERCIAL
- PARK
- EDUCATIONAL
- PRIVATE RESIDENCE
- ENTERTAINMENT
- RELIGIOUS
- GOVERNMENT
- SCIENTIFIC
- INDUSTRIAL
- TRANSPORTATION
- MILITARY
- OTHER:

4 OWNER OF PROPERTY

NAME

Hollingsworth Farms Ltd. Partnership

Telephone #:

STREET & NUMBER

Box 101

CITY, TOWN

Church Hill

VICINITY OF

STATE, zip code

Maryland 21623

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,

REGISTRY OF DEEDS, ETC. Queen Anne's County Courthouse

Liber #: MWM 174

Folio #: 643

STREET & NUMBER

Courthouse Square

CITY, TOWN

Centreville

STATE

Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

FEDERAL STATE COUNTY LOCAL

DEPOSITORY FOR SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

QA-180

| | | | |
|------------------------------------|--------------------------------------------------|---------------------------------------------|---------------------------------------------------|
| CONDITION | | CHECK ONE | CHECK ONE |
| <input type="checkbox"/> EXCELLENT | <input checked="" type="checkbox"/> DETERIORATED | <input type="checkbox"/> UNALTERED | <input checked="" type="checkbox"/> ORIGINAL SITE |
| <input type="checkbox"/> GOOD | <input type="checkbox"/> RUINS | <input checked="" type="checkbox"/> ALTERED | <input type="checkbox"/> MOVED DATE _____ |
| <input type="checkbox"/> FAIR | <input type="checkbox"/> UNEXPOSED | | |

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Hollingsworth Farm located on Hollingsworth Road east of Church Hill is a two part frame building dating from the mid-19th century. It is composed of a two story five bay section and a four bay 1 1/2 story section, both of which are covered with brown wood shingles.

Across the east facade of the main part is a three bay porch with turned columns and pierced gallery beneath the roof. It stands on brick piers. Both of the other sections stand on a brick foundation. All of the windows throughout have 6/6 sash. The front entrance has a bold six-panel door with small panels in the center. There is a transom above the door. The principal cornice is relatively simple with the exception of the fascia which has a very executed applied scalloped board. The wing has a window and door closest the main part and two windows on the other half of the facade. Two dormers with 'A' roofs pierce the steeply pitched 'A' roof. At the ends of the main part and the gable of the wing rise brick chimneys. The 'A' roof of the main section is relatively shallow.

CONTINUE ON SEPARATE SHEET IF NECESSARY

CONTINUATION SHEET

7.1 DESCRIPTION

Across three of the four bays in back of the wing is a lean-to, partly enclosed. There are two dormers on the roof. The back of the main section has the same number of windows as the front, but there is no porch or transom, and the center window of the second story is lower than the rest.

Behind the house is a small board and batten smoke-house on brick piers. It appears to be late 19th century.

The interior plan consists of a central stair hall with dining room and living room flanking it. The wing appears to house a kitchen and pantry. The interior of the house was not accessible to the surveyor.

8 SIGNIFICANCE

PERIOD

AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW

- | | | | | |
|-----------------------------------------------|--------------------------------------------------|-------------------------------------------------|-------------------------------------------------|----------------------------------------------|
| <input type="checkbox"/> PREHISTORIC | <input type="checkbox"/> ARCHEOLOGY-PREHISTORIC | <input type="checkbox"/> COMMUNITY PLANNING | <input type="checkbox"/> LANDSCAPE ARCHITECTURE | <input type="checkbox"/> RELIGION |
| <input type="checkbox"/> 1400-1499 | <input type="checkbox"/> ARCHEOLOGY-HISTORIC | <input type="checkbox"/> CONSERVATION | <input type="checkbox"/> LAW | <input type="checkbox"/> SCIENCE |
| <input type="checkbox"/> 1500-1599 | <input type="checkbox"/> AGRICULTURE | <input type="checkbox"/> ECONOMICS | <input type="checkbox"/> LITERATURE | <input type="checkbox"/> SCULPTURE |
| <input type="checkbox"/> 1600-1699 | <input checked="" type="checkbox"/> ARCHITECTURE | <input type="checkbox"/> EDUCATION | <input type="checkbox"/> MILITARY | <input type="checkbox"/> SOCIAL/HUMANITARIAN |
| <input type="checkbox"/> 1700-1799 | <input type="checkbox"/> ART | <input type="checkbox"/> ENGINEERING | <input type="checkbox"/> MUSIC | <input type="checkbox"/> THEATER |
| <input checked="" type="checkbox"/> 1800-1899 | <input type="checkbox"/> COMMERCE | <input type="checkbox"/> EXPLORATION/SETTLEMENT | <input type="checkbox"/> PHILOSOPHY | <input type="checkbox"/> TRANSPORTATION |
| <input type="checkbox"/> 1900- | <input type="checkbox"/> COMMUNICATIONS | <input type="checkbox"/> INDUSTRY | <input type="checkbox"/> POLITICS/GOVERNMENT | <input type="checkbox"/> OTHER (SPECIFY) |
| | | <input type="checkbox"/> INVENTION | | |

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The Hollingsworth Farm is a mid-19th century frame vernacular structure, consisting of a five bay long, two story main part and a four-bay, 1 1/2 story service wing. Its plan and form are typical of houses from the late 18th century thru the mid-19th century. Only the details of the windows, doors and porch indicate its late construction.

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE COUNTY

STATE COUNTY

11 FORM PREPARED BY

NAME / TITLE

Michael O. Bourne, Historic Sites Surveyor

ORGANIZATION

Queen Anne's County Historical Society

DATE

9/20/83

STREET & NUMBER

TELEPHONE

CITY OR TOWN

Centreville


STATE

Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438



QA-180
State of Maryland
Queen Annes County
7.5 min. topo. map
1980 revisions
Scale: 1:62500

