

# Maryland Historical Trust

## State Historic Sites Inventory Form

### 1. Name (indicate preferred name)

historic SUBERS FARM or LEACH FARM

and/or common

### 2. Location

street & number 321 Kibler Road \_\_\_ not for publication

city, town Chestertown, MD \_\_\_ vicinity of congressional district 1st.

state Maryland county Queen Annes

### 3. Classification

| Category  | Ownership  | Status  | Present Use                                     |   |
|---|--|---|---|---|
| <input checked="" type="checkbox"/> district    | <input type="checkbox"/> public                    | <input checked="" type="checkbox"/> occupied        | <input checked="" type="checkbox"/> agriculture | <input type="checkbox"/> museum                       |
| <input checked="" type="checkbox"/> building(s) | <input checked="" type="checkbox"/> private        | <input type="checkbox"/> unoccupied                 | <input type="checkbox"/> commercial             | <input type="checkbox"/> park                         |
| <input type="checkbox"/> structure              | <input type="checkbox"/> both                      | <input type="checkbox"/> work in progress           | <input type="checkbox"/> educational            | <input type="checkbox"/> private residence            |
| <input type="checkbox"/> site                   | <b>Public Acquisition</b>                          | <b>Accessible</b>                                   | <input type="checkbox"/> entertainment          | <input type="checkbox"/> religious                    |
| <input type="checkbox"/> object                 | <input type="checkbox"/> in process                | <input checked="" type="checkbox"/> yes: restricted | <input type="checkbox"/> government             | <input type="checkbox"/> scientific                   |
|   | <input type="checkbox"/> being considered          | <input type="checkbox"/> yes: unrestricted          | <input type="checkbox"/> industrial             | <input type="checkbox"/> transportation               |
|   | <input checked="" type="checkbox"/> not applicable | <input type="checkbox"/> no                         | <input type="checkbox"/> military               | <input checked="" type="checkbox"/> other: apartments |

### 4. Owner of Property (give names and mailing addresses of all owners)

name Chino Farms, Inc.

street & number 841 McGuinness Road telephone no.: 410-778-2125

city, town Chestertown, MD state and zip code 21620

### 5. Location of Legal Description

courthouse, registry of deeds, etc. Queen Annes County Land Records Office liber MWM 399

street & number folio 688

city, town Centerville state MD

### 6. Representation in Existing Historical Surveys

title N/A

date \_\_\_ federal \_\_\_ state \_\_\_ county \_\_\_ local

depository for survey records

city, town state

# 7. Description

Survey No. QA-496

|  |                                       |   |   |                    |
|--|---------------------------------------|---|---|--------------------|
| <b>Condition</b>                         |                                       | <b>Check one</b>                            | <b>Check one</b>                                  |                    |
| <input type="checkbox"/> excellent       | <input type="checkbox"/> deteriorated | <input type="checkbox"/> unaltered          | <input checked="" type="checkbox"/> original site |                    |
| <input checked="" type="checkbox"/> good | <input type="checkbox"/> ruins        | <input checked="" type="checkbox"/> altered | <input type="checkbox"/> moved                    | date of move _____ |
| <input type="checkbox"/> fair            | <input type="checkbox"/> unexposed    |   |   |                    |

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

Subers Farmhouse, 321 Kibler Road is an early 20th century farmhouse located in the seventh election district of Queen Annes County, north of the crossroads referred to as Catlin Corner. It faces primarily east toward the lane to Kibler Road and includes several barns that were not included in this survey. The house is divided into two apartments, with one being on the first and another on the second and third floors.

The house is a five-bay long frame dwelling standing on a brick foundation. It is two-and-one-half stories tall and is covered with aluminum siding. There is an 'L' addition behind the south end of the house which is two stories tall and two-bays long. A one story family room was built in the corner of the 'L' in recent years. On both the east side of the main house and the south side of the kitchen 'L' there are covered porches with concrete floors and late 20th century iron balustrades. The windows have 1/1 sash and originally had shutters but do not at present. There are three "A" roof dormer windows on the east slope of the roof.

The plan of the house consists of a central stair hall with two flanking rooms. Behind the south room is a one room kitchen with bath between the two. The placement of the new room in the corner of the 'L' makes it possible to access the north room from the kitchen without having to use the stair hall, which is dedicated to the second floor apartment. The stair backs up to the kitchen, where there is access to the basement.

The basement is only under the northern half of the house. It has hard machine-made brick walls, concrete floor and circular sawn 2 X 10 floor joists overhead. Balloon framing with corner bracing is visible from the basement. In the north gable is the base of a one flue chimney.

The door and window trim is composed of approximately a four inch board with three reeds running down the center thereof. It is joined with both a mitered and a corner block corners. The only original doors are located on the closets and they have five horizontal panels. The hardware on the closets consists of a plain round metal knob and a long elliptical escutcheon which contains both the knob and keyhole.

The stair is a straight run to a landing and then turns 90° into the second story hall. Its balustrade consists of a large square paneled newel post with turned balusters, typical of the 1910 period. The room above the first floor kitchen consist of a kitchen and bath, with the living room taking up the south room. The north room and two attic rooms are bedrooms for this apartment

The finished attic or third floor is accessible from an enclosed stair in the  
at of the hall. There is a washer/dryer hook-up in the attic hall. Around the  
stair well is a solid balustrade of vertical beaded boards. Access to the unfinished  
attic over the kitchen is gained from the south attic room. From there it is possible  
to see the common rafter roof structure for both sections of the house. The kitchen  
attic rafters have neither tie beams nor ridge board, they are simply nailed together  
with wire nails.

The floors throughout the house are covered with carpet. Originally, there  
were pine floors, some of which are visible from the basement.

# 8. Significance

Survey No. QA-496

| Period                                    | Areas of Significance—Check and justify below    |   |   |  |
|---|--|---|---|--|
| <input type="checkbox"/> prehistoric      | <input type="checkbox"/> archeology-prehistoric  | <input type="checkbox"/> community planning     | <input type="checkbox"/> landscape architecture | <input type="checkbox"/> religion        |
| <input type="checkbox"/> 1400-1499        | <input type="checkbox"/> archeology-historic     | <input type="checkbox"/> conservation           | <input type="checkbox"/> law                    | <input type="checkbox"/> science         |
| <input type="checkbox"/> 1500-1599        | <input type="checkbox"/> agriculture             | <input type="checkbox"/> economics              | <input type="checkbox"/> literature             | <input type="checkbox"/> sculpture       |
| <input type="checkbox"/> 1600-1699        | <input checked="" type="checkbox"/> architecture | <input type="checkbox"/> education              | <input type="checkbox"/> military               | <input type="checkbox"/> social/         |
| <input type="checkbox"/> 1700-1799        | <input type="checkbox"/> art                     | <input type="checkbox"/> engineering            | <input type="checkbox"/> music                  | <input type="checkbox"/> humanitarian    |
| <input type="checkbox"/> 1800-1899        | <input type="checkbox"/> commerce                | <input type="checkbox"/> exploration/settlement | <input type="checkbox"/> philosophy             | <input type="checkbox"/> theater         |
| <input checked="" type="checkbox"/> 1900- | <input type="checkbox"/> communications          | <input type="checkbox"/> industry               | <input type="checkbox"/> politics/government    | <input type="checkbox"/> transportation  |
|   |  | <input type="checkbox"/> invention              |   | <input type="checkbox"/> other (specify) |

**Specific dates** \_\_\_\_\_ **Builder/Architect** \_\_\_\_\_

check: Applicable Criteria:  A  B  C  D  
and/or  
Applicable Exception:  A  B  C  D  E  F  G

Level of Significance:  national  state  local

Prepare both a summary paragraph of significance and a general statement of history and support.

The house located at 321 Kibler Road, Chestertown, is significant because it is an early 20th century vernacular form of farm house that developed in the 18th century as the prototypical farmhouse and was used with little change except for building methodology and millwork for over 200 years. From the exterior, it appears that the building could be nearly 60 years earlier in date than it is.

The farm was acquired by Chino Farms, Inc. in 1992 from Mr. & Mrs. Franklin Davis. In that deed, it is referred to as the Subers Farm or the Leach Farm and consists of 243 acres of land. No other research has been undertaken on this source except that the farm is listed on the 1877 Lake, Griffing, Stevenson Atlas of Kent and Queen Annes Counties in the ownership of Mrs. Hendrix.

10. Geographical Data

Acreage of nominated property 243 acs.

Quadrangle name

Quadrangle scale

UTM References do NOT complete UTM references

A Zone Easting Northing

B Zone Easting Northing

C Zone Easting Northing

D Zone Easting Northing

E Zone Easting Northing

F Zone Easting Northing

G Zone Easting Northing

H Zone Easting Northing

Verbal boundary description and justification

List all states and counties for properties overlapping state or county boundaries

state code county code

state code county code

11. Form Prepared By

name/title Michael Bourne, Easement Administrator

organization Maryland Historical Trust date


street & number 100 Community Place telephone 410-514-7633

city or town Crownsville state MD 21032

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust
Shaw House
21 State Circle
Annapolis, Maryland 21401
(301) 269-2438



QA-496  
U.S.G.S. 7.5 min. Map  
CHESTERTOWN QUAD

(CHURCH HILL)  
5862 III NW

MC GINNES 27 MI.

12°30'

510 000  
FEET

4343

4342

4341

4339

QA-496  
Subers Farm

Mary McCarthy  
Spring/Summer 2003  
Digital color photo on file at MHT

