

QA-680
711 Main Street
Stevensville, Queen Anne's County

Constructed ca. 1950
Commercial – Healing & Wellness Center

Summary Description

The property at 711 Main Street consists of three distinct sections. The western section, a one-story, three-bay, side-gable building is clad with stone on the front elevation. The rear and west side elevations are covered in horizontal board siding. A shed-roofed, box dormer rises out of the roof on the rear elevation of this section. The middle, side-gable dwelling is one story high and one bay wide, but is much smaller than the western section resulting in a much lower roofline. The eastern section is comprised of a one-story, two-bay, side gable building that is attached to, but slightly offset from the middle section.

Summary Statement of Significance

The building at 711 Main Street is significant as an example of adaptive re-use. Once a dwelling, built during the middle portion of the Twentieth Century when Stevensville was beginning to stretch out along Route 18, this building has found new life as a Healing and Wellness Center.

QA-680 711 Main St
Stevensville, Maryland
Queen Anne's County

Description

The property at 711 Main Street consists of three distinct sections. The western section, a one-story, three-bay, side-gable building is clad with stone on the front elevation. The rear and west side elevations are covered in horizontal board siding. A shed-roofed, box dormer rises out of the roof on the rear elevation of this section. The middle, side-gable dwelling is one story high and one bay wide, but is much smaller than the western section resulting in a much lower roofline. The eastern section is comprised of a one-story, two-bay, side gable building that is attached to, but slightly offset from the middle section.

A large, stone chimney is located outside of the west gable end. A screened-in porch is also located on the west elevation. A small cupola topped with a weathervane rises out of the top of the eastern section of the building.

The building is topped with a rust colored asphalt siding and clad in a wide horizontal board siding that is painted a tan color. The asymmetrical fenestration is primarily comprised of six-over-six vinyl windows of varying sizes. A bay window is located on the western side of the front elevation

Significance

The building at 711 Main Street is significant as an example of adaptive re-use. Once a dwelling, built during the middle portion of the Twentieth Century when Stevensville was beginning to stretch out along Route 18, this building has found new life as a Healing and Wellness Center. Though the building has been adapted through the years, each section of the building was added to meet the needs of the occupants and stands as a record of the buildings past. The change from dwelling to commercial space takes the process a step further by allowing the building to meet the needs of the larger community.

Boundaries

The boundaries of this property are as described in liber SM 1831 folio 46.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Inventory No. QA-680

1. Name of Property (indicate preferred name)

historic 711 Main Street

other

2. Location

street and number 711 Main Street __ not for publication

city, town Stevensville __ vicinity

county Queen Anne's County

3. Owner of Property (give names and mailing addresses of all owners)

name Michele R. Fish, Trustee

street and number 501 Wy Narrows Drive telephone

city, town Queenstown state MD zip code 21658

4. Location of Legal Description

courthouse, registry of deeds, etc. Queen Anne's County Courthouse liber SM 1831 folio 46

city, town Centreville tax map 56 tax parcel 18 tax ID number 04-051084

5. Primary Location of Additional Data

- Contributing Resource in National Register District
- Contributing Resource in Local Historic District
- Determined Eligible for the National Register/Maryland Register
- Determined Ineligible for the National Register/Maryland Register
- Recorded by HABS/HAER
- Historic Structure Report or Research Report at MHT
- Other: _____

6. Classification

Category	Ownership	Current Function	Resource Count	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input type="checkbox"/> agriculture	<input type="checkbox"/> landscape	Contributing
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input checked="" type="checkbox"/> commerce/trade	<input type="checkbox"/> recreation/culture	<input type="checkbox"/> Noncontributing
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> defense	<input type="checkbox"/> religion	<input type="checkbox"/> buildings
<input type="checkbox"/> site		<input type="checkbox"/> domestic	<input type="checkbox"/> social	<input type="checkbox"/> sites
<input type="checkbox"/> object		<input type="checkbox"/> education	<input type="checkbox"/> transportation	<input type="checkbox"/> structures
		<input type="checkbox"/> funerary	<input type="checkbox"/> work in progress	<input type="checkbox"/> objects
		<input type="checkbox"/> government	<input type="checkbox"/> unknown	<input checked="" type="checkbox"/> Total
		<input type="checkbox"/> health care	<input type="checkbox"/> vacant/not in use	
		<input type="checkbox"/> industry	<input type="checkbox"/> other:	
				Number of Contributing Resources previously listed in the Inventory
				0

7. Description

Inventory No. QA-680

Condition

excellent deteriorated
 good ruins
 fair altered

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

The property at 711 Main Street consists of three distinct sections. The western section, a one-story, three-bay, side-gable building is clad with stone on the front elevation. The rear and west side elevations are covered in horizontal board siding. A shed-roofed, box dormer rises out of the roof on the rear elevation of this section. The middle, side-gable dwelling is one story high and one bay wide, but is much smaller than the western section resulting in a much lower roofline. The eastern section is comprised of a one-story, two-bay, side gable building that is attached to, but slightly offset from the middles section.

A large, stone chimney is located outside of the west gable end. A screened-in porch is also located on the west elevation. A small cupola topped with a weathervane rises out of the top of the eastern section of the building.

The building is topped with a rust colored asphalt siding and clad in a wide horizontal board siding that is painted a tan color. The asymmetrical fenestration is primarily comprised of six-over-six vinyl windows of varying sizes. A bay window is located on the western side of the front elevation

8. Significance

Inventory No. QA-680

Period	Areas of Significance	Check and justify below		
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> health/medicine	<input type="checkbox"/> performing arts
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> archeology	<input type="checkbox"/> education	<input type="checkbox"/> industry	<input type="checkbox"/> philosophy
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> architecture	<input type="checkbox"/> engineering	<input type="checkbox"/> invention	<input type="checkbox"/> politics/government
<input checked="" type="checkbox"/> 1900-1999	<input type="checkbox"/> art	<input type="checkbox"/> entertainment/ recreation	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 2000-	<input type="checkbox"/> commerce	<input type="checkbox"/> ethnic heritage	<input type="checkbox"/> law	<input type="checkbox"/> science
	<input type="checkbox"/> communications	<input type="checkbox"/> exploration/ settlement	<input type="checkbox"/> literature	<input checked="" type="checkbox"/> social history
	<input type="checkbox"/> community planning		<input type="checkbox"/> maritime history	<input type="checkbox"/> transportation
	<input type="checkbox"/> conservation		<input type="checkbox"/> military	<input type="checkbox"/> other: _____

Specific dates

Architect/Builder

Construction dates ca. 1950

Evaluation for:


National Register

Maryland Register

not evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance projects, complete evaluation on a DOE Form – see manual.)

The building at 711 Main Street is significant as an example of adaptive re-use. Once a dwelling, built during the middle portion of the Twentieth Century when Stevensville was beginning to stretch out along Route 18, this building has found new life as a Healing and Wellness Center. Though the building has been adapted through the years, each section of the building was added to meet the needs of the occupants and stands as a record of the buildings past. The change from dwelling to commercial space takes the process a step further by allowing the building to meet the needs of the larger community.



QA - 680

711 Main St

Stevensville Vicinity, Queen Anne's County Maryland
Kent Island, Maryland Quadrangle (1:24,000)

Photo Log

QA- 680 – 711 Main Street
Photos Taken November 2009
By Rochelle Bohm, Consultant
Queen Anne's County

Photos Printed on Epson Premium Glossy Paper with Epson UltraChrome pigmented inks.

File Name (s)	Description
QA-680_2009-11-18_01 QA-680_2009-11-18_01.TIF	Environmental view looking northwest
QA-680_2009-11-18_02 QA-680_2009-11-18_02.TIF	Perspective view of south and east elevations looking northwest
QA-680_2009-11-18_03 QA-680_2009-11-18_03.TIF	View of south elevation looking north
QA-680_2009-11-18_04 QA-680_2009-11-18_04.TIF	Perspective view of north and east elevations looking southwest
QA-680_2009-11-18_05 QA-680_2009-11-18_05.TIF	View of north elevation looking south

HEALING
&
WELLNESS
Center

DR. JENNIFER M. WOOD
PHYSICIAN, D.D.S.

HEALTHY CHOICES
7-11-11
10000 10000
10000 10000

QA - 680

711 MAIN ST, STEVENSVILLE VICINITY
QUEEN ANNE'S COUNTY, MARYLAND

NOVEMBER 2009

MD SHPO

ENVIRONMENTAL VIEW FROM NORTHEAST

1015



QA-680

711 MAIN ST. STEVENSVILLE VICINITY
QUEEN ANNE'S COUNTY, MARYLAND

NOVEMBER 2009

MO SHPO

PERSPECTIVE VIEW OF SOUTH & EAST
ELEVATIONS LOOKING NORTHWEST.

245



QA-680

1711 MAIN ST., STEVENSVILLE VICINITY
QUEEN ANNE'S COUNTY, MARYLAND

NOVEMBER 2009

MD SHPO

VIEW OF SOUTH ELEVATION LOOKING NORTH,

345



QA-680

711 MAIN ST., STEVENSVILLE VICINITY
QUEEN ANNE'S COUNTY, MARYLAND

NOVEMBER 2009

MD SHPO

PERSPECTIVE VIEW OF NORTH AND EAST
ELEVATIONS LOOKING SOUTHWEST

4 of 5



QA-680

711 MAIN ST. STEVENSVILLE VICINITY
QUEEN ANNE'S COUNTY, MARYLAND

NOVEMBER 2009

MD SHPO

VIEW OF NORTH ELEVATION LOOKING
SOUTH.

545