

QA-694
1105 Main St
Stevensville, Queen Anne's County

Constructed ca. 1920
Private

Summary Description

The dwelling at 1105 Main Street is a one-and-one-half-story, five-bay, side-gable building. A shallow, hipped-roof porch supported by round pillars runs the full length of the front elevation. A concrete pad runs the full length and width of the porch. A one-story, shed-roofed addition is located on the northwest corner of the rear, or north, elevation.

Summary Statement of Significance

The dwelling at 1105 Main Street is significant for the historic details and form of the building. The exterior configuration suggests this building might have been used as a duplex. The six-over-six windows and the multi-paneled, multi-light doors suggest this building was built in the early 1900's.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Inventory No. QA-694

1. Name of Property (indicate preferred name)

historic 1105 Main Street

other

2. Location

street and number 1105 Main Street _ not for publication

city, town Stevensville _ vicinity

county Queen Anne's County

3. Owner of Property (give names and mailing addresses of all owners)

name Charles Jewell III & Melonie Baxter

street and number 1105 Main Street telephone

city, town Stevensville state MD zip code 21666

4. Location of Legal Description

courthouse, registry of deeds, etc. Queen Anne's County Courthouse liber SM 1825 folio 40

city, town Centreville tax map 57 tax parcel 2 tax ID number 04-025288

5. Primary Location of Additional Data

- Contributing Resource in National Register District
- Contributing Resource in Local Historic District
- Determined Eligible for the National Register/Maryland Register
- Determined Ineligible for the National Register/Maryland Register
- Recorded by HABS/HAER
- Historic Structure Report or Research Report at MHT
- Other: _____

6. Classification

Category	Ownership	Current Function	Resource Count	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input type="checkbox"/> agriculture	<input type="checkbox"/> landscape	Contributing
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> commerce/trade	<input type="checkbox"/> recreation/culture	Noncontributing
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> defense	<input type="checkbox"/> religion	<input type="checkbox"/> buildings
<input type="checkbox"/> site		<input checked="" type="checkbox"/> domestic	<input type="checkbox"/> social	<input type="checkbox"/> sites
<input type="checkbox"/> object		<input type="checkbox"/> education	<input type="checkbox"/> transportation	<input type="checkbox"/> structures
		<input type="checkbox"/> funerary	<input type="checkbox"/> work in progress	<input type="checkbox"/> objects
		<input type="checkbox"/> government	<input type="checkbox"/> unknown	<input checked="" type="checkbox"/> Total
		<input type="checkbox"/> health care	<input type="checkbox"/> vacant/not in use	
		<input type="checkbox"/> industry	<input type="checkbox"/> other:	
				Number of Contributing Resources previously listed in the Inventory
				0

7. Description

Inventory No. QA-694

Condition

excellent deteriorated
 good ruins
 fair altered

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

The dwelling at 1105 Main Street is a one-and-one-half-story, five-bay, side-gable building. Entrance doors are located on the corners of the front, or south, elevation. These doors are configured with twelve lights over two panels. Three gable dormers, containing six-over-six windows, rise out of the asphalt shingled roof. The dwelling, which is sheathed in vinyl siding contains many of the original six-over-six wood windows that are arranged symmetrically on the front and side elevations. A shallow, hipped-roof porch supported by round pillars runs the full length of the front elevation. A concrete pad runs the full length and width of the porch. A one-story, shed-roofed addition is located on the northwest corner of the rear, or north, elevation.

8. Significance

Inventory No. QA-694

Period	Areas of Significance	Check and justify below		
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> health/medicine	<input type="checkbox"/> performing arts
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> archeology	<input type="checkbox"/> education	<input type="checkbox"/> industry	<input type="checkbox"/> philosophy
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> architecture	<input type="checkbox"/> engineering	<input type="checkbox"/> invention	<input type="checkbox"/> politics/government
<input checked="" type="checkbox"/> 1900-1999	<input type="checkbox"/> art	<input type="checkbox"/> entertainment/ recreation	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 2000-	<input type="checkbox"/> commerce	<input type="checkbox"/> ethnic heritage	<input type="checkbox"/> law	<input type="checkbox"/> science
	<input type="checkbox"/> communications	<input type="checkbox"/> exploration/ settlement	<input type="checkbox"/> literature	<input checked="" type="checkbox"/> social history
	<input type="checkbox"/> community planning		<input type="checkbox"/> maritime history	<input type="checkbox"/> transportation
	<input type="checkbox"/> conservation		<input type="checkbox"/> military	<input type="checkbox"/> other: _____

Specific dates

Architect/Builder

Construction dates ca. 1920

Evaluation for:

National Register

Maryland Register

not evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance projects, complete evaluation on a DOE Form – see manual.)

The dwelling at 1105 Main Street is significant for the historic details and form of the building. The exterior configuration suggests this building might have been used as a duplex. The six-over-six windows and the multi-paneled, multi-light doors suggest this building was built in the early 1900's. These details and its possible use as a duplex suggest the innovative use or conversion of historic buildings to meet the needs of the changing Stevensville community.

At the time of survey the dwelling was slated for demolition.

9. Major Bibliographical References

Inventory No. QA-694

Kent Island Heritage Society Records

McAlester, Virginia & Lee. A Field Guide to American Houses. New York: Knopf, 1995.

Queen Anne's County Land Records

10. Geographical Data

Acreage of surveyed property 4.65 acres

Acreage of historical setting _____

Quadrangle name Kent Island, Maryland

Quadrangle scale: 1:24,000

Verbal boundary description and justification

The boundaries of this property are as described in liber SM 1823 folio 40.


11. Form Prepared by

name/title	Rochelle Bohm		
organization	QA County. Dept. of Land Use, Growth Management, & Environment date 6/29/10		
street & number	160 Coursevall Drive	telephone	410-758-1255
city or town	Centreville	state	Maryland

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust
Maryland Department of Planning
100 Community Place
Crownsville, MD 21032-2023
410-514-7600



QA - 694

1105 Main St

Stevensville Vicinity, Queen Anne's County Maryland
Kent Island, Maryland Quadrangle (1:24,000)

Photo Log

QA- 694 – 1105 Main Street
Photos Taken November 2009
By Rochelle Bohm, Consultant
Queen Anne's County

Photos Printed on Epson Premium Glossy Paper with Epson UltraChrome pigmented inks.

File Name (s)	Description
QA-694_2009-11-18_01 QA-694_2009-11-18_01.TIF	Perspective view of south and west elevations looking northeast
QA-694_2009-11-18_02 QA-694_2009-11-18_02.TIF	View of south elevation looking north
QA-694_2009-11-18_03 QA-694_2009-11-18_03.TIF	Perspective view of south and east elevations looking northwest
QA-694_2009-11-18_04 QA-694_2009-11-18_04.TIF	Perspective view of south and east elevations looking northwest
QA-694_2009-11-18_05 QA-694_2009-11-18_05.TIF	Detail of door on southeast corner of south elevation



QA-694

1105 MAIN ST. STEVENSVILLE
QUEEN ANNE'S COUNTY, MARYLAND

NOVEMBER 2009

MD SHPO

PERSPECTIVE VIEW OF SOUTH & WEST ELEVATIONS
LOOKING NORTHEAST.

1 of 5



QA-694

1105 MAIN ST. STEVENSVILLE
QUEEN ANNE'S COUNTY, MARYLAND

NOVEMBER 2009

MD SHPO

VIEW OF SOUTH ELEVATION LOOKING NORTH.

2 of 5



QA-694

1105 MAIN ST. STEVENSVILLE
QUEEN ANNE'S COUNTY, MARYLAND

NOVEMBER 2009

MD SHPO

PERSPECTIVE VIEW OF SOUTH & EAST ELEVATIONS
LOOKING NORTHWEST

3 of 5



QA - 694

1105 MAIN ST. STEVENSVILLE
QUEEN ANNE'S COUNTY, MARYLAND

NOVEMBER 2009

MD SHPD

PERSPECTIVE VIEW OF SOUTH & EAST ELEVATIONS
LOOKING NORTHWEST.

4 of 5



1105

QA-694

1105 MAIN ST. STEVENSVILLE
QUEEN ANNE'S COUNTY, MARYLAND

NOVEMBER 2009

MD SHPO

DETAIL OF DOOR ON SOUTHEAST CORNER OF
SOUTH ELEVATION.

5 of 5