

QA-73  
Windsor (Site)  
Centreville vicinity  
Private

18th century

Before it was demolished, Windsor was one of the finest small brick houses in the county. Dating to the 18th century, Windsor was a relatively unusual example of a story-and-a-half, double pile house, similar to Bachelor's Hope (QA-224) and the period two form of Stevens Adventure (QA-137). The four room interior plan is virtually identical to the plan of Morgan's Enclosure (QA-169) and the reconstructed plan of Cloverfields (QA-269), both on Kent Island. Other variations of this plan type have been noted elsewhere in the county. Significant decorative details included a Wall-of-Troy cornice and the outline of a barrell vaulted entrance porch, original mantels, overmantels, wainscot paneling and a fully paneled chimney breast.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

**1 NAME**

HISTORIC

Windsor, Kent Hall

AND/OR COMMON

**2 LOCATION**

STREET & NUMBER

Southeast side White Marsh Road

CITY, TOWN

Centreville

VICINITY OF

CONGRESSIONAL DISTRICT

1st

STATE

Maryland

COUNTY

Queen Anne's

**3 CLASSIFICATION**

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input type="checkbox"/> PUBLIC	<input type="checkbox"/> OCCUPIED	<input checked="" type="checkbox"/> AGRICULTURE <input type="checkbox"/> MUSEUM
<input type="checkbox"/> BUILDING(S)	<input checked="" type="checkbox"/> PRIVATE	<input checked="" type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL <input type="checkbox"/> PARK
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> PRIVATE RESIDENCE
<input checked="" type="checkbox"/> SITE	<b>PUBLIC ACQUISITION</b>	<b>ACCESSIBLE</b>	<input type="checkbox"/> ENTERTAINMENT <input type="checkbox"/> RELIGIOUS
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input checked="" type="checkbox"/> YES: RESTRICTED	<input type="checkbox"/> GOVERNMENT <input type="checkbox"/> SCIENTIFIC
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> INDUSTRIAL <input type="checkbox"/> TRANSPORTATION
		<input type="checkbox"/> NO	<input type="checkbox"/> MILITARY <input type="checkbox"/> OTHER:

**4 OWNER OF PROPERTY**

NAME

Louise C. Cook

Telephone #:

STREET & NUMBER

RT#1

CITY, TOWN

Centreville

VICINITY OF

STATE, zip code

Maryland 21617

**5 LOCATION OF LEGAL DESCRIPTION**

COURTHOUSE,  
REGISTRY OF DEEDS, ETC

Queen Anne's County Courthouse

Liber #: TSP 71

Folio #: 188

STREET & NUMBER

Courthouse Square

CITY, TOWN

Centreville

STATE

Maryland

**6 REPRESENTATION IN EXISTING SURVEYS**

TITLE

DATE

FEDERAL  STATE  COUNTY  LOCAL

DEPOSITORY FOR  
SURVEY RECORDS

CITY, TOWN

STATE

QA-73

**7 DESCRIPTION**

<b>CONDITION</b>		<b>CHECK ONE</b>	<b>CHECK ONE</b>
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input checked="" type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED    DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		
	<input checked="" type="checkbox"/> Site		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

Windsor was located on the southeast side of White Marsh Road approximately 1/4 mile east of the intersection with Tanyard Road and four miles northeast of Centreville.

The only records that have survived of the house are two photographs, a plan, and a brief description published by Dr. H.C. Forman in 1956. At that time the house was vacant and in declining condition. It was later demolished. Bricks from the building are said to have been used to construct two wings on a frame house approximately three miles northeast of Centreville on Maryland Route 213. The following description is based on the record published by Forman. For more precise details see Forman, Tidewater Maryland Architecture and Gardens, p. 73, 76, 89, 90.

Windsor was a relatively small brick house, 1 1/2 stories high, five bays wide and two rooms deep, with one flush chimney at each end of the pitched gable roof.

The principal entrance was centered on the front facade, flanked by two 9/9 windows on each side. Two 6/6 pitched roof dormers were located

CONTINUE ON SEPARATE SHEET IF NECESSARY

## CONTINUATION SHEET

## 7.1 DESCRIPTION

on the second floor. The outline of a handsome barrel vaulted entrance porch is clearly visible in Dr. Forman's photographs, with one plain pilaster with an ornately molded cap to the left of the door. Flemish bond brickwork is visible where the porch was removed. The rest of the brickwork is obscured by whitewash. The eaves on this facade were finished with a large, molded cornice with a Wall-of-Troy dentil course band below the soffit. The entrance door had a transom and paneled jambs.

On the right gable wall, there was one window to the left of the chimney on the first floor and a pair of smaller windows flanking the chimney on the second floor.

Although no photographs have survived of the left gable or the rear facade, Forman's plan allows some description. A door was centered on the rear facade, flanked by two windows to the right and one to the left. On the gable wall, there was one door at the rear and a single window toward the front on the first floor. Most likely there also were windows in the upper gable flanking the chimney.

The interior plan was relatively unusual. The front door opened into a large hall that was three bays across and extended more than half the depth of

## CONTINUATION SHEET

## 7.2 DESCRIPTION

the house. To the rear of this hall was a separate stair hall, with the stair rising against the rear facade wall to a landing against the gable wall, then turning 180 degrees to rise to the second floor. To the left of the front hall was a relatively large parlor that shared a chimney stack with a smaller dining room to the rear. A door in the gable wall of the dining room evidently led to a detached or separate kitchen.

Dr. Forman describes the interior as quite ornate. There were mantels and overmantels in all four rooms, and paneling on the hall fireplace rising to the ceiling. The remaining three rooms had wainscot paneling up to window sill height. All four rooms had heavily molded cornices, including a dentil course cornice in the hall and a Wall-of-Troy cornice in the stair hall.

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
1400-1499	<input checked="" type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input checked="" type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

Before it was demolished, Windsor was one of the finest small brick houses in the county. Dating to the 18th century, Windsor was a relatively unusual example of a story-and-a-half, double pile house, similar to Bachelor's Hope (QA-224) and the period two form of Stevens Adventure (QA-137). The four room interior plan is virtually identical to the plan of Morgan's Enclosure (QA-169) and the reconstructed plan of Cloverfields (QA-269), both on Kent Island. Other variations of this plan type have been noted elsewhere in the county. Significant decorative details included a Wall-of-Troy cornice and the outline of a barrell vaulted entrance porch, original mantels, overmantels, wainscot paneling and a fully paneled chimney breast.

CONTINUE ON SEPARATE SHEET IF NECESSARY

**9 MAJOR BIBLIOGRAPHICAL REFERENCES**

QA-73

Forman, Henry Chandlee. Tidewater Maryland Architecture and Gardens. New York: Bonanza Books, 1956.

CONTINUE ON SEPARATE SHEET IF NECESSARY

**10 GEOGRAPHICAL DATA**

ACREAGE OF NOMINATED PROPERTY \_\_\_\_\_

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE	COUNTY
STATE	COUNTY

**11 FORM PREPARED BY**

NAME / TITLE

Orlando Ridout V, Historic Sites Surveyor

ORGANIZATION

Queen Anne's County Historical Society

DATE

10/26/81

STREET & NUMBER

TELEPHONE

CITY OR TOWN

Centreville


STATE

Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust  
The Shaw House, 21 State Circle  
Annapolis, Maryland 21401  
(301) 267-1438



SECOND

SIXTH

QA-73  
Windsor  
Site

