

Maryland Historical Trust State Historic Sites Inventory Form

1. Name (indicate preferred name)

historic Trimble House (preferred)

and/or common Quarters "W"/Building #965

2. Location

street & number In Patuxent River Naval Air Station on Johnson Road not for publication

city, town Lexington Park vicinity of congressional district first

state Maryland county St. Mary's

3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input checked="" type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input checked="" type="checkbox"/> private residence
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input checked="" type="checkbox"/> not applicable	<input checked="" type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

4. Owner of Property (give names and mailing addresses of all owners)

name Department of the Navy, U.S. Government

street & number telephone no.:

city, town state and zip code

5. Location of Legal Description

courthouse, registry of deeds, etc. St. Mary's County Courthouse liber JMM

street & number folio 165

city, town Leonardtown state MD

6. Representation in Existing Historical Surveys

title none

date federal state county local

pository for survey records

city, town state

7. Description

Survey No. SM 359

Condition

excellent
 good
 fair

deteriorated
 ruins
 unexposed

Check one

unaltered
 altered

Check one

original site
 moved date of move _____

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

8. Significance

Survey No.

SM359

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates built c. 1820-40 **Builder/Architect**

check: Applicable Criteria: A B C D
and/or
Applicable Exception: A B C D E F G
Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.

9. Major Bibliographical References

Survey No. SM-359

Homeowner's Loan Association, Valuation Analysis and Conclusions (1942). Ms. on file, Southern Maryland Regional Preservation Center, St. Mary's City, MD.

10. Geographical Data

Acreeage of nominated property _____

Quadrangle name Solomons Island, MD

Quadrangle scale 1:24000

UTM References do NOT complete UTM references

A	<input type="text"/>	<input type="text"/>	<input type="text"/>
	Zone	Easting	Northing

B	<input type="text"/>	<input type="text"/>	<input type="text"/>
	Zone	Easting	Northing

C	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

D	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

E	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

F	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

G	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

H	<input type="text"/>	<input type="text"/>	<input type="text"/>
---	----------------------	----------------------	----------------------

Verbal boundary description and justification

List all states and counties for properties overlapping state or county boundaries

state	code	county	code

11. Form Prepared By

name/title Orlando Ridout V, Dennis J. Pogue

organization MHT date 5-1-83

street & number 21 State Circle telephone 269-2438

city or town Annapolis state MD

Field Notebook MD-7; Recorded 21 December 1982.

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust
Shaw House
21 State Circle
Annapolis, Maryland 21401
(301) 269-2438

Trimble House:

7.0

The Trimble House is located on a level terrace approximately 10 feet above sea level, facing and less than 100 feet west of the Chesapeake Bay. The house is a $1\frac{1}{2}$ -story frame dwelling three bays long and one room deep with exterior brick chimneys at each end of the steeply pitched gable roof. The house has been enlarged and extensively renovated; additions include a lean-to across the entire west facade and a two-part addition to the north.

The principal facade faces east to the Chesapeake Bay. The front door is offset slightly to left of center, flanked by one 9-over-6 window on either side. A later door has been cut in at the extreme north end of this facade. Three pitched roof dormers are ranged across the second story. The center dormer is fitted with 6-over-6 sash and is larger than the flanking dormers, which are fitted with 4-over-4 sash. The door is trimmed with ^awide, flattened ogee/astroyal backband applied to a plain (probably replaced) fascia, while the windows are trimmed with plain beaded fascias. The cut-in door to the north has matching trim but modern milling marks are evident and the trim is clearly made to match the early trim.

A one-story frame addition covers the majority of the north gable wall. The exterior brick chimney appears to be rebuilt. The only opening on this facade is one 9-over-6 window to the west of the chimney on the first story.

The original west facade of the house is concealed by a later one story frame lean-to addition. Two dormer windows on the second story remain in place but the sash has been removed and the openings blocked.

The exterior chimney on the south gable wall does not appear to have been rebuilt. The chimney is flanked by single 9-over-6 windows on the first floor and one 4-over-4 window in the east bay of the second story.

The interior of the main house was probably originally divided into a hall and parlor or a center passage plan. It has been opened up into a single large room with fireplaces centered on the north and south gable walls. An open-strung (?) stair rises against the west facade wall, turns ^s 90 degrees, and continues up to the second story. This stair is presumably rebuilt and quite possibly is not in an original location, but it includes an early bannister consisting of delicate turned newls, a continuous molded rail, tapered balusters, scrolled step brackets, and replaced treads.

The most significant surviving ^{interior} features are the first floor mantels. The south mantel is composed of molded pilasters flanking the opening below sideblocks and a frieze. The sideblocks are decorated with oval fretwork. The complex molded mantel shelf is dominated by an ogee/astrayal profile similar to the backband on the front door architrave. ←

← The north mantel is a board surround with a cove/astrayal backband framing the opening below small sideblocks, a larger center block, and a complex molded shelf.

The second-floor plan has been modified to accommodate a modern bath and closets, but evidence survives of original vertical beaded board partitions that formed a center stair passage plan with one chamber on either side and a small unheated room at the east end of the passage. The north room was heated by a small fireplace on the north gable wall. This fireplace is fitted with an early 19th century mantel that consists of a board surround with ogee/astrayal backband framing the opening below a plain frieze and complex shelf.

A small opening in the ceiling of the west lean-to allows examination of the west eave of the original house. One original beaded weatherboard survives and the ghost outline of the cornice bedmold is evident. The weatherboard is secured with early machine nails; the rafters are nailed to the plate with one large wrought spike and several smaller machine nails. ←

└ From this limited access to the lean-to roof, it would appear that the lean-to is an early addition that has been extensively altered.

8.0

The Trimble House is a 1½-story frame dwelling that appears to date to circa 1820s. It was enlarged at an early period by the addition of a frame lean-to across the west facade and in the 20th century has been further enlarged and extensively renovated. The early fenestration pattern, 9-over-6 sash and molded exterior architrave trim, is largely intact. The interior plan has been opened up into a single room, but three original mantels and a possibly rebuilt open-strung stair survive. Other features of interest include the beaded board partitions on the second story and the beaded weatherboard and cornice evidence visible from the crawl space above the lean-to ceiling.

SM-359



1942



SM-359
 Trimble House
 Solomons Island Quad

4239
17'30"

4238

4237

4236

4235000 N

38°15'

V T R I V E R

Hog Pt

Fishing Pt

Pearson Creek

Harper Creek

Cedar Poi

Fresh Pond

PATUXENT RIVER

AIR TEST CENTER

SM 359

Abell 2

Pine Hill

Towers

CHESAPEAKE





#965 Trimble House

(Sm 359)