

Capsule Summary

Survey No.: T-1128

Name: 24108 Mount Pleasant Road

Construction Date: early-twentieth century

Town/Vicinity: St. Michaels

County: Talbot

Access: Private

Summary Description:

The building is located on Mount Pleasant Road, west of St. Michaels, in a semi-rural setting. The house is a one-and-one-half-story, wood framed residence with a lateral gabled roof and full width screened porch. Originally rectangular in plan, the house was expanded to the west with a one-and-one-half-story addition. Centrally located dormers are placed on the front and rear elevations. The building rests on a brick pier foundation and is clad in asphalt shingles.

Maryland Historical Trust
State Historic Sites Inventory Form

MARYLAND INVENTORY OF
HISTORIC PROPERTIES

Survey No. T-1128

Magi No.

DOE yes no

1. Name (indicate preferred name)

historic

and/or common 24108 Mount Pleasant Road

2. Location

street & number 24108 Mount Pleasant Road not for publication

city, town St. Michaels vicinity of congressional district First

state Maryland county Talbot

3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input checked="" type="checkbox"/> private residence
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input checked="" type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input checked="" type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

4. Owner of Property (give names and mailing addresses of all owners)

name Charles M. Kirby et al.

street & number 24108 Mount Pleasant Road telephone no.:

city, town St. Michaels state and zip code MD 21663

5. Location of Legal Description

courthouse, registry of deeds, etc. Talbot County Courthouse liber 532

street & number Washington Street folio 72

city, town Easton state MD 21601

6. Representation in Existing Historical Surveys

title None

date federal state county local

depository for survey records

city, town state

7. Description

Survey No. T-1128

Condition

excellent
 good
 fair

deteriorated
 ruins
 unexposed

Check one

unaltered
 altered

Check one

original site
 moved date of move _____

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

Contributing Resource Count: 1

This building is a one-and-one-half-story, wood frame residence with a lateral gable roof and full width screened porch exhibiting influences of the Craftsman Style. The building is located on Mount Pleasant Road west of St. Michaels in a semi-rural setting. Originally rectangular in plan, a one-and-one-half-story addition has been attached to the west elevation of the house. The facade contains a central entrance with flanking two-over-two, double hung windows. Centrally located dormers with paired windows are located on the front and rear elevations. An exterior end, concrete block chimney is attached to the west end of the main block. The facade of the west wing contains a single entrance and a two-over-two, double hung window. The rear elevation contains a central entrance that has been boarded over and two, six-over-six, double-hung windows. The building rests on a brick pier foundation and is clad with asphalt shingles.

Several modern outbuildings lie north of the main house. A half story, plywood shed roofed structure is in the center of the yard and may be covering a pump or well. A second plywood shed is located in the northwest corner of the property. The shed has openings on the south and west elevations. Just north of this shed is a metal shed which opens to the east.

8. Significance

Survey No. T-1128

Period	Areas of Significance--Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistory	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates _____ Builder/Architect _____ unknown _____

check: Applicable Criteria: A B C D
and/or

Applicable Exception: A B C D E F G

Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.

This building is a modest example of early twentieth century domestic architecture with Craftsman influences common to the area. Its date of construction places it in the Industrial/Urban Dominance chronological period (1870-1930). The building's original form has been altered by the addition of the west wing, and its historic character compromised by the introduction of asphalt siding. It does not embody the distinctive characteristics of its type, and therefore, cannot be considered architecturally significant. Furthermore, it is not associated with an important historic figure or event. Therefore, the property is recommended not eligible for listing in the National Register of Historic Places A, B or C.

MARYLAND HISTORICAL TRUST REVIEW

Eligibility recommended _____ Eligibility not recommended X

Criteria: A B C D Considerations: A B C D E F G None

Comments: _____

[Signature]
 Reviewer, Office of Preservation Services

[Signature]
 Reviewer, NR program

4/20/99
 Date

8/14/00
 Date



T-1128

24108 Mount Pleasant Road

St. Michaels, MD

SKETCH MAP - NOT TO SCALE

drawn by: Rachel Mancini
John Milner Associates, Inc.
August, 1998



**MARYLAND COMPREHENSIVE
HISTORIC PRESERVATION PLAN DATA**

HISTORIC CONTEXT

Geographic Organization: Eastern Shore

Chronological/Development Period(s): Industrial/Urban Dominance Period A.D. 1870-1930

Historic Period Theme(s): Architecture, Landscape Architecture, Community Planning


Resource Type:

Category: Building

Historic Environment: Village

Historic Function(s) and Use(s): DOMESTIC/single dwelling

Known Design Source: none



T-1128
24108 Mount Pleasant Rd.
St. Michaels, MD
QUAD ST. MICHAELS, MD

BROAD
CREEK
Point O' Pines
Mulberry Point

Hambleton
Island

12'30"

196



T-1128

24108 Mt Pleasant Rd.
St. Michaels, Talbot Co, MD

Rachel Mancini

August 4, 1998

negs → MD SHPO

Main house. South elevation - front

1 of 8

PROTEC8/98<No.12 >011
798 0682 N N N N 21 2<040>



T-1128

24108 Mt. Pleasant Rd.

St. Michaels, Talbot Co., MD

Rachel Mancini

August 4, 1998

neg's → MD SHPO

PROTECS/98<No-11 >010
798 0682 N N N N 16 2(040)

Main house, east elevation

2 of 8



T-1128

24108 Mt. Pleasant Road
St. Michaels, Talbot Co., MD

Rachel Mancini

August 4, 1998

neg's → MD SHPO

Main house, north elevation

3 of 8

PROTECS/98<No.10 >009
298 0682 N N N-1 12 2(040)

12/17



T- 1128
24108 Mt. Pleasant Road
St. Michaels, Talbot Co., MD
Rachel Mancini
August 4, 1998
neg's → MD SHPO

PROTECS/98<No. 9 >008
798 0682 N N N-1 09 2<048>

Main house, west elevation

4 of 8



T-1128

24108 Mt. Pleasant Road
St Michaels, Talbot Co., MD

Rachel Mancini

August 4, 1998

neg's → MD SHPO

PROTEC8/98<No. 8 >887
798 0682 N N N-1 11 2 (848)

Outbuildings, looking NW

5 of 8



T-1128

24108 Mt. Pleasant Rd.

St. Michaels, Talbot Co., MD

Rachel Mancini

August 4, 1998

neg's → MD SHPO

PROTEC8/98<No. 7 >005
798 0682 N N N-1 04 2(040)

Outbuilding, looking South

6 of 8

12/20



T-1128

24108 Mt. Pleasant Rd.

St. Michaels, Talbot Co., MD

Rachel Mancini

August 4, 1998

negs → MD SHPO

PROTEC8/98<No. 6 >005
798 0682 N N N N 06 2 (040)

Outbuildings, looking SW

7 of 8



T-1128

24108 Mt. Pleasant Rd.
St. Michaels, Talbot Co, MD
Rachel Mancin.

August 4, 1998

neg^s → MD SHPO

Outbuildings, looking NE

8 of 8

PROTEC8/98<No. 5 >004
798 0682 N N N-2 01 2(040)

12/22