

T-807
Laura Miller House
Copperville
Private

c. 1900

The Laura Miller house is a plain two-story, three-bay frame dwelling that dates to the early twentieth century. Built around 1900, the asbestos shingled frame dwelling is similar to other village dwellings with its symmetrical fenestration and interior end brick chimneys. The house is one of approximately a dozen turn of the twentieth century houses that defines Copperville.

HISTORIC CONTEXT INFORMATION

Resource Name: LAURA MILLER HOUSE

MHT Inventory Number: T-807

MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA:

- 1) Historic Period Theme(s): ARCHITECTURE
- 2) Geographic Orientation: EASTERN SHORE
- 3) Chronological/Developmental Period(s):
INDUSTRIAL/URBAN DOMINANCE
1870-1930
- 4) Resource Type(s):
SINGLE-FAMILY DWELLING

Maryland Historical Trust State Historic Sites Inventory Form

1. Name (indicate preferred name)

historic

and/or common LAURA MILLER HOUSE

2. Location

street & number West side of Copperville Road not for publicationcity, town Copperville vicinity of congressional district First

state Maryland county Talbot

3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input checked="" type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input type="checkbox"/> private residence
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input checked="" type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input checked="" type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military	<input checked="" type="checkbox"/> other: vacant

4. Owner of Property (give names and mailing addresses of all owners)

name

street & number telephone no.:

city, town state and zip code

5. Location of Legal Description

courthouse, registry of deeds, etc. Talbot County Clerk of Court liber

street & number Talbot County Courthouse folio

city, town Easton state Md 21871

6. Representation in Existing Historical Surveys

title

date federal state county local

pository for survey records

city, town

state

7. Description

Survey No. T-807

Condition		Check one	Check one	
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input checked="" type="checkbox"/> original site	
<input type="checkbox"/> good	<input type="checkbox"/> ruins	<input checked="" type="checkbox"/> altered	<input type="checkbox"/> moved	date of move _____
<input checked="" type="checkbox"/> fair	<input type="checkbox"/> unexposed			

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The Laura Miller house is located on the west side of Copperville Road in the small village of Copperville, Talbot County, Maryland. The two-story, three-bay frame dwelling faces southeast with the gable roof oriented on a northeast/southwest axis.

Built around 1910, the two-story, three-bay frame dwelling is supported on a low masonry foundation, and the house is clad with a layer of asbestos shingles. The medium pitched asphalt shingle roof has extended eaves and sloped soffits. Attached to the back of the main block is a single story shed roofed addition.

The southeast (main) facade is a three-bay elevation with a center four-panel door and flanking boarded over windows. The front door is sheltered by a single-bay porch supported on square posts. Lighting the second floor are three six-over-six sash windows.

The southwest gable end is a blind wall surface with a slightly extended eave and an interior end brick stove flue. An interior end stack rises through the northeast gable end as well.

The back (northwest) side of the house is partially covered by the single-story rear wing. Exterior finishes follow along the same methods as the rest of the house.

The interior was not seen.

8. Significance

Survey No. T-807


Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/ humanitarian
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> theater
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> transportation
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> other (specify)
		<input type="checkbox"/> invention		

Specific dates	Builder/Architect
----------------	-------------------

check: Applicable Criteria: A B C D
 and/or
 Applicable Exception: A B C D E F G
 Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.

The Laura Miller house is a plain two-story, three-bay frame dwelling that dates to the early twentieth century. Built around 1900, the asbestos shingled frame dwelling is similar to other village dwellings with its symmetrical fenestration and interior end brick chimneys. The house is one of approximately a dozen turn of the twentieth century houses that defines Copperville.



T-807
LAURA MILLER HOUSE
Copperville, Maryland
St. Michaels, MD Quadrangle
1942

Bennett Pt

Wyetown Point

SHAW BAY

Creek

Creek

Copperville

Tank

Tun's Mills

C R E E K

NECK

Unionville



T-807

LAURA MILLER HOUSE

Copperville, Talbot County, MD

Southeast elevation

6/90, Paul Touart, photographer

Negative/MD Historical Trust