

ABSTRACT

WA-I-376

19th Century

Stockslager Farm
Hagerstown Vicinity
private

This farmstead, now demolished included a large, two story, eight bay brick and presumably brick cased log house, and a brick bank barn with decorative geometric ventilators in its end walls. Both structures appeared to have been built during the mid 19th centuries.

MARYLAND HISTORICAL TRUST

WA-I-376
 District 26
 Map 49
 Parcel 1663
 MAGI # 2205835535
 1409

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

AND/OR COMMON

Stockslager Farm

*Jan demolished
 house still there*

2 LOCATION

STREET & NUMBER

Off Downsville Pike (Rte. 632) South of Oak Rdige Drive on Garden Lane

CITY, TOWN

CONGRESSIONAL DISTRICT

 VICINITY OF Hagerstown

6

STATE

Maryland

COUNTY

Washington

3 CLASSIFICATION

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input type="checkbox"/> PUBLIC	<input checked="" type="checkbox"/> OCCUPIED	<input type="checkbox"/> AGRICULTURE <input type="checkbox"/> MUSEUM
<input checked="" type="checkbox"/> BUILDING(S)	<input checked="" type="checkbox"/> PRIVATE	<input type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL <input type="checkbox"/> PARK
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> EDUCATIONAL <input checked="" type="checkbox"/> PRIVATE RESIDENCE
<input type="checkbox"/> SITE	<input type="checkbox"/> PUBLIC ACQUISITION	<input type="checkbox"/> ACCESSIBLE	<input type="checkbox"/> ENTERTAINMENT <input type="checkbox"/> RELIGIOUS
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input type="checkbox"/> YES: RESTRICTED	<input type="checkbox"/> GOVERNMENT <input type="checkbox"/> SCIENTIFIC
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> INDUSTRIAL <input type="checkbox"/> TRANSPORTATION
		<input checked="" type="checkbox"/> NO	<input type="checkbox"/> MILITARY <input type="checkbox"/> OTHER

4 OWNER OF PROPERTY

NAME

Leslie Wakeknight
~~Oak Ridge Park Apts. Section 5~~

Telephone #:

STREET & NUMBER

~~C/O Mr. Edwin B. Feldman~~
 3000 7th St. N. E.

CITY, TOWN

Washington

VICINITY OF

STATE, zip code

D. C. 20017

5 LOCATION OF LEGAL DESCRIPTIONCOURTHOUSE,
REGISTRY OF DEEDS, ETC.

Washington County Court House

Liber #: 633

Folio #: 547

STREET & NUMBER

West Washington Street

CITY, TOWN

Hagerstown

STATE

Maryland

21740

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

Maryland Historical Trust Survey #091

DATE

Summer 1967

 FEDERAL STATE COUNTY LOCALDEPOSITORY FOR
SURVEY RECORDS

Maryland Historical Trust

CITY, TOWN

Annapolis

STATE

Maryland

21401

7 DESCRIPTION

WA I-376

CONDITION

EXCELLENT
 GOOD
 FAIR

DETERIORATED
 RUINS
 UNEXPOSED

CHECK ONE

UNALTERED
 ALTERED < 50%

CHECK ONE

ORIGINAL SITE
 MOVED DATE _____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This house and barn, visited in April of 1975 were ^{not} demolished sometime between then and April of 1977. They were located on the west side of the Downsville Pike, Maryland route 632 south of Oak Ridge Drive in Washington County. Situated on a slight hill they faced southeast.

The house was a two story, eight bay structure presumably of brick and log construction. Its five southwestern bays at the front elevation were recessed beneath a double porch which was included under the roof span. This porch was supported by tapered square posts and was enclosed at the second story level with a plain balustrade. Displayed at the front elevation of the three northeastern bays was all stretcher brick bond. At the front elevation beneath the double porch the wall surface was coated with stucco which was incised with lines to look like block and painted red. The house is said to have been partly constructed of logs and sheathed with bricks. Variations in window size and construction suggest the possibility of alterations and renovations to the house during the mid 19th century.

Openings in the northeast three bays were aligned with each other in the walls. Those in the southeast section were spaced more randomly. Some windows in this part of the house had wide casings with molded trim and held nine over six pane double hung sashes at both the first and second stories. Most of the windows in the northeast section were relatively large with narrow beaded casings holding six over six pane double hung sashes. To these front window frames were attached pairs of three panel shutters.

The main entrance was located in the center bay of the northeast portion of the front elevation. Included in the framing was a broad transom with diamond shaped panes and matching sidelights. The door had four panels. An entrance porch at this bay was supported by pairs of chamfered posts between which ran a scroll cut balustrade. Other doors are located at both levels of the double porch. These had six panels and were hung beneath four light transoms.

The roof was sheathed with standing seam tin and terminated with barge boards set directly against the end walls. Brick chimneys were located inside the end walls and at the point where the recess for the southwest section began.

North of the house was a brick end barn with patterns of geometric ventilators in its end wall. Between the house and barn were a series of small sheds.

Although this complex has been demolished completely, at the time it was photographed in 1975, it was in fair condition. The property contains ~~15.46~~ ^{2r} acres and is ~~owned by a modern apartment complex.~~ ^{adjacent to a}

Modern apt. complex.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

PERIOD

AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW

<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input checked="" type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

This farmstead, now demolished included a large, two story, eight bay brick and presumably brick cased log house, and a brick bank barn with decorative geometric ventilators in its end walls. Both structures appeared to have been built during the mid 19th century. The house, however, had several windows and doors which displayed earlier construction methods, suggesting that the house may have been partially composed of an earlier structure which underwent extensive renovations during the mid 19th century. Much of the brick wall surface could be veneer over an earlier log building. During much of the second half of the 19th and first half of the 20th centuries, this farm was owned by members of the Stockslayer or Stockslager family. Included in the farm were parts of the land grants "Heisterboro," "Black Oak Ridge" and "David's Contentment."

House on National Register according to E. Feldman, developer of Oak Ridge Apts.

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Washington County Land Records.

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY 15.46 acres

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE	COUNTY

11 FORM PREPARED BY.

NAME / TITLE

Paula Stoner Dickey, Consultant

ORGANIZATION

Washington County Historical Sites Survey

DATE

November 1977

STREET & NUMBER

County Office Building, 33 West Washington Street

TELEPHONE

791-3065

CITY OR TOWN

Hagerstown

STATE

Maryland 21740

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

MARYLAND HISTORICAL TRUST

WA-I-376
 District 26
 Map 49
 Parcel 1663
 MAGI # 2205835535

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

AND/OR COMMON

Stockslager Farm

2 LOCATION

STREET & NUMBER

Off Downsville Pike (Rt. 632) South of Oak Ridge Drive on Garden Lane

CITY, TOWN

 VICINITY OF Hagerstown

CONGRESSIONAL DISTRICT

6

STATE

Maryland

COUNTY

Washington

3 CLASSIFICATION

CATEGORY

DISTRICT
 BUILDING(S)
 STRUCTURE
 SITE
 OBJECT

OWNERSHIP

PUBLIC
 PRIVATE
 BOTH
PUBLIC ACQUISITION
 IN PROCESS
 BEING CONSIDERED

STATUS

OCCUPIED
 UNOCCUPIED
 WORK IN PROGRESS
ACCESSIBLE
 YES: RESTRICTED
 YES: UNRESTRICTED
 NO

PRESENT USE

AGRICULTURE
 COMMERCIAL
 EDUCATIONAL
 ENTERTAINMENT
 GOVERNMENT
 INDUSTRIAL
 MILITARY
 MUSEUM
 PARK
 PRIVATE RESIDENCE
 RELIGIOUS
 SCIENTIFIC
 TRANSPORTATION
 OTHER

4 OWNER OF PROPERTY

NAME

Oak Ridge Park Apts. Section 5

Telephone #:

STREET & NUMBER

3000 7th St. N. E.

C/O Mr. Edwin B. Feldman

CITY, TOWN

Washington

VICINITY OF

STATE, zip code

D. C. 20017

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,

REGISTRY OF DEEDS, ETC.

Washington County Court House

Liber #: 633

Folio #: 547

STREET & NUMBER

West Washington Street

CITY, TOWN

Hagerstown

STATE

Maryland

21740

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

Maryland Historical Trust Survey # 091

DATE

Summer 1967

 FEDERAL STATE COUNTY LOCALDEPOSITORY FOR
SURVEY RECORDS

Maryland Historical Trust

CITY, TOWN

Annapolis

STATE

Maryland

21401

7 DESCRIPTION

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input checked="" type="checkbox"/> ALTERED < 50%	<input type="checkbox"/> MOVED DATE _____
<input type="checkbox"/> FAIR	<input checked="" type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This house and barn, visited in April of 1975 were demolished sometime between then and April of 1977. They were located on the west side of the Downsville Pike, Maryland route 632 south of Oak Ridge Drive in Washington County. Situated on a slight hill they faced southeast.

The house was a two story, eight bay structure presumably of brick and log construction. Its five southwestern bays at the front elevation were recessed beneath a double porch which was included under the roof span. This porch was supported by tapered square posts and was enclosed at the second story level with a plain balustrade. Displayed at the front elevation of the three northeastern bays was all stretcher brick bond. At the front elevation beneath the double porch the wall surface was coated with stucco which was incised with lines to look like block and painted red. The house is said to have been partly constructed of log and sheathed with bricks. Variations in window size and construction suggest the possibility of alterations and renovations to the house during the mid 19th century.

Openings in the northeast three bays were aligned with each other in the walls. Those in the southeast section were spaced more randomly. Some windows in this part of the house had wide casings with molded trim and held nine over six pane double hung sashes at both the first and second stories. Most of the windows in the northeast section were relatively large with row beaded casings holding six over six pane double hung sashes. To these front window frames were attached pairs of three panel shutters.

The main entrance was located in the center bay of the northeast portion of the front elevation. Included in the framing was a broad transom with diamond shaped panes and matching sidelights. The door had four panels. An entrance porch at this bay was supported by pairs of chamfered posts between which ran a scroll cut balustrade. Other doors are located at both levels of the double porch. These had six panels and were hung beneath four light transom.

The roof was sheathed with standing seam tin and terminated with barge boards set directly against the end walls. Brick chimneys were located inside the end walls and at the point where the recess for the southwest section began.

North of the house was a brick end barn with patterns of geometric ventilators in its end walls. Between the house and barn were a series of small sheds.

Although this complex has been demolished completely, at the time it was photographed in 1975, it was in fair condition. The property contains 15.46 acres and is owned by a modern apartment complex.

8 SIGNIFICANCE

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input checked="" type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

This farmstead, now demolished included a large, two story, eight bay brick and presumably brick cased log house, and a brick bank barn with decorative geometric ventilators in its end walls. Both structures appeared to have been built during the mid 19th century. The house, however, had several windows and doors which displayed earlier construction methods, suggesting that the house may have been partially composed of an earlier structure which underwent extensive renovations during the mid 19th century. Much of the brick wall surface could be veneer over an earlier log building. During much of the second half of the 19th and first half of the 20th centuries, this farm was owned by members of the Stockslayer or S' kslager family. Included in the farm were parts of the land grants "Heisterboro," "Black Oak Ridge" and "David's Contentment."

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

Washington County Land Records.

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATAACREAGE OF NOMINATED PROPERTY 15.46 acres

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE COUNTY

STATE COUNTY

11 FORM PREPARED BY

NAME / TITLE

Paula Stoner Dickey, Consultant

ORGANIZATION

Washington County Historical Sites Survey

DATE

November 1977

STREET & NUMBER

County Office Building, 33 West Washington Street

TELEPHONE

791-3065

CITY OR TOWN

Hagerstown

STATE

Maryland 21740

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

5463 11' NE
(MASON-DIXON)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

WA-I-376

77 45'
39° 37' 30"

*Funston
quad.*



660,000 FT

Joins Map 20


39°37'30"

MD GRID 650,000 FT

11

12

13



WA-I-376
 ADC of Alexandria Inc., 1984

Exit-29

FUNKSTOWN

10

11

12

13

A

B

C

D

E

F

G

H

11

12

13

WA-I-376

ADC of Alexandria Inc., 1984

Exit-29

FUNKSTOWN

10

11

12

13

A

B

C

D

E

F

G

H

11

12

13

WA-I-376

ADC of Alexandria Inc., 1984

Exit-29

FUNKSTOWN

10

11

12

13

5423 (11 NE
(MASON-DIXON)

WA I 376

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

UNITED
DEPARTMENT
CORPS OF

77°45'
39°37'30"


266000m E

267

42°30'

268

5463
269 (HAGER





WA 1-276

Stockslager Farm

PAULA STONER DICKEY
CONSULTANT, WASHINGTON CO
HISTORICAL SITES SURVEY



WA 5-813

4-1-1917

10-1-1917

Stocklager Farm

PAULA STONER DICKEY
CONSULTANT, WASHINGTON CO.
HISTORICAL SITES SURVEY