

ABSTRACT
WA-I-415
Log House
Hagerstown Vicinity
private

Early 19th Century

This farmstead consisting of a composition siding sheathed log house, a stone and frame springhouse and a frame bank barn is an example of Cumberland Valley vernacular architecture. One of the most notable features of the house is its exposed stone chimney on the surface of one of the end walls. This type of chimney construction is often associated with early log houses, suggesting the possibility of a late 18th or early 19th century building date.

MARYLAND HISTORICAL TRUST

WA-I-415
 District 10
 Map 57
 Parcel 176
 Magi # 2206395335

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

AND/OR COMMON

Log House

2 LOCATION

STREET & NUMBER

Route 65 at I-70

CITY, TOWN

 VICINITY OF Hagerstown

CONGRESSIONAL DISTRICT

6

STATE
MarylandCOUNTY
Washington**3 CLASSIFICATION**

CATEGORY

 DISTRICT BUILDING(S) STRUCTURE SITE OBJECT

OWNERSHIP

 PUBLIC PRIVATE BOTH

PUBLIC ACQUISITION

 IN PROCESS BEING CONSIDERED

STATUS

 OCCUPIED UNOCCUPIED WORK IN PROGRESS

ACCESSIBLE

 YES: RESTRICTED YES: UNRESTRICTED NO

PRESENT USE

 AGRICULTURE COMMERCIAL EDUCATIONAL ENTERTAINMENT GOVERNMENT INDUSTRIAL MILITARY MUSEUM PARK PRIVATE RESIDENCE RELIGIOUS SCIENTIFIC TRANSPORTATION OTHER**4 OWNER OF PROPERTY**

NAME

Daisy I. Barkdoll (Life Estate) C/O Howard Barkdoll Telephone #:

STREET & NUMBER

Route # 1

CITY, TOWN

Boonsboro

VICINITY OF

STATE, zip code

Maryland 21713

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,

REGISTRY OF DEEDS, ETC.

Washington County Court House

Liber #: 619

Folio #: 124

STREET & NUMBER

West Washington Street

CITY, TOWN

Hagerstown

STATE

Maryland 21740

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

 FEDERAL STATE COUNTY LOCALDEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

Wk I-415

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input checked="" type="checkbox"/> ALTERED < 50%	<input type="checkbox"/> MOVED DATE _____
<input checked="" type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This farm complex is located at the end of a private lane, west of Maryland Route 65 and immediately north of I-70, south of Hagerstown in Washington County. The house faces north. It is a two story, five bay log dwelling resting on fieldstone foundations. The surface of the building is sheathed with wooden weatherboarding upon which is a layer of composition siding. A recessed double porch included under the main roof span shelters the west bays of the front or north elevation. One notable feature of the exterior wall surface is the exposed chimney back in the east end wall. This method of chimney construction is found in some log houses and apparently facilitated access to the firebox for repair or replacement.

Many windows, particularly those at the second story retain six over six pane double hung sashes. Others have two over two pane sashes. Two picture windows have been installed in the front elevation at the first story on either side of the door. Window frames are narrow, some with flat applied trim.

The main entrance is located in the second bay from the east end of the house. Other entrances are located in the second bay from the west end at both levels of the double porch.

Extending to the rear of the house is a one story, two bay structure to which is attached rock faced concrete block outkitchen.

Corrugated sheet metal forms the roof of the house which protrudes beyond the end walls. A brick chimney extends from inside the east end wall. It is this chimney that has the exposed fire box back on the exterior wall surface. Smaller brick chimneys are located on the north and south slopes of the roof at the interior of the house, toward its west end.

North of the house is a stone and frame springhouse. Further to the north is a large frame bank barn which faces southeast. Sheds and agricultural structures are located nearby. The property contains approximately 50 acres.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

WA I-415

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input checked="" type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input checked="" type="checkbox"/> early COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

This farmstead consisting of a composition siding sheathed log house, a stone and frame spring-house and a frame bank barn is an example of Cumberland Valley vernacular architecture. One of the most notable features of the house is its exposed stone chimney on the surface of one of the end walls. This type of chimney construction is often associated with early log houses suggesting the possibility of a late 18th or early 19th century building date.

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATAACREAGE OF NOMINATED PROPERTY approximately 50 acres

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

11 FORM PREPARED BY

NAME / TITLE

Paula Stoner Dickey, Consultant

ORGANIZATION

Washington County Historical Sites Survey

DATE

December 1977

STREET & NUMBER

County Office Building, 33 West Washington Street

TELEPHONE

791-3065

CITY OR TOWN

Hagerstown


STATE

Maryland 21740

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438



WA-I-415
Handwritten notes

WA-I-407

PT 4 MI
3 MI



WAT 45
N.C.
1911 10-27

Log House
Rt. 65 at I-70
Hagerstown

PAULA STONER DICKEY
CONSULTANT, WASHINGTON CO.
HISTORICAL SITES SURVEY



6/14/78
A
1978

Log House
Rt. 65 at I-70
Hagerstown

PAULA STONER DICKEY
CONSULTANT, WASHINGTON CO.
HISTORICAL SITES SURVEY



Cont. - 2/10
8-10
Apr 11 1965

Log House
Rt. 65 at I-70
Hagerstown

PAULA STONER DICKEY
CONSULT NT, WASHINGTON CO,
HISTORICAL SITES SURVEY



1985-1986
Bryant
Log House
Rt. 65 at I-70
Hagerstown

PAULA STONER DICKEY
CONSULTANT, WASHINGTON CO.
HISTORICAL SITES SURVEY