

ABSTRACT

WA-II-139

19th Century

Mid 19th Century Farm

Hagerstown Vicinity

private

This set of buildings provides an example of a farm complex dating from the third quarter of the 19th century. Said to have been built in 1865 the house, a two story five bay brick structure with a central entrance displays influence of the Greek Revival style in its door and window treatment juxtaposed with some Victorian brackets on the porch. These 19th century elements are placed upon a building of the traditional farmhouse plan.



MARYLAND HISTORICAL TRUST

WA-II-139
District 16
Map 58
Parcel 24
MAGI # 2207395535

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

AND/OR COMMON

Mid 19th Century Farm

2 LOCATION

STREET & NUMBER

White Hall Road, South of I-70

CITY, TOWN

VICINITY OF Hagerstown

CONGRESSIONAL DISTRICT

6

STATE

Maryland

COUNTY

Washington

3 CLASSIFICATION

CATEGORY

OWNERSHIP

STATUS

PRESENT USE

DISTRICT

PUBLIC

OCCUPIED

AGRICULTURE

MUSEUM

BUILDING(S)

PRIVATE

UNOCCUPIED

COMMERCIAL

PARK

STRUCTURE

BOTH

WORK IN PROGRESS

EDUCATIONAL

PRIVATE RESIDENCE

SITE

PUBLIC ACQUISITION

ACCESSIBLE

ENTERTAINMENT

RELIGIOUS

OBJECT

IN PROCESS

YES: RESTRICTED

GOVERNMENT

SCIENTIFIC

BEING CONSIDERED

YES: UNRESTRICTED

INDUSTRIAL

TRANSPORTATION

NO

MILITARY

OTHER:

4 OWNER OF PROPERTY

NAME

Frank McKee

Telephone #:

STREET & NUMBER

28 East Lincoln Avenue

CITY, TOWN

Hagerstown

VICINITY OF

STATE, zip code

Maryland 21740

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,

REGISTRY OF DEEDS, ETC.

Washington County Court House

Liber #: 259

Folio #: 373

STREET & NUMBER

West Washington Street

CITY, TOWN

Hagerstown

STATE

Maryland 21740

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

FEDERAL STATE COUNTY LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input checked="" type="checkbox"/> ORIGINAL SITE
<input checked="" type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input checked="" type="checkbox"/> ALTERED < 50%	<input type="checkbox"/> MOVED DATE _____
<input type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This farm complex is located on the west side of White Hall Road just south of I-70, south-east of Hagerstown in Washington County, Maryland. The house and barn are situated on relatively high ground and face east.

The house is a two story, five bay brick structure resting on low fieldstone foundations. A two story two bay ell extends to the rear of the main section. The front part of the house is large being quite broad across the end walls. American or common brick bonding is used at all elevations and the entire surface of the house was painted red at one time.

Windows appear to have been spaced evenly in the front elevation. They have narrow frames which hold six over six pane double hung sashes. Openings at the first story level appear larger than those at the second story level. Wide wooden exposed lintels are present above the windows. At the front elevation these are trimmed with a series of dentil projections. Most windows have shutters. Some of those at the first story have three panels while others have sets of movable louvers.

The main entrance is centered in the front elevation with the opening including a seven light transom and sidelights inside paneled jambs. Extending across the entire front elevation is a one story porch with a massive entablature with a series of large dentils matching those used on the window lintels. The eaves boxing and barge areas of the house are also finished with dentils. The front porch has massive scroll cut brackets set above short square posts which rest on brick piers.

The roofing material is slate. Brick chimneys are located inside the gable ends.

A two story porch is attached to the rear elevation of the main section.

Just north of the house is a stone smoke house with a hipped roof and wooden ventilator cupola. Other domestic outbuildings are located nearby.

A frame bank barn which retains part of a wood shingle roof is located behind the house.

The buildings appear to be in good condition and are located on a farm containing 81.47 acres. According to the present owner, the house was built in 1865.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input checked="" type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

This set of buildings provides an example of a farm complex dating from the third quarter of the 19th century. Said to have been built in 1865 the house, a two story five bay brick structure with a central entrance displays influence of the Greek Revival style in its door and window treatment juxtaposed with some Victorian period brackets on the porch. These 19th century elements are placed upon a building of the traditional farmhouse plan.

CONTINUE ON SEPARATE SHEET IF NECESSARY

MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY 81.47 acres

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE	COUNTY

11 FORM PREPARED BY

NAME / TITLE

Paula Stoner Dickey, Consultant

ORGANIZATION

Washington County Historical Sites Survey

DATE

February 1978

STREET & NUMBER

County Office Building, 33 West Washington Street

TELEPHONE

791-3065

CITY OR TOWN

Hagerstown

STATE

Maryland 21740

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

FUNKSTOWN QUADRANGLE

MARYLAND—WASHINGTON CO.

7.5 MINUTE SERIES (TOPOGRAPHIC)

SW/4 HAGERSTOWN 15' QUADRANGLE

WA-II-139

5463 11 NE
(SMITHSBURG)

271 40'

272


273

620 000 FEET

274

77°37'30"

39°37'30"



4389

650 000
FEET

4388

4386

4385

35'

4384

Wagners Crossroads

WA-II-197

WA 77 57
11-20-92
Mid 19th Century Farm

White Hall Rd., S. of I-70
Hagerstown Vicinity

PAULA STONER DICKEY
CONSULTANT, WASHINGTON CO.
HISTORICAL SITES SURVEY



14 5 E
Mid 19th Century Farm

White Hall Rd., S. of I-70
Hagerstown Vicinity

PAULA STONER DICKEY
CONSULTANT, WASHINGTON CO.
HISTORICAL SITES SURVEY



11/10/73
1973
1973

Mid 19th Century Farm

White Hall Rd., S. of I-70
Hagerstown Vicinity

PAULA STONER DICKEY
CONSULTANT, WASHINGTON CO.
HISTORICAL SITES SURVEY



Mid 19th Century Farm

Mid 19th Century Farm

White Hall Rd., S. of I-70
Hagerstown Vicinity

PAULA STONER DICKEY
CONSULTANT, WASHINGTON CO.
HISTORICAL SITES SURVEY



Mid 19th Century Farm

White Hall Rd., S. of I-70
Hagerstown Vicinity

PAULA STONER DICKEY
CONSULTANT, WASHINGTON CO.
HISTORICAL SITES SURVEY