

WA-II-480      Frame House

Late 19th century

Lappans

Private

This house is a two-story, three-bay by two-bay stone foundation. Its walls are of narrow German siding painted white. It has a gable roof covered in sheet metal. Brick chimneys are located interior-end at each gable end. A long ell is attached to the rear of the house. This appears to be a later addition because of the change in the foundation.

Magi No.

DOE  yes  no

# Maryland Historical Trust State Historic Sites Inventory Form

## 1. Name (indicate preferred name)

historic

and/or common Frame house

## 2. Location

street & number west side of Rt. 65, .3 mile north of Lappans Road  not for publicationcity, town Lappans  vicinity of congressional district sixthstate Maryland county Washington

## 3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input checked="" type="checkbox"/> private residence
<input type="checkbox"/> site	<b>Public Acquisition</b>	<b>Accessible</b>	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input type="checkbox"/> not applicable	<input checked="" type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

## 4. Owner of Property (give names and mailing addresses of all owners)

name Beckley

street &amp; number \_\_\_\_\_ telephone no.: \_\_\_\_\_

city, town \_\_\_\_\_ state and zip code \_\_\_\_\_

## 5. Location of Legal Description

courthouse, registry of deeds, etc. Washington County Courthouse liberstreet & number Washington Street foliocity, town Hagerstown state Maryland

## 6. Representation in Existing Historical Surveys

title \_\_\_\_\_

date \_\_\_\_\_  federal  state  county  local

depository for survey records \_\_\_\_\_

city, town \_\_\_\_\_ state \_\_\_\_\_

# 7. Description

Survey No. WA-II-480

<b>Condition</b>		<b>Check one</b>	<b>Check one</b>	
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input type="checkbox"/> original site	
<input type="checkbox"/> good	<input type="checkbox"/> ruins	<input type="checkbox"/> altered	<input type="checkbox"/> moved	date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed			

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

This house is a two-story, three-bay by two-bay stone foundation. Its walls are of narrow German siding painted white. It has a gable roof covered in sheet metal. Brick chimneys are located interior-end at each gable end. A long ell is attached to the rear of the house. This appears to be a later addition because of the change in the foundation. The house appears to be from the late 19th century.

The frame house is located on the west side of Rt. 65, .3 miles north of Lappans Road. It is situated close to the road and is close to the other houses in Lappans. The main facade faces east.

The main facade is asymmetrical with a centrally located door. The entrance has a one-bay gable roof porch supported on a boxed posts. The windows in the other two bays of the first story and the three bays of the second story are six-over-six sash windows. The roof has a boxed cornice that returns at the gable ends. The ell has a one-story porch on the inner side of the ell. The northern side of the ell has one window on the first and two windows on the second stories. This gives this facade a bare look because of the lack of windows in the area that connects the two section. The gable end on the north side only has a small attic window.

There is a small shed outbuilding on this property.

# 8. Significance

Survey No. WA-II-480

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400–1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500–1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600–1699	<input type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/ humanitarian
<input type="checkbox"/> 1700–1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> theater
<input type="checkbox"/> 1800–1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> transportation
<input type="checkbox"/> 1900–	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> other (specify)
		<input type="checkbox"/> invention		

**Specific dates**


**Builder/Architect**

check: Applicable Criteria:  A  B  C  D  
and/or  
Applicable Exception:  A  B  C  D  E  F  G  
Level of Significance:  national  state  local

Prepare both a summary paragraph of significance and a general statement of history and support.

This building is a contributing structure in the Lappans Survey District.





WA-II-480

Fiery Siding

Balls Road

ANTIETAM

CREEK

**WA-II-480**  
**Frame House**  
**Furkstown Quad, 1953, PR 1971**

Roxbury Sta

Water Tank

STATE PENAL FARM

Roxbury

Lappans

Cem. of St Marks Ch

Devils Backbone

Breathedsville

Beaver

Emmertsville

Fairplay

4386  
4385  
35'  
4384  
4381  
2'30"  
4380

68  
65  
63

OHIO  
OHIO  
OHIO

ANR

BM 481

64

64

64

64



1. Frame House           WA-II-480
2. Washington County; Maryland
3. Joe Getty
4. May 1983
5. Maryland Hist. Trust, Annapolis, Md.
6. East and north elevation; camera  
facing southwest
7. 1/1