

WA-II-486      Frame House

Late-19th century

Lappans

Private

The Frame House is a three-bay by two-bay L-shaped structure. It is covered in a modern asphalt siding that simulates brick. A modern pattern asphalt shingle covers the gable roof. The main facade has an asymmetrical first story with an off-center entrance. The main facade is marked by a full-length, one-story porch with boxed posts and stick railing. The house is positioned so that the porch is slightly raised from ground level which is unique among the other houses in Lappans.

# Maryland Historical Trust State Historic Sites Inventory Form

## 1. Name (indicate preferred name)

historic

and/or common  Frame house

## 2. Location

street & number east side of Rt. 65, .28 mile south of Lappans Road  not for publicationcity, town Lappans  vicinity of  congressional district sixthstate Maryland  county Washington

## 3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input checked="" type="checkbox"/> private residence
<input type="checkbox"/> site	<b>Public Acquisition</b>	<b>Accessible</b>	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input type="checkbox"/> not applicable	<input checked="" type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

## 4. Owner of Property (give names and mailing addresses of all owners)

name

street &amp; number telephone no.:

city, town state and zip code

## 5. Location of Legal Description

courthouse, registry of deeds, etc. Washington County Courthouse liber

street &amp; number Washington Street folio

city, town Hagerstown state Maryland

## 6. Representation in Existing Historical Surveys

title

date  federal  state  county  local

depository for survey records

city, town state

# 7. Description

Survey No. WA-II-486

<b>Condition</b>		<b>Check one</b>	<b>Check one</b>
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input type="checkbox"/> original site
<input type="checkbox"/> good	<input type="checkbox"/> ruins	<input type="checkbox"/> altered	<input type="checkbox"/> moved    date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed		

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The frame house is a three-bay by two-bay L-shaped structure. It is covered in a modern asphalt siding that simulates brick. A modern pattern asphalt shingle covers the gable roof. The main facade has an asymmetrical first story with an off-center entrance. The main facade is marked by a full-length, one-story porch with boxed posts and stick railing. The house is positioned so that the porch is slightly raised from ground level which is unique among the other houses in Lappans. The house appears to have been constructed in the late 19th century.

The house is located on the east side of Rt. 65, .28 mile south of Lappans Road in Lappans. The property sits in a cluster of late 19th century buildings and sits on a slight rise close to the road. The main facade faces west.

The foundation is constructed of stone. The ornamentation consists of the first story porch details and plain wood trim on the windows. There are interior-end brick chimneys at the northernmost gable end of the house and at the gable end of the ell.

There are no significant outbuildings on the property.

# 8. Significance

Survey No. WA-II-486

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/ humanitarian
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> theater
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> transportation
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> other (specify)
		<input type="checkbox"/> invention		

**Specific dates**


**Builder/Architect**

check: Applicable Criteria:  A  B  C  D  
and/or  
Applicable Exception:  A  B  C  D  E  F  G  
Level of Significance:  national  state  local

Prepare both a summary paragraph of significance and a general statement of history and support.

The frame house is a contributing structure in the Lappans Survey District.





WA-II-486

Fiery Siding

OHIO

Balls Road

ANTIETAM

CREEK

Roxbury Sta.

Water Tank

STATE PENAL FARM

Roxbury

Lappans

Cem. St Marks

**WA-II-486**  
**Frame House**  
**Funkstown Quad, 1953, PR 1971**

Devils Backbone

Breathesville

Bedover

Emmertsville

Fairplay

4386  
4385  
35'  
4384  
W. IAMSPORT 4.4 MI.  
WYLS 0.3 MI.  
5463 III SE (WILLIAMSPORT)  
4381  
2'30"  
4380

65

514

513

495

68

65

BM 481

OHIO AND

63

500

500

500

500

64

500

500

500

500



1. Frame House           WA-II-486
2. Washington County, Maryland
3. Joe Getty
4. May 1983
5. Maryland Hist. Trust, Annapolis, Md.
6. West & south facades; camera facing  
northeast
7. 1/1