

Maryland Historical Trust State Historic Sites Inventory Form

Magi No.

DOE yes no

1. Name (indicate preferred name)

historic Frame house

and/or common

2. Location

18914 Sandy Hook Road ^{JKL} _{12/1/05}street & number south side of Sandy Hook Road, .04 mile east of Clark Road not for publicationcity, town Sandy Hook _____ vicinity of _____ congressional district sixthstate Maryland _____ county Washington

3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input checked="" type="checkbox"/> private residence
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input checked="" type="checkbox"/> not applicable	<input checked="" type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

4. Owner of Property (give names and mailing addresses of all owners)

name _____

street & number _____ telephone no.: _____

city, town _____ state and zip code _____

5. Location of Legal Description

courthouse, registry of deeds, etc. Washington County Courthouse liber _____street & number Washington Street folio _____city, town Hagerstown state Maryland

6. Representation in Existing Historical Surveys

title _____

date _____ federal state county local

depository for survey records _____

city, town _____ state _____

7. Description

Survey No. WA-III-087

Condition		Check one	Check one
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input checked="" type="checkbox"/> original site
<input checked="" type="checkbox"/> good	<input type="checkbox"/> ruins	<input checked="" type="checkbox"/> altered	<input type="checkbox"/> moved
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed		date of move _____

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The frame house is a two-story frame structure constructed in a rectangular plan. It is a three-bay by one-bay structure on a stone foundation. It has a one-story rear addition. The exterior is covered in asphalt shingles. The main facade is symmetrically arranged with a central entrance and a full-length, one-story porch. The structure has a gable roof and interior-end brick chimneys.

The property is located on the south side of Sandy Hook Road, approximately .04 mile east of Clark Road, in Sandy Hook. The house sits slightly back from the road. The main facade faces south.

The two-story structure is constructed of frame covered in asphalt shingles. It is on a rough-laid fieldstone foundation painted white. The main facade is symmetrically arranged with a central entrance. Windows and doors have plain trim with molded cornice. The windows sash is four vertical panes in the upper sash and a single pane in the lower sash. These windows are located in the outer bays of the first story and the three bays of the second story. The full-length, one-story porch has a hipped roof supported by square posts. The porch railing is covered in asphalt shingles. There are corner boards at the corners of the structure. The gable ends have a four-pane window in the gable. The roof has a boxed cornice and is covered in asphalt shingles. Interior-end brick chimneys rise from each gable. The one-story rear addition is constructed of frame covered in vertical board siding. Its exterior appearance reveals all modern materials although a earlier addition might be underneath the modern materials.

There are no significant outbuildings on the property.

8. Significance

Survey No. WA-III-087

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/ humanitarian
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> theater
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> transportation
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> other (specify)
		<input type="checkbox"/> invention		

Specific dates

Builder/Architect

check: Applicable Criteria: A B C D
and/or

Applicable Exception: A B C D E F G

Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.

This site is a contributing structure in the Sandy Hook Survey District.

9. Major Bibliographical References

Survey No. WA-III-087

10. Geographical Data

Acreage of nominated property _____

Quadrangle name _____

Quadrangle scale _____

UTM References do NOT complete UTM references

A

--	--	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--	--

B

--	--	--	--	--	--	--	--	--	--	--	--

--	--	--	--	--	--	--	--	--	--	--	--

C

--	--	--	--	--	--	--	--	--	--	--	--

D

--	--	--	--	--	--	--	--	--	--	--	--

E

--	--	--	--	--	--	--	--	--	--	--	--

F

--	--	--	--	--	--	--	--	--	--	--	--

G

--	--	--	--	--	--	--	--	--	--	--	--

H

--	--	--	--	--	--	--	--	--	--	--	--

Verbal boundary description and justification

List all states and counties for properties overlapping state or county boundaries

state	code	county	code
-------	------	--------	------

state	code	county	code
-------	------	--------	------

11. Form Prepared By

name/title Joe Getty

organization Maryland Historical Trust

date April 1983

street & number 21 State Circle

telephone

city or town Annapolis

state Maryland

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.


return to: Maryland Historical Trust
 Shaw House
 21 State Circle
 Annapolis, Maryland 21401
 (301) 269-2438

WA-III-087

Frame House

18914 Sandy Hook Road (MD 180), Sandy Hook

Harpers Ferry Quadrangle



1993-94 Aerial Photo




FREDERICK & WASHINGTON

HARPERS FERRY, VA-MD-W VA
QUADRANGLE
USGS 7.5 minute map
1:24 000
1969

COMMONWEALTH OF VIRGINIA
DIVISION OF MINERAL RESOURCES
JAMES L. CALVER, STATE GEOLOGIST

767 768 (KEEDYSVILLE) 769





1. WA-III-087
2. Washington Co., Md.
3. Joe Getty
4. ~~April 1983~~ 7/82
5. Md. Hist. Trust, Annapolis, Md.
6. South elev. (camera facing north)
7. 1/1