

Maryland Historical Trust State Historic Sites Inventory Form

1. Name (indicate preferred name)

historic Frame house

and/or common

2. Location

18902 Sandy Hook Road ^{JK 12/1/05}street & number northeast corner of the intersection with Sandy Hook and Clark Roads not for publicationcity, town Sandy Hook vicinity of congressional district sixthstate Maryland county Washington

3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input type="checkbox"/> building(s)	<input type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input type="checkbox"/> private residence
<input type="checkbox"/> site	Public Acquisition	Accessible	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

4. Owner of Property (give names and mailing addresses of all owners)

name

street & number telephone no.:

city, town state and zip code

5. Location of Legal Description

courthouse, registry of deeds, etc. Washington County Courthouse ^{m. 87 p. 109} liberstreet & number Washington Street foliocity, town Hagerstown state Maryland

6. Representation in Existing Historical Surveys

title

date federal state county local

depository for survey records

city, town state

7. Description

Survey No. WA III-092

Condition

excellent
 good
 fair

deteriorated
 ruins
 unexposed

Check one

unaltered
 altered

Check one

original site
 moved date of move _____

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The frame house is a two-story frame structure constructed in a rectangular plan. It contains its original exterior wood siding and many of its early ornamental features including a full-length, one-story porch bracket cornice and window trim with crossettes, pointed-arch cornices, and round-arch upper pane sash. The retention of these features makes the structure one of the better preserved buildings in Sandy Hook. The structure appears to date from the mid-to-late 19th century.

The property is located in the north east corner of the intersection of Sandy Hook and Clark Road, in Sandy Hook. The structure sits back from the road and is centrally located on its lot. The main facade faces south.

The two-story structure is constructed of frame covered in aluminum siding. The house is constructed on a fieldstone foundation. The structure is currently painted white with trim painted in a dark color. In sections of the house, these contrasting colors enhance the pattern of ornamentation, such as the bracket cornice (where the background is painted dark and the bracket white), the window trim (where the architraves are painted dark and the window sash white), and the porch (where the alternating white and dark colors are used). The main facade is symmetrically arranged with a central entrance and a full-length, one-story porch. Two-over-two sash windows are in the outer bays of the first story, three bays of the second story, and one on each story of the gable ends. The gable ends also have a small window in the gable. The front porch has a hipped roof supported on square posts. Panel ornamentation is located on the railing. The structure has cornerboards painted in a dark color. There is a gable roof covered in asphalt shingles.

There are no significant outbuildings on the property.

8. Significance

Survey No. WA-III-092

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/ humanitarian
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> theater
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> transportation
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> other (specify)
		<input type="checkbox"/> invention		

Specific dates _____ **Builder/Architect** _____

check: Applicable Criteria: A B C D
and/or
Applicable Exception: A B C D E F G


Level of Significance: national state local

Prepare both a summary paragraph of significance and a general statement of history and support.


This site is a contributing structure in the Sandy Hook Survey District.

WA-III-032, Sandy Hook Survey District

(All prefixes "WA-III-")



WA-III-092
Frame House
18902 Sandy Hook Road (MD 180), Sandy Hook
Harpers Ferry Quadrangle



1993-94 Aerial Photo




FREDERICK & INGTON

HARPERS FERRY, VA-MD-W VA
QUADRANGLE
USGS 7.5 minute map
1:24 000
1969

COMMONWEALTH OF VIRGINIA
DIVISION OF MINERAL RESOURCES
JAMES L. CALVER, STATE GEOLOGIST

767 768 (KEEDYSVILLE) 769





1. WA-III-092
2. Washington Co., Md.
3. Joe Getty
4. ~~April 1983~~ 7/82
5. Md. Hist. Trust, Annapolis, Md.
6. South elev. (camera facing north)
7. 1/1