

2300546506

STATE Maryland
COUNTY Wicomico
TOWN Salisbury VICINITY
STREET NO. north of Salisbury Mall

HISTORIC AMERICAN BUILDINGS SURVEY
INVENTORY W1- 54

2. NAME Victorian Barn

DATE OR PERIOD c. 1860-80
STYLE
ARCHITECT
BUILDER

ORIGINAL OWNER
ORIGINAL USE barn
PRESENT OWNER
PRESENT USE site
WALL CONSTRUCTION frame
NO. OF STORIES

3. FOR LIBRARY OF CONGRESS USE


4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION OPEN TO PUBLIC no

Since visiting the Victorian Barn, it has been removed, torn down, or burned. (see MHT file)

It was a large two-story, board and batten structure with an elaborate bracket cornice which returned upon itself and continued up the gables. In the center of the "A" roof was a rectangular vent with hipped roof, louvered vents, bracket cornice and weather vane with cow upon it.

On the first story, were three rows of six single sash on each side, probably installed when the barn was used for milking. One door was located on the second story of the same side. Each gable had two windows on each story, a center wide entrance on first story and opening in gable for hauling in hay. It rested on a brick foundation.

All interior structure was sawn by a radial saw; mortised and pegged. The roof was constructed in the manner of a medieval truss (see diagram).



demolished

5. PHYSICAL CONDITION OF STRUCTURE Endangered Interior Exterior



6. LOCATION MAP (Plan Optional)

7. PHOTOGRAPH

8. PUBLISHED SOURCES (Author, Title, Pages)
INTERVIEWS, RECORDS, PHOTOS, ETC.

9. NAME, ADDRESS AND TITLE OF RECORDER

Michael Bourne
3/2/71

DATE OF RECORD

SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE



