

WO-258  
Looking Good Hair Salon  
Snow Hill  
private

1894-1895

The Looking Good Hair Salon retains an intact late nineteenth-century storefront with a Victorian bracketed cornice atop large glass display windows and a recessed side entrance. The second floor is defined by four two-over-two sash windows that boast rusticated red sandstone sills and corbelled brick segmental arches. Also in good condition is the decorative metal cornice that finishes the top of the parapet wall. This stretcher bond brick commercial building stands in a row of contemporary structures and adds to the period character of North Washington Street.

HISTORIC CONTEXT INFORMATION

Resource Name: LOOKING GOOD HAND SAND

MHT Inventory Number: WD-258

MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA:

1) Historic Period Theme(s):

ARCHITECTURE, ECONOMIC

2) Geographic Orientation:

EASTERN SHORE

3) Chronological/Developmental Period(s):

1910-1930 INDUSTRIAL-URBAN DOMINANCE

4) Resource Type(s):

1. STANDING STRUCTURES  
a. STONE

# Maryland Historical Trust State Historic Sites Inventory Form

## 1. Name (indicate preferred name)

historic

and/or common LOOKING GOOD HAIR SALON

## 2. Location

street & number 211 North Washington Street  not for publicationcity, town Snow Hill  vicinity of congressional district First

state Maryland county First

## 3. Classification

Category	Ownership	Status	Present Use	
<input type="checkbox"/> district	<input type="checkbox"/> public	<input checked="" type="checkbox"/> occupied	<input type="checkbox"/> agriculture	<input type="checkbox"/> museum
<input checked="" type="checkbox"/> building(s)	<input checked="" type="checkbox"/> private	<input type="checkbox"/> unoccupied	<input checked="" type="checkbox"/> commercial	<input type="checkbox"/> park
<input type="checkbox"/> structure	<input type="checkbox"/> both	<input type="checkbox"/> work in progress	<input type="checkbox"/> educational	<input type="checkbox"/> private residence
<input type="checkbox"/> site	<b>Public Acquisition</b>	<b>Accessible</b>	<input type="checkbox"/> entertainment	<input type="checkbox"/> religious
<input type="checkbox"/> object	<input type="checkbox"/> in process	<input checked="" type="checkbox"/> yes: restricted	<input type="checkbox"/> government	<input type="checkbox"/> scientific
	<input type="checkbox"/> being considered	<input type="checkbox"/> yes: unrestricted	<input type="checkbox"/> industrial	<input type="checkbox"/> transportation
	<input checked="" type="checkbox"/> not applicable	<input type="checkbox"/> no	<input type="checkbox"/> military	<input type="checkbox"/> other:

## 4. Owner of Property (give names and mailing addresses of all owners)

name

street &amp; number telephone no.:

city, town state and zip code

## 5. Location of Legal Description

courthouse, registry of deeds, etc. Worcester County Clerk of Court liber

street &amp; number Worcester County Courthouse folio

city, town Snow Hill state MD 21863

## 6. Representation in Existing Historical Surveys

title

date  federal  state  county  local

depository for survey records

city, town state

# 7. Description

Survey No. W0-258

<b>Condition</b>		<b>Check one</b>	<b>Check one</b>	
<input type="checkbox"/> excellent	<input type="checkbox"/> deteriorated	<input type="checkbox"/> unaltered	<input checked="" type="checkbox"/> original site	
<input checked="" type="checkbox"/> good	<input type="checkbox"/> ruins	<input checked="" type="checkbox"/> altered	<input type="checkbox"/> moved	date of move _____
<input type="checkbox"/> fair	<input type="checkbox"/> unexposed			

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The Looking Good Hair Salon is located at 211 North Washington Street in the center of Snow Hill, Worcester County, Maryland. The two-story, four-bay brick building faces northeast.

Built around 1894, the two-story, stretcher bond brick building is covered by a flat roof that is hidden behind a parapet wall. The sides of the building are fully covered by adjacent structures.

The southeast (main) elevation retains an intact late nineteenth-century storefront with a recessed side entrance in the southernmost bay. A glazed four-panel front door and large plate glass display windows fill the first floor wall, while a bracketed cornice stretches above the door and window openings. The second floor is lighted by four two-over-two sash windows that are fitted with rusticated red sandstone sills and segmental raised brick arches. A delicate incised line decoration embellishes the window headers. Fixed above the windows are four screened vents, and a metal bracketed cornice finishes the top of the parapet wall. End blocks to the cornice are distinguished by small finials.

The interior has been reworked with modern materials, and most original features have been removed or covered over. The second floor was not seen.

# 8. Significance

Survey No. W0-258

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input checked="" type="checkbox"/> 1800-1899	<input checked="" type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates	Builder/Architect
check: Applicable Criteria: <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D and/or	
Applicable Exception: <input type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G	
Level of Significance: <input type="checkbox"/> national <input type="checkbox"/> state <input checked="" type="checkbox"/> local	

Prepare both a summary paragraph of significance and a general statement of history and support.

The Looking Good Hair Salon retains an intact late nineteenth-century storefront elevation with a Victorian bracketed cornice atop large plate glass display windows and a recessed side entrance. The second floor is defined by four two-over-two sash windows that boast rusticated red sandstone sills and corbelled brick segmental arches. Also in good condition is the decorative metal cornice that finishes the top of parapet wall. Although the first floor interior of the store has been remodeled, the intact exterior exhibits consistent period features that parallel contemporary commercial buildings throughout downtown Snow Hill.







1077 LACE, GRIFFIN  
 AND - STEVENSON ATLAS  
 W0-258

**SNOW HI**

1-95  
SANBORN  
INSURANCE  
MAP



WO-258  
LOOKING GOOD HAIR SALON  
Snow Hill, MD Quadrangle, 1966

WO-258

